

C/60

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 2024/681

Dated:-12.11.2024

To,
The Manager,
Geetanjali Inn,
3997- 4000 & 4001, Gali School Wali,
Bagichi Ram Chander, Mohalla Kaseruwalan,
Pahar Ganj, New Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/S Geetanjali Inn, 3997- 4000 & 4001 Gali School Wali, Bagichi Ram Chander, Mohalla Kaseruwalan, Pahar Ganj, New Delhi.

Sir,
This has reference to ID No. 2024101515681 dated 15/10/24 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 04/11/24 in the presence of **Mr. Salman** and following shortcomings were observed:-

1. Smoke management system is not provided.
2. CO type detectors found nonfunctional.
3. Hose reel & pump found nonfunctional

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,


(Addl. Chrg.)
DIRECTOR
Delhi Fire Service

Copy to:
Addl. Commissioner of Police(lic), 1st floor, Defence Colony Police Station, New Delhi