049

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2024 684

Dated:-1.3./1.1/2024

To,

The Manager
M/S Hindustan International DX Guest House,
1518, Ranjeet Gali, Paharganj, New Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/S Hindustan International DX Guest House, located at 1518, Ranjeet Gali, Paharganj, New Delhi.

Sir,

This has reference to on line ID No. 2024102015910 dated 20/10/24, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 08/11/24 in the presence of Mr. Sagar and following shortcomings were observed: -

1. CO- detector is not provided.

2. PA system found nonfunctional.

3. Smoke management system is not provided.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and resubmit for further consideration in the matter.

Yours faithfully,

Delhi Fire Service

Copy to:
The Addl. Commissioner of Police (Lic), Ist floor, Defence Colony Police Station, New Delhi.