



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

NO. F6/DFS/MS/SZ/2024/ 9 68 2

DATED: // //2/2024

To,

The Executive Engineer (E)
DED-71, CPWD,IARI,
Pusa Campus, New Delhi-110012

Subject: Renewal of Fire safety Certificate from fire safety & means of escape point of view in r/o National Agriclture Science Complex, Pusa New Delhi-

Sir.

Please refer to your letter No. D/B/(2)/DED-71/2024-25/3044 dated 08/11/2024 on the subject cited above. In this connection it is to inform you that the above said premises was visited by the officers concerned of this department on 28/11/2024 in the presence of Sh. Harender Parshad (Operator) & Mr. Avdash Kumar (Supervisor) to see the compliance of the shortcomings communicated vide this office letter No. F.6/DFS/MS/SZ/2019/4696, dated 02/08/2019 and found that the shortcomings are still not complied.

In view of the above shortcomings renewal of Fire Safety Certificate from fire safety point of view cannot be considered at this stage. You are directed to comply all the shortcomings under intimation with this department for further consideration in the matter.

Yours faithfully,

(Atul/Garg)

Delhi Rire Officer

Copy to:-

1. The Under Secretary E & MS, NSAC Complex, Pusa new Delhi, for Information.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/2019/SZ/ 4696 To,

Dated:

02/08/15

The Executive Engineer(E), ED-XI, CPWD, Pusa, New Delhi-110012.

Subject: - Renewal Fire Safety Certificate in r/o National Agriculture Science Complex Pusa, New Delhi-110012.

Sir.

This is in reference to your letter No. DB(10)/ED-XI/2019-20/185 dated 11.6.2019 on the subject cited above. In this connection it is to inform you that the above said buildings/complex has been inspected by the officer concerned of this department from fire safety point of view on 18.7.2019 in presence of Sh. Sunul Kumar Sinha AE (E) & Sh. Sanjay Kumar JE (E) CPWD.

During the course of inspection the following shortcomings have been observed:-

1. Some of First hose reels found non functional & jammed.

2. Automatic sprinkler system is provided in basement of all blocks, but found removed in upper floors of the Symposium/Auditorium Block.

3. Internal hydrants are provided but boxes, RRL Hose, Branch with Nozzle found missing.

4. Hose boxes of some Yard Hydrants are missing.

5. Main Fire pumps not found on auto mode due to leakage/renovation works in pipeline.

6 Pressurization in lift shafts found removed.

In view of the above shortcomings fire safety Certificate cannot be renewed at this stage. You are advised to rectify the above said shortcomings under intimation to this department for taking further necessary action.

1. The under Secretary E&MS, NSAC Complex, Pusa, New Delhi, for information.