



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/SGH/2024/SZ/ 666

Dated: 11 /12/2024

To

Sh. Harish Chander (Liaison Officer), U.T. Administration of Daman & Diu, Dadar & Nagar Haveli and UT of Lakshadweep House, UT Bhawan, Plot No. 16, Tenzing Norgay Marg, Chanakya Puri, New Delhi-110021

Sub: Regarding issuance of Fire Safety Certificate in r/o UT Guest House for Lakshadweep, Daman & Diu, Dadra & Nagar Haveli, Plot No. 16, Chanakyapuri, New Delhi–110021 Sir,

This has reference to your letter No. Nil dated 18.11.2024, received through outdoor diary No. 9154 dated 18/11/2024. In this connection, the premise was inspected by the officer concerned of this department from fire & life safety point of view on dated 22/10/2024 in the presence of Sh. Dimpal Kumar (Supervisor) & Sh. Rajesh. During course of inspection, the shortcomings observed are as below.

1. Smoke Check Door found removed/replaced.

2. Conference hall & Banquet are converted into eating establishment. Hence, required to be applied though online portal.

3. Electrical shaft found unsealed.

4. Automatic fire detection system found non-functional.

5. Exit signages found removed at some places.

6. Lift signages not provided at upper floors.

7. The width of doors provided for protection of exits in stairs found 1.30m against required width of 1.50m.

In view of the above shortcomings, the application for issuance of fire safety certificate is rejected. You are advised to rectify the above shortcomings under intimation to this department for further action in the matter.

Yours faithfully

DIRECTOR 1. No. 011-23414000