


DELHI JAL BOARD; GOVT. OF NCT OF DELHI OFFICE OF THE EXECUTIVE ENGINEER (SDW)-IV SEWAGE TREATMENT PLANT KONDLI, KONDLI, DELHI-110096

Ph: 011-22613156

E-mail: eesdw4.djb@nic.in



150CT 2020

STOP CORONA

"Wash Your Hand, Wear Mask & Maintain Social Distance"

No.: F-29(Ko)/DJB/EE(SDW)-IV/2020/

21071

Dated:

To.

M/s VA Tech Wabag Limited,

"WABAG House"

No.17, 200 Feet Thoraipakkam

Pallavaram Main Road,

Sunnambu Kolathur,

Chennai- 600 117,

INDIA

E-mail: wabag@wabag.in, r_mittal@wabag.in

AND

M/s VA Tech Wabag Limited,

4, H. Floor, Plot No. A-13A, Graphix Tower,

Sector-62, Noida, U.P.-201301.

E-mail: rajiv_mehta@wabag.in

[Kind Attention: Sh. Rajiv Mittal, MD]

Name of Work:- 45 MGD Sewage Treatment Plant and other related associated/ allied appurtenant works on design, Build & Operated basis at Kondli, Delhi.

Agreement No.: - 02(2008-2009)/ EE(C)DR.IX dated 12.06.2008.

Subject: - Letter of Debarment of M/s VA Tech Wabag Limited from participating in future projects/tenders/bids/works to be undertaken by Delhi Jal Board for 3 (Three) years.

Reference:

i) DJB's Show Cause Notice vide No. DJB/CE(SDW)/2016/299 dated 25.05.2016

ii) DJB's Show Cause Notice vide No.F-29(Ko)/DJB/EE(SDW)-IV/2017/4388 to 4393 dated 01.03.2017

iii) DJB's Show Cause Notice vide No.F-29(Ko)/DJB/EE(SDW)-IV/2017/4758 to 4763 dated 24.03.2017

iv) DJB's Show Cause Notice vide No.F-29(Ko)/DJB/EE(SDW)-IV/2020/351

- v) DJB's Letter No.F-29(Ko)/ DJB/EE(SDW)-IV/2020/757 dated 31.07.2020
- vi) M/s VA Tech Wabag Ltd. Letter No. VATech/DJB/KMS/ns/2020/06/1804 dated 29.06.2020
- vii) M/s VA Tech Wabag Ltd. Letter No. VATech/DJB/10M80-RM/06/1804A dated 04.08.2020.

Dear Sir,

WHEREAS, Contract Agreement for the work of "45 MGD Sewage Treatment Plant and other related associated/ allied appurtenant works on design, Build & Operated basis at Kondli, Delhi" (hereinafter referred as Project) was issued to M/s VA Tech Wabag Limited (hereinafter referred as 'Selected bidder' or 'Executing Agency') vide C.A. No.-2(2008-2009)/EE(C) Dr.-IX on 12.06.2008 by Delhi Jal Board (hereinafter referred as 'DJB' or 'Authority').

- 2. AND WHEREAS, the broad scope of work covered under this project are:-
 - (i) Design and construction of Sewage Treatment plant based on Activated sludge process for 90 MGD Peak Flow, 45 MGD average flow and 22.5 MGD lean flow.
 - (ii) Three months trial run after installation and commissioning of processing units, one year Defect Liability Period and 10 year's subsequent Operation-cum-Optimal utilization of equipment/ processing units and the facility to achieve the design parameters for Treated-Effluent BOD/TSS-20/30 mg/l (i/c cost of consumables required) excluding the electricity bill against use of grid power payable by DJB.
 - (iii) Comprehensive maintenance/ repair/ renovation/ replication of equipment/ units including men, material and machines required.
 - (iv) Handling and Disposal of Residue/ sludge and other by-products of Sewage treatment Process.
 - (v) Guaranteed Electricity generation with use of Biogas Engines.
 - (vi) Carrying out the required analysis, maintenance, storage and retrieval of data and submission of reports.
 - (vii) Housekeeping and maintenance of Administrative Block, Internal Roads, Surface Drains, Horticulture and Landscaping.
 - (viii) Safety and security of DJB property.
 - (ix) Statutory approvals and Liasoning.
 - (x) Any other activity/ works not mentioned specifically but deemed essential to achieve the goal as required time to time.
- 3. AND WHEREAS, the 45 MGD STP Phase-IV was put on trial run for the period of three months on 29.08.2013 as per provision of the contract. One year's Defect Liability Period was started w.e.f. 29.11.2013. The Executing Agency has failed to achieve the design parameters (BOD/TSS 20/30 mg/l), for treated effluent during this period hence the DLP was extended for the period of one year i.e. up to 28.11.2015 as per provision of contract agreement. However the Executing Agency again could not achieve the treated effluent parameter due

to which DLP was extended up to 31.01.2016. Accordingly, the period of stipulated 10 year's O&M started w.e.f. 01.02.2016.

- 4. AND WHEREAS, the performance of the plant has been continuously under scrutiny, since the start of O&M period i.e. w.e.f 2016. There have been many occasions when it was observed that the Executing Agency failed to operate & maintain the plant as per SOP. Consequently Show Cause Notices dated 25.05.2016, 01.03.2017 & 24.03.2017 were issued to the firm. Subsequently IIT Delhi was also appointed by the department vide letter No. F-9(L)/DJB/EE(SDW)-IV/2017/191 to 198 dated 22.04.2017 for conducting process audit of 45 MGD STP, Kondli at the risk and cost of the Executing Agency.
- 5. AND WHEREAS, the IIT Delhi vide its report dated 17.01.2018 had submitted process audit report to DJB wherein some recommendations were suggested. The key recommendations were as under:

(i) In the initial portion of the aeration tanks, one extra diffuser sub grid may be provided due to sulphide, which is enormously high in this wastewater.

(ii) Maintenance of diffuser pipes needs proper attention. Therefore, it is proposed to install modular grid for air supply. However, maintenance of diffusers with affecting the operation of aeration tank is really a difficult task. Therefore, a preventing maintenance schedule put in place. In future arrangement provision of retrievable grid can be planted.

(iii) Plant should have automatic control system for better operation and control. Such control system is immediately needed at the primary sludge sump.

- 6. AND WHEREAS, the above recommendations were conveyed to the firm vide letter. No. F-29(Ko)/DJB/EE(SDW)-IV/2018/3865 dated 09.02.2018 for compliance. These were required to be complied with by the firm to meet the treated effluent parameters as per the provisions of the contract agreement. In response to the DJB's letter, the firm committed certain timelines to implement the recommendations of IIT Delhi. However, the firm failed to implement the above recommendations till date.
- 7. AND WHEREAS, large number of complaints from nearby residential colonies of Mayur Vihar Ph-III regarding emission of bad odour from the plant, owing to poor performance of the Executing Agency, Hon'ble Vice Chairman, DJB under took an inspection of the plant on 22.05.2020. Dissatisfied with operation & maintenance of the plant then, it was decided and directed to initiate stern action against the Executing Agency as per contract agreement.
- 8. AND WHEREAS, the Executing Agency M/s VA Tech Wabag Ltd. miserably failed to maintain the Electrical & Mechanical equipments installed at the 45 MGD STP and observed that more than 40% of major E&M equipments are out of order. Also, the power generation through Bio-gas by the company was never found stable during the O&M period.

- 9. AND WHEREAS, due to failures on the part of the Executing Agency, Show Cause Notice was issued on 22.06.2020 seeking explanation as to why the Executing Agency should not be debarred from participation in the future bidding process of DJB on account of poor performance and why the work of O&M of 45 MGD STP Kondli should not be handed over to the other firm at the Executing Agency's risk & cost.
- AND WHEREAS, DJB considered the subsequent reply of Show Cause Notice submitted vide letter No. VATech/DJB/KMS/ns/2020/06/1804 dated 29.06.2020 and after scrutiny of the response of the Executing Agency, it is stated that the submissions/reply of M/s VA Tech Wabag Ltd. is not found satisfactory. Accordingly, a disagreement note to the firm was sent vide letter no. F-29(Ko)/DJB/EE(SDW)-IV/2020/757 dated 31.07.2020 on the following grounds:
 - (i) The firm has failed to generate guaranteed energy (in kWh) due to non-functioning of Bio-gas engines as per schedule XVII, Vol-II and clause 1.2.2.7 Vol-I of Contract Agreement. This is putting extra financial burden on DJB. As per the CA provisions, electricity requirement from the grid is 'NIL'. This stands communicated repeatedly to you through e-mails / registered letters / verbal instructions.
 - (ii) The E&M equipment installed at the plant are not functioning properly and even presently around 40% essential equipments are lying idle / un-attended. There have been many instances when more than 40% major, essentially required equipments remained under break down maintenance which adversely affecting performance of the plant. These instances stand already communicated through e-mails / registered letters / verbal instructions.
 - (iii) The firm has failed to maintain the facility in a good working order including sustaining adequate DO / MLSS levels / inventory of spare parts as per clause no. 5.4.3 Vol. –I of Contract Agreement causing emission of bad odour in and around the facility. This is eventually disturbing ecology and life of nearby households against which large number of complaints have been pouring in from the RWAs in the vicinity of that area.
 - (iv) The firm claimed the presence of excess sulphide in raw sewage being received at 45 MGD STP, as culprit for bad odour / corrosion of equipments / wear & tear of equipment AND WHEREAS a report submitted by Quality Control Wing of DJB confirms presence of sulphides at other STPs like 25 MGD Ph-II, and 9 MGD Chilla, located either in the same premises or in the vicinity thereof being operated & maintained by other O&M contractors. However, not such complaints, due to the said

reasons have been reported so far from STPs other than 45 MGD STP.

(v) supply and control of the acility.

The firm has ailed to comply with some of the recommendations given by IIT I elhi in its report cated 17.01.2017 such as provision of one extra diffuser sub-grid, installation of module grid for air utomatic control system for better operation and

(vi) In addition premises an conditions.

above there have been occasions where no deployment (O&M staff was found even at very critical units like inlet works / I imary units making the plant dysfunctional. This led to overflow a d consequent scattering of raw sewage inside STP adjoining residential colony creating unhygienic

11.

AND WHEREAS, as a res it of poor performance of the plant, proposal was placed before debarment or mmittee for deliberation and deciding further course of action against Executing gency M/s VA Tech Wabag Ltd.

12. Agency raised the issue

AND WHEREAS, pursuant to the debarmer t committee meeting, a personal hearing was granted on 25 09.2020, which was attended by Sh. Rajiv Mittal, Managing Director, on be alf of M/s VA Tech Wabag Ltd. The Executing of sulphide con ents, excess flow at the STP, requirement of sludge beds or sludge disposal and force majeure etc.

13.

AND WHEREAS, the committee heard views of Executing Agency intently. But the Executing Agency wa unable to satisfy the committee with concrete reasons behind the non-op ration of electrical and mechanical equipments at the plant, its inability to sabilize the power generation, and its inability to achieve the treated effluent arameters on regular basis.

inspection/night duty that seriously and communicate (DPCC) for necessary actic 31(A) of Air(Prevention and I ontrol of Pollution) Act, 1981.

AND WHEREAS, various in tances were also recorded by DJB during surprise executing Agency was bypassing the untreated sewage/sludge into river Y muna thereby clearly violating the conditions of Contract Agreement and als direction of Hon'ble NGT. DJB had viewed it very the same to Delhi Pollution Control Committee against the Executing Agency for bypassing the untreated sewage which is gainst the Environment (Protection) Act. The Delhi Pollution Control Committee (DPCC) in response to DJB's letter has issued Show Cause Notice vide ated 18.09.2020 to the Executing Agency under section 33(A) of Water(Prevention and Control of Pollution) Act, 1974 and u/s

15. Environment (Protection) Ac reputational damages due 1

AND WHEREAS, DJB has suffered power loss, loss under the provisions of loss of endangering life and property and Selected Bidder's fundamental breaches to the Contract Agreement, and Selected Bidder's persistent poor performance in

Page 5 of 9

respect to the Operation and Maintenance of the 45 MGD STP Phase-IV at Kondli.

16. AND WHEREAS in view of above and taking into consideration all the facts and records, as per the recommendations of Debarment Committee who have unanimously come to the conclusion that:
"M/s VA Tech Wabag Limited is hereby debarred for the period of 3 (Three)

"M/s VA Tech Wabag Limited is hereby debarred for the period of 3 (Three) years from participating directly or indirectly in any work/tender/bid connected with Delhi Jal Board".

- 17. AND WHEREAS approval was obtained from the Competent Authority for "Debarring "M/s VA Tech Wabag Limited for the period of 3 (Three) years from participating directly or indirectly in any work/tender/bid connected with Delhi Jal Board".
- 18. Therefore, Executing Agency M/s VA Tech Wabag Limited is hereby conveyed that "M/s VA Tech Wabag Limited is debarred for the period of 3 (Three) years with immediate effect from participating directly or indirectly in any work/tender/bid connected with Delhi Jal Board".
- This letter is issued without prejudice to any other right or remedy available to the Authority under the Contract Agreement and/or applicable law.

20. This is issued with the approval of the Competent Authority.

(Rakesh Kumar Kaushik) — Executive Engineer (SDW)-IV

Copy to Water and Sewage Utilities of all States/UTs through their Chief Secretary/ Administrator to Hon'ble LG of UTs:-

S. No. 1.	State / UTs Andaman & Nicobar Islands	Address Office of the Andaman & Nicobar
2.	Andhra Pradesh	Administration Secretariat, Port Blair Office of the Chief Secretary Government of Andhra Pradesh Velagapudi Amaravati-522503
3.	Arunachal Pradesh	Office of the Chief Secretary Government of Arunachal Pradesh, Itanagar-791111
4.	Assam	Office of the Chief Secretary Government of Assam, P.O. Assam Sachivalaya, Guwahati-781006
	:	Page 6 of 9

5.	Bihar	Office of the Chief Secretary Government of Bihar, Main Secretariat Building, Patna- 800015		
6.	Chandigarh	Office of the Administrator, 4th floor, Haryana Civil Secretariat, Chandigarh		
7.	Chhattisgarh	Office of the Chief Secretary Government of Chhattisgarh, Mahanadi Bhawan, Mantralaya, Naya Raipur-492002		
8.	Dadra and Nagar Haveli	Office of the Administrator Dadra and Nagra Haveli Secretariat, 66 KVA Road, Amli, Silvassa-396230		
9.	Daman and Diu	Office of the Administrator Union Territory of Daman & Diu, Secretariat, Moti Daman-396220		
10.	Goa	Office of the Chief Secretary Government of Goa, Panaji-403001		
11.	Gujarat	Office of the Chief Secretary Government of Gujarat, Block No. 1, 5th Floor, Sardar Bhawan, Sachivalaya, Gandhinagar-382010		
12.	Haryana	Office of the Chief Secretary Government of Haryana,———————————————————————————————————		
13.	Himachal Pradesh	Office of the Chief Secretary Government of Himachal Pradesh, ** Shimla-171002		
14.	J&K	Office of the Administrator Government of Jammu & Kashmir, Shrinagar-190001		
15.	Jharkhand	Office of the Chief Secretary Government of Jharkhand, Ranchi- 834001		
16.	Karnataka	Office of the Chief Secretary Government of Karnataka, Bangalore-560001		
17.	Kerala	Office of the Chief Secretary Government of Kerala, Thiruvananthapuram- 695001		

Page **7** of **9**

18.	Lakshadeep	Office of the Administrator Union territory of Lakshdweep, Lakshdweep House, Kavaratti-68258
19.	Leh and Ladakh	Office of the Commissioner/ Secretary, UT Secretariat, Leh and Ladakh.
20.	Madhya Pradesh	Office of the Chief Secretary Government of Madhya Pradesh, Bhopal-462004
21.	Maharashtra	Office of the Chief Secretary Government of Maharashtra, Mantralaya, Mumbai- 400032
22.	Manipur	Office of the Chief Secretary Government of Manipur, Old Secretariat, Bapupara, Imphal-795001
23.	Meghalaya .	Office of the Chief Secretary Government of Meghalaya, Shillong- 793001
24.	Mizoram	Office of the Chief Secretary Government-of Mizoram, Aizawl- 796001
25.	Nagaland	Office of the Chief Secretary Government of Nagaland, Kohima – 797001
26	. Odisha	Office of the Chief Secretary Government of Odisha, Bhubaneshwar- 795001
27	Puducherry	Office of the Chief Secretariat Govt. of Puducherry, Goubert Avenue PUDHUCHERRY- 605001
28	B. Punjab	Office of the Chief Secretary Government of Punjab, Chandigarh- 160001
29	Rajasthan	Office of the Chief Secretary Government of Rajasthan, Jaipur-302005.
30	0. Sikkim	Office of the Chief Secretary Government of Sikkim, New Secretariat, Development Area, Gangtok-737101 Page 8 of 9
		100000

31.	Tamil Nadu		Office of the Chief Secretary Government of Tamilnadu, Chennai- 600009
32.	Telangana		Office of the Chief Secretary Government of Telangana, Secretariat, Hyderabad-500022
33.	Tripura		Office of the Chief Secretary Government of Tripura, New Secretariat Complex, Agartala– 799011
34.	Uttar Pradsesh		Office of the Chief Secretary Government of Uttar Pradesh, Shri Lal Bahadur Shastri Bhawan, Lucknow- 226001
35.	Uttarakhand		Office of the Chief Secretary Government of Uttarakhand, Dehradun-248001
36.	West Bengal	A 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Office of the Chief Secretary Government of West Bengal, Kolkata- 700001

Executive Engineer (SDW)-IV

Copy for information to:-

- 1. OSD to Chairman, DJB
- 2. OSD to Vice Chairman, DJB
- 3. PS to CEO, DJB
- 4. Member (Dr.)/Member (WS)/Member(F)/Member(A)
- 5. CVO
- 6. All CEs/Dir (F&A)/Dir(A&P)/Dir(Revenue)
- 7. All SEs
- 8. All EEs
- 9. EE(EDP) To upload in the DJB website
- 10. All AOs
- 11. All AAOs

12. Office Copy/Case File

[EE (ENP)-Toupload in the DJD

Executive Engineer (SDW)-IV

Prog I 2218 2020