## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F5/(3A)/DF5/005/2011/194

Dated: 16/08/11

## FIRE SAFETY CERTIFICATE

Certified that M/s. Lotus Automobiles, Petrol Pump cum Service Station located at 76/26. Andheria Mod, Mehrauli Gurgaon Road, Mehrauli, New Delhi - 110030 was granted NOC by this department vide letter No.F5/(3A)/DFS/2009/116 dated 19-03-2009. The premises was re-inspected by the officer concerned of this department on 25-07-2011 in the presence of Sh. Joginder Singh, General Manager of the service station comprised of ground plus one upper floor owned / occupied by M/s. Lotus Automobiles have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class of Petroleum (Petrol Pump) with effect from 1.6.0.00/.lu.....for a period of Three Years in accordance with Rule 36 unless renewed under Rule 37 of sooner cancelled under rule 40 and subject to compliance of the conditions Rule 38 of the Delhi Fire Service Rule-2010

CHIEF FIRE OFFICER DELHI FIRE SERVICE

9/1

Copy to:

 The Administrative Officer (South Zone), Municipal Corporation of Delhi, Office of the Assistant Commissioner (South Zone), Green Park, New Delhi

Sh. Rajinder Kuamr.
M/s. Lotus Automobiles.
Khasra No.76/26, Andheria Mod.
Mehrauli Gurgaon Road, Mehrauli,
New Delhi - 110030

## Ref. letter No. 166/AC/SZ/09 dated 04-05-2011

May kindly see the above mentioned letter received from, The Administrative Officer (South Zone), Municipal Corporation of Delhi, Office of the Assistant Commissioner (South Zone), Green Park, New Delhi regarding renewal of NOC of trade license in favour of Sh. Rajinder Kumar, M/s. Lotus Automobiles, Khasra No.76/26, Andheria Mod, Mehrauli Gurgaon Road, Mehrauli, New Delhi - 110030.

In this connection, it is to inform you that the above mentioned premises was inspected by the undersigned on 25-07-2011 to verify the existing fire protection arrangements as already provided therein. Sh. Joginder Singh, General Manager was also present at the time of inspection.

During the course of inspection, it was observed that the petrol pump is comprised of ground plus one upper floor is located on the right side of the license premises. The ground floor consist of lube bay, office, a sales room and first floor has one office cum storage and staff room. The staircase leading to first floor is directly leading out side the building. The canopy is away from the main building. The electric wiring is concealed, MCB are provided or the main and distribution electric circuit. There are 2 Nos. of 20000 ltr. underground petrol storage tank each of MS petrol and Xtra Premium respectively having 18 No. of nozzles. Similarly, 1 No. of 20000 ltr. underground diesel (HSD) tank and 1 No. of 50000 ltr. each and 1 No. of 20000 ltr. underground Xtra mile diesel tank having 8 Nos. and 2 Nos. nozzles respectively. Further, the following fire safety arrangements required under rule 33 are provided.

- Access to Building: Provided (Main Mehrauli Gurgaon road) 1.
- Number, Width, Type and arrangement of exits: Provided (one 2. staircases having width 1.50 mtr.)
- Protection of Exits by means of fire check door(s) and or 3. pressurization: Not required.
- Compartmentation: Not required. 4.
- Smoke management system: Not required 5.
- Fire Extinguishers: Provided (4 Nos., CO2 type fire extinguishers in 6. 4.5 kg capacirty ISI marked and 7 Nos. of DCP type extinguishers in 10 kg., capacity ISI marked, 8 Nos. dry sand fire buckets, 2 Nos. AFFF type fire extinguishers in 9 ltr. capacity ISI marked)
- First Aid Hose Reels: Not required 7.
- Automatic Fire Detection and alarming system: Not required. 8.
- MOEFA: (Manually Operated Electric Fire Alarm): Not required 9.
- Public Address System: Not required 10.
- Automatic sprinkler system: Not required 11. Internal Hydrant and yard Hydrant: Not required
- Pumping arrangements: Not required 13.
- Captive water storage for fire fighting: Not required 14.
- Exit Signage: Provided 15.

12.

## Special Fire Protection system for protection of Special risks: Not required

The above mentioned fire safety arrangements were checked/tested randomly and found in good working condition at the time inspection.

In view of the above, this department may have no objection for the renewal of N.O.C. from fire safety and means of escape point of view subject to the conditions laid down in the fire safety certificate.

Accordingly fire safety certificate is prepared and put up for perusal and signature if approved please.

DO (BCP)

Dy.CF.

Es Din

Ar hus

Mari

As approved, F.T. letter is putup for your synature please.

SEE PLINE

12/8/201