

No: F6/DFS/MS/EH/2011/2147

Dated: 02/08/11

To

The Health Officer,
Civil Line Zone (MCD),
16 Raj Pur Road,
Delhi.

FIRE SAFETY CERTIFICATE

Certified that the – Nirula's Corner House (P) Ltd, located at Delhi University Delhi comprised of - ground floor- occupied by- M/s Nirula's Corner House (P) Ltd, was issued NOC vide this officer letter No. F.6/DFS/MS/EH/08/3001 dated 03.11.2008. The premises was re-inspected by the officer concerned of this department on 04.08.2011 and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working conditions. The premises have therefore, deemed complied with the requirement under rule 33 of the Delhi Fire Service Rules, 2010 and the building/premises is fit for occupancy class Assembly with effect from. 02/08/11 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules,2010.

Issued on02/08/11.....at New Delhi by

Yours Faithfully

Chief Fire Officer
Delhi Fire Service

Copy to :

- I. Mr. R.B.Yadav,
Security Officer
M/s Nirula's Corner (P) Ltd.

May kindly see the letter no DHO/CL2/2011/543
 dt-28/6/2011 received from DHO, CL2 Delhi regarding
 issuance of no objection certificate in Nyo Nirula's
 Corner house (1) Ltd. Delhi University Delhi. In
 this regard an inspection was carried out by
 me & signed on 4/7/2011 from fire safety point
 of view. Sh. Avinash Chandra Security Manager
 and Sh. R.B. Yadav Security Officer were present at the
 time of inspection.

During the course of inspection it has
 been observed that the restaurant is located
 on the ground floor in a double story bldg.
 The 1st floor is being used as DUTA office
 having separate stair case. The electrical
 wiring were laid through concealed type
 MCBs also installed there. The existing
 fire safety arrangements were checked as per
 NBS Act. The detail is as under.


- 1) Access : provided 30' wide road.
- 2) No. width type of exit
 Exit : 3 nos of exit/entrance.
 The 2 nos of 1.50 mtr. each and one
 of 1.20 mtr.
- 3) Protection of exits : Not Required
- 4) Compartmentation : Not Required.

- No 8
- 5) Smoke Management System \rightarrow provided Exhaust fan.
 - 6) Fire Extinguishers \rightarrow provided CO_2 & Water CO_2
Fire Extinguishers 1-5-1 marked.
 - 7) First Aid first aid kit \rightarrow provided.
 - 8) Automatic fire detection & Alarm System \rightarrow Not Required.
 - 9) MOPFA \rightarrow provided.
 - 10) I-A-System \rightarrow Not Required.
 - 11) Sprinkler System \rightarrow Not Required.
 - 12) Internal Hydrant \rightarrow provided Down Coma System.
 - 13) Pumping Arrangement \rightarrow provided 4.50 cfm
Cap. with 40 mtr. head.
 - 14) Captive water storage for firefighting \rightarrow provided 0-H. Tank
of 5000 ltr.
 - 15) Exit Signage \rightarrow provided.
 - 16) Provision of lift \rightarrow Not Required.
 - 17) Stand by power supply \rightarrow provided Df set 62.5 kVA.
and Emergency light (Inverter)

- 18) Refuse Area - Not Required.
- 19) Control Room - Not Required.
- 20) Spl. Fire Protection - Not Required.

The above said fire safety arrangements were checked / tested and found in satisfactory working condition.

In view of the above satisfactory fire safety arrangement provided by the management. ^{for the renovation} NCC is recommended. A fire safety certificate is placed opp. side in the file for approval & sign. pl.

Submitted to
 In Chg. (Do HC Aneja) 
 19/11/11