GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/EH/2011/ 2 1 3 5

Dated: 02/09/11

FIRE SAFETY CERTIFICATE

Certified that the M/s Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.) located at 1st floor, Community Centre, New Friends Colony, New Delhi is running at first floor, comprised of ground plus one upper floor was granted 'NOC' by this department vide letter No. F.6/DFS/MS/EH/2009/3036 dated 15-10-2009 have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and verified by the officer concerned of Delhi fire service on 29.07.2011 in the presence of Mr. Ravi Sethi, Manager of the restaurant and that the building/premises is fit for occupancy class Assembly building (Restaurant) with effect from \(\textit{Manager} \frac{1}{2} \) \(\frac{1}{2} \) \(\frac{1}{2} \) for a period of 3(three) years in accordance with rule 36 unless renewed under rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions given below.

Issued on $\frac{e^2}{4}$ at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to: -

- The DEO (Restaurant), GNCT of Delhi, Excise & Tax Department, L & J Block, LP.Estate, New Delhi
- The Authorized Signatory, M/s Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.) located at 1st floor, Community Centre, New Friends Colony, New Delhi

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in

Ref:- Letter No. nil dated nil

With reference above quoted letter received from the Authorized Signatory, M/s Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.) regarding the grant of fire safety certificate in respect of M/s Yum Yum Tree Restaurant (a unit of Tusaj Lifestyle Pvt. Ltd.) located at 1st floor, Community Centre, New Friends Colony, New Delhi.

The restaurant premises have been inspected by ADO(Mathura road) in presence of Mr Ravi Sethi, Manager on 29-07-2011 to verify the shortcomings pointed out in earlier inspection which was communicated vide letter dated 21-03-2011. The said restaurant is located in the first floor of a building comprised of ground (shops of other party) and first floor(restaurant). The management have complied all the shortcomings as seen during inspection. The details of fire safety arrangements is as under:-

- Access:- The restaurant is located on the community centre complex and approachable
- Number, Width, type & arrangement of exits:- Two independent staircases having width 1.5 mts and 1.0 mts width in front and rear side have been provided in the
- Protection of exits by means of fire check door and or pressurization:- Not required. All the staircases are independent and directly opening to the outside open area. 3.
- Smoke management system: Smoke venting system have been provided in the 5
- Fire extinguishers: 04 nos of Water CO2 type fire extinguishers of 9 lts capacity each and 04 number of CO2 type fire extinguishers of 4.5 Kg capacity each have been 6.
- First aid hose reel: 01 nos of first aid hose reel found provided in the restaurant. provided in the restaurant. 7.
- Automatic fire detection & alarming system:- Not required but provided in the entire 8. restaurant and found functional.
- MOEFA:- Provided and found functional 9.
- Automatic sprinkler system:- Provided in the entire restaurant and found functional. Public address system:- Not required
- Internal hydrants & yard hydrants:- Down comer system with hose box containing 02 11. delivery hoses and one branch pipe found provided and functional. 12.
- Pumping arrangement: 600 LPM and 225 LPM capacity fire pumps found provided on the terrace connected with over head water tank. 13.
- Captive water storage for fire fighting: 5, 000 lts capacity over head water storage tank with boosting arrangement found provided on the terrace for fire fighting 14. purposes.
- Exit signage:- Provided
- 17. Stand by power supply:- 125 KVA generator connected with all essential supplies like 16. Provision of lifts:- Not applicable fire pumps, corridors lights etc found Provided & functional
- 18. Refuge area:- Not required
- Special fire protection systems for protection of special risk:- 02 nos ABC type fire 19. Fire control room: Not required extinguishers found provided near the electric panel.

In view of the satisfactory functionability of fire safety arrangements in the said restaurant, this department may have no objection for the renewal of fire safety certificate subject to the conditions laid down in the certificate. Accordingly fire safety certificate is prepared and put up for perusal and signature please

Do (B(P) 14)

Ado: M. E. Chartoupudly