## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No F 6/DFS/MS/2011/ Motel 2381

Dated 30 09/11

#### FIRE SAFETY CERTIFICATE

Certified that the Motel building in the name and style of M/s TRICOLOR HOTELS LTD at kh. No. 22/10,22/11,23/6,23/7,8/2/1,23/15,23/7,23/14/1,8/2/1,23/15,23/16/1 at NH-8, Village Samlkha, New Delhi was granted NOC by this department vide letter No F 6 / DFS / MS / 2006 / 1255 dated 06.06.2006. The premises was re-inspected by the officer concerned of this department on 08.09.2011 in the presence of Sh. Anjan Sen Gupta (DGM Hotel) and other technical staff and found that the said Motel building have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy with effect from 3.9 \( \lambda 9.4 \)... for a period three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on Solos for at New Delhi by.

CHIEF FIREOFFICER DELHI FIRE SERVICE

## Copy to: -

- The Joint Director (Bldg) C&I, DDA Building Section, INA Vikas Sadan, New Delhi.
- Sh. Aman Sarin, M/s TRICOLOR HOTELS LTD at kh. No. 22/10,22/11,23/6,23/7,8/2/1,23/15,23/7,23/14/1,8/2/1,23/15,23/16/1 at NH-8, Village Samlkha, New Delhi

#### Conditions for the validity of fire safety certificate

- All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire protection measures shall be maintained in perfect working conditions all the times as seen during inspection.
- 3. All the staff members must know the correct method operation of fire fighting system.
- Any lapse rendering fire fighting system/equipment non-functional shall be risk and responsibility of the management.
- This inspection report may not in any way be treated as regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

Remend

		SPECTION REPORT Motel building in the name of style of Teicolor Hotels 2 to at the name 2/10 22/19 23/6 23/7 8/2/1 23/15 23/7 23/14/12 (23/16/11: NH-8, SAMALKHA, NEW BECK)				
	3 T CO	: New Case/ Renewal				
	- 127					
	4. Details of previous NOC : Le	tter No. F6/DFS/MS/B.P/GH/2005/351/ dated 18-02-				
	5. Fire Safety directives letter No F6/DF5/MS/B.P/GH/2005/351/ dated 18-0					
	6. Date of inspection : (8-09-1)					
	Name of the Inspecting Officers : Assistant Divisional					
	Surrey of officers					
į.		m the building side SH. Angan Sen Gupta (DGM Ho)				
S.	Applicant's letter No.	36432-37/1	ddf.c.P/Lie.	(4) alt 0. 01.0		
No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC / BR	Provided at site	Remarks		
1	Access to building MR/NMR					
	<ul> <li>Road width</li> </ul>	12 intes	and the second second			
	Gate width	5 mtss	90 mtgs	m.R		
	<ul> <li>Width of internal road</li> </ul>	5 MLES	06 MZES	MR		
2		N.R.	N. R	M. R		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	09	04	m.R. B		
	<ul> <li>Basements</li> </ul>	08	08			
	b. Width of staircases			M. R.		
	Upper Floors	1.25MZ85	1 - 4			
1	<ul> <li>Basements</li> </ul>	1.50 mts	1.5 mts	MR		
	c. Protection of exits	1 307108	1.5 Miss	m. R		
	<ul> <li>Fire check door</li> </ul>	Neggiorat				
	<ul> <li>Pressurization</li> </ul>	Required	Provided	MR		
	e. No. of continuous staircases to terrace	Required in	Provided in	M.R		
	g. Width of Corridor	Fork	Fores	M.R.		
19	h. Door Size	1.25 MB	1.5Mty	m.R		
1	II. DOOL SIZE	1 mts	1 mtz	0.60000 (55)		

contd:

	Compartmentation.				
	Fire check door	Required.	Provided	M. K	
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required. Required	Provided.	0.00001	
	<ul> <li>Fire Rating of shaft door</li> </ul>	146-	1 /2-	M. R	
	Water Curtain	N.R.	N.R.	M.R.	
	<ul> <li>Fire Dampers</li> </ul>	Required.	Horided		
4	Smoke Management System.	Neg - sec-	7		
	Basements	30 a/c per hour	Provided.	M.R	
	Upper floors	12 a/c per hour	flovided.	M.R.	
	**************************************		-		
5	Fire Extinguishers				
	<ul> <li>Total numbers</li> </ul>	48	24+24=48	Mik	
	Types	contype45kg	water con type q & con type q & skg. All 151 make.	Da M.K	
	IS marking	ISI marked 9 44	All 1.51 model	M.R.	
6	First-Aid Hose Reels.				
	<ul> <li>Total numbers on each floor</li> </ul>	3	12	MR	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided-	MR	
	Nozzle diameter	5 mm	Provided.	M.R.	
7	Automatic fire detection and alarming system.				
	Type of detectors	N.R	N-R	ps. R	
	Location of Main Panel	N-R	N.R.	m.R	
	<ul> <li>Location of Repeater Panel</li> </ul>	N.R.	N. R.	M.R	
	Alternate source of power	N.R.	N.R.	M.R.	
	Hooters' Location	N.R.	N.R.	m.R.	
8	MOEFA	Required.	Previded.	M.R.	
9	Public Address System.	Required.	Provided	M. R.	
10	Automatic Sprinkler System.				
	Basement	Required.	Provided-	M.A.	

contd: -

# motel Tricolde, SAMALKAA

	<ul> <li>Upper Floor</li> <li>Sprinkler above false ceiling</li> </ul>	Required.	(a) (b)			
7595c		Not Equie	1 Provided.	M.R.		
11	Internal Hydrants					
	Size of riser/down-comer	100 MM.	100 MM.	M.R.		
	Number of hydrants per floor     Hose Box	3	3	m.R.		
0.0-		3	3	M.R.		
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	09	09	M.R.		
	Hose Box	09	09	m.R.		
13	Pumping Arrangements.					
	Ground Level					
	<ul> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual</li> </ul>	2280 LPM.	2280 LPM	M.R		
		60 M.	60 M	M.R.		
		one	one	M-R		
		180 L.P.M	180 LPM	M.R		
		Bo m	60 M	M·R		
		2280 LPM	2280 LPM	M.R.		
		60 M.	82 m.	M.R.		
	stopping	Acito Statting	Provided .	M.R.		
	<ul> <li>Pump House Access</li> <li>Terrace level</li> </ul>	leguised.	Provided.	M.R.		
	> Discharge of pump	N.R	N.R			
	➤ Head of the prime.	N.R	N. R.	m. R		
7.	➢ Power Supply	N.R	N.R	m.R		
	> Auto Starting of pump	N.R.	N.R.	m.R.		
14	Captive Water Storage for fire is a sage		Tax Tax	The state of the s		
	Underground tank capacity		100,000 10	N. R.		
	Draw-off connection	Required.	Provided.	M.R.		

cortal: -

Reman

4

	➤ Fire service inlet  ➤ Access to tank  • Overhead Tank	Requised.	Peridal	m. R	
15	Overhead Tank capacity	10,000 Liz	) e		
	Exit Signage.	Required.	Provides	1 - m.R.	
16	Provision of Lifts.			11. X.	
	Pressurization of Lift Shaft	Required.	Provided	- M.R.	
	Pressurization of Lift lobby	Not kegun	N.R.	M. R	
	Communication In lift Car	Requirest	Provided.	m.R.	
	<ul> <li>Fireman's Grounding Switch</li> </ul>	-		250	
	Lift Signage	Respuded	provided.	M.R.	
		Required.	Pravided-	m.k.	
17	Standby power supply	Required	500KVA	200.	
18	Refuge Area.	762	D.G. Set	M.R.	
	> Total Area				
	> Location	N-R	N.R		
10		N. R	N. R.		
19	Fire Control Room				
	Detector System Panel	N.R	· N. R		
	<ul> <li>Flow Switch Panel</li> </ul>	N.R.	NR		
	PA System Panel	N.R.	N.R.		
	Batter backup	N. R.	N.R.		
	<ul> <li>Building Floor Plans</li> </ul>	N.R.			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N.R.	N.R.		

The fire protection systems provided in the building were test checked and found functional at the time

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue-shortcomings as noted at serial numbers.

(5)

Signature of the Inspecting Officer

Name S.S. Karyling
Designation ASSH Dividira

Signature of the Inspecting Officer 73//

Name D.S. yadar.

Designation ADO