FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE [SEE SUB-RULE (1) OF RULE 35]

OVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/0Fs/ons/2011/2410

Dated: 6 4/10 /2011

FIRE SAFETY CERTIFICATE

Certified that the M/s Murti Hospitality Pvt. Ltd. at Kh.N. 86/10, 86/11, 86/20, 78/21, 86/1 & 85/15/2 Gehevra, Delhi, comprised of Basement + Ground + first floor, owned/occupied by M/s Murti Hospitality Pvt. Ltd has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 27/09/2011 in the presence of Sh. Rajender Aggarwal (owner) and that the building/premises is fit for occupancy Class D (Assembly) with effect from \(\infty \frac{1}{2} \infty \infty \infty \frac{1}{2} \infty \infty \infty \frac{1}{2} \infty \infty \infty \frac{1}{2} \infty \infty

Issued on 54 / 19 / 1.1at New Delhi by

Chief Fire Officer Delhi Fire Service

Copy to: The Director

M/s Murti Hospitality Pvt. Ltd.

Kh.N. 86/10, 86/11, 86/20, 78/21, 86/1 & 85/15/2 Gehevra. Delhi

010

Following fire safety directives must be adhered to:-

- All the fire safety arrangement provided their in shall be maintained in good working conditions at all time.
- Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3) The trained fire fighting staff should be available round the clock.
- Any deviation, with regards to construction etc shall be verified by the concerned building sanctioning agency.
- 5) The basement shall be used strictly as per the provision of building Bye-Laws.
- 6) This certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. This is available on www.dfs. delhigovt.nic.in

May kindly peruse letter nil dated 08/09/2011 received from Director, Murti Hospitality Pvt. Ltd. intimating regarding compliance of fire safety guidelines issued vide letter no. F6/DFS/MS/BP/2006/1984 dated 09.08.2006 and requesting to inspect the premises & issue NOC. Accordingly building was observed that it is a resort with restaurant and rooms (18 app). Point wise compliance of the fire safety guideline are summarized as below.

1. Name &address of the building : Murti Hospitality Pvt. Ltd. K.N. 86/10, 86/11, 86/20,

78/21, 86/1 & 85/15/2 Gehevra, Delhi

2. Type of Occupancy : Assembly

3. Type of Case : New Case

4. Details of previous NOC : N.A.

Fire Safety directives letter No. : F-6/DFS/MS/BP/2006/1984

6. Date of inspection ± 27/09/2011

Name of the Inspecting Officers : DO Sunil Chowdary (D.O. West)

8. Name and designation of officers

From the building side : Sh. Rajesh Yadav, Manager

9. Year of Construction : 2006-2007

10. Applicant's letter No. : Nil Dated 08/09/2011

INSPECTION REPORT

Point wise fire safety arrangements/equipments are mentioned as under:-

S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL Requirement	Provided at site	Remarks MR/NMR	
	Access to building				
	Road width	9 mtrs	60 mtr	M.R.	
	 Gate width 	5 mtrs	6 mtrs	M.R.	
	Width of internal road	6 mtr	6 mtr	M.R.	
2.	Number, Width, Type & Arrang	ement of Exits			

	Number of staircases				
	Upper Floors	Two	05 nos	M.R. /	
	Basement	Two	05 nos	M.R/	
	b. Width of staircases				
	Upper Floors	5 feet	5 feet /	M.R.	
	Basement	5 feet	5 feet /	M.R.	
	c. Protection of exits				
	Fire check door	Required	Provided	M.R.	
	 Pressurization 	N.A.	N.A.	M.R.	
	d. No. of continuous staircases to terrace	Two	03	M.R.	
	e. Width of Corridor	5 feet	5 feet	M.R.	
	f. Door size	1 mtr	1 mtr	M.R.	
3.	Compartmentation.				
	Fire check door	Required	Provided as show in the plan	M.R.	
	Sealing of electrical shafts	Required	sealed	/ M.R.	
	Fire Rating of shaft door	4 hrs	4 hrs	/ M.R.	
	Water Curtain	N.R.	N.A.	/ M.R.	
	Fire Dampers	Required	Provided	/ M.R.	
1.	Smoke Management System.				
	Basements	Required	Provided	/ M.R	
	Upper floors	N.R	Provided	M.R	

	Fire Extinguishers					
1	Total numbers	20	36	M.R		
	• Types	CO ² , WCO ² , DCP	CO ² , WCO ² ,	M.R		
	IS marking	Reqired	yes	M.R.		
6.	First-Aid Hose Rees.					
	Total numbers on each floor	03	03 nos	M.R.		
	Length of hose reel hose	30 mtr	36 mtr	M.R.		
	Nozzle diameter	5 mm	20/6	M.R.		
8	Automatic fire detection and alarming system.					
	Type of detectors	N/R	Smoke detectors provided	M.R.		
	Location of Main Panel	N/R	G. floor	M.R.		
	Location of Repeater Panel	N/R	Reception	M.R.		
	Alternate source of power	N/R	UPS/Battery	M.R.		
	Hooter's Location	N/R	staircase	M.R.		
3.	MOEFA	Required	provided	M.R.		
).	Public Address System.	Required	provided	M.R.		
10.	Automatic Sprinkler system					
	Basement	required	provided _	M.R.		
	Upper Floor	N/R	Provided	M.R.		
	 Sprinkler above false ceiling 	N.R.	Provided .	M.R		

	Size of riser/down-comer	150 mm	150 mm /	M.R.		
	 Number of hydrants per floor 	03	03 nos _	M.R.		
	Hose Box	03 per floor	03 nos provided	M.R.		
2.	Yard Hydrants.					
	Total number of hydrants	N.R.	05 nos /	M.R.		
	Hose Box	N.R.	05 nos /	M.R.		
13.	Pumping Arrangements.					
	Ground Level	1/2				
	 Discharge of main pump 	N.R.	1620 LPM	M.R.		
	➤ Head of Main pump	45 mtr	97.2 m	M.R.		
	> Number of main pumps	one	Two	M.R.		
	> Jockey Pump out put	N.R.	180 LPM /	M.R.		
	Jockey pump head	N.R.	7.2	M.R.		
	Standby pump out put	1620 LPM	97.2 m	M.R.		
	> Standby pump Head	N.R.	97.2 m	M.R.		
	 Auto Starting/Manual stopping 	N.R.	Auto	M.R.		
	> Pump Hose Access	Required	Provided	M.R.		
	Terrace level	900 LPM	900 LPM	M.R.		
	 Discharge of pump 	35	35 mtr /	M.R.		
	Head of the pump		7			

	➢ Power supply	Required	12.5 HP	M.R.		
	> Auto Starting of pump	N.R.	Provided	M.R.		
14.	Captive Water Storage for fire fighting.					
	Underground tank capacity	N.R.	150 KL provided	M.R.		
	> Draw -off connection	N.R.	150 mm provided	M.R.		
	➢ Fire service inlet	N.R.	150 mm provided	M.R.		
	> Access to tank	N.R.	provided /	M.R.		
	Overhead Tank Capacity	15000	20,000	M.R.		
15	Exit Signage.	required	Provided	M.R.		
16.	Provision of Lifts		A 2			
	Pressurization of Lift Shaft	N.R.	N.R.	M.R.		
	Pressurization of Lift lobby	required	provided	M.R.		
	Communication In lift Car	required	provided	M.R.		
	Fireman's Grounding Switch	required	provided	M.R.		
	Lift Signage	required	provided	M.R.		
17.	Standby power supply	N.R	D.G. set 62K.V.A	M.R.		
18.	Refuge Area					
	> Total Area	Required	N.R.	M.R.		
	➤ Location	N.R.	N.R.	M.R.		
19.	Fire Control Room		+			

	➤ Detector System Panel	N.R.	Provided	M.R.
	➤ Flow Switch Panel	N.R.	provided	M.R.
	> PA system Panel	required	provided	M.R
	> Batter backup	N.R.	Provided /	M.R.
	➤ Building Floor plans	Required	available /	M.R.
20.	Special Fire Protection Systems for	N.R.	N.R.	M.R.
	Protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/.

Signature of the Inspection Officer

Signature of the Inspection Officer

Name SUNIL CHAMBDELY

Name

Designation (. (wwst))

Designation