GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO. F6/0F5/ms/2011/2633

DATED: 21/10/11

FIRE SAFETY CERTIFICATE

Certified that the M/s DLF Promenade Mall building at Plot No-3, Nelson Mandela Marg, Vasant Kunj New Delhi-110070 comprise of two basement, lower ground, upper ground, first floor and projection room was granted NOC by this department vide letter no. F.6/MS/DFS/2008/2663 dated 19.09.2008. The premises was re-inspected by the officer concerned of this department on 27.09.2011 in the presence of Cap. Vikas Yadav, of the mall and that the building is fit for occupancy class "Merchantile building" with effect from ... 21/10/1011.... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to condition under rule 38 of the Delhi Fire Service Rule 2010, as mentioned below.

Issued on at New Delhi by

Chief Fire Officer Delhi Fire Service

Copy to,

1. The Jt. Director (Bld), DDA, Building Section INA, Vikas Sadan, New Delhi.

 The Authorized Signature, DLF Promenade Mall, Plot No-3, Nelson Mandela Marg, Vasant Kunj New Delhi-110070.

Conditions for the validity of fire safety certificate

a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.

 Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.

c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.

d. The basement shall be used strictly as per the provisions of Building Bye laws.

e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Name & Address of the building: DLF Promerade Mall Plat No 3 Vasant Kung Nelson Mendale 1. : Merchantile Type of Occupancy 2. Type of Case : New Case/ Renewal L 3. : Letter No. 6 10 15 ms 20 426 Dated: 19/9/08 Details of Previous NOC 4. Fire Safety directives letter No. : F(1075)ms 18 P | 2005 1 (18) 5. 27/9/11 6. Date of inspection : DO South D.P. Bhardway ADOST SS Kausher 7. Name of Inspecting Officers 8. Name and designation of Officers : Cop Vikash Yadav from the building side 2007 Year of construction 9.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at Site	Remarks MR/NMR
1.	Access to building			
	 Road width Gate width Width of internal road 	Require Lond Reguire Contr Reguire Contr		ML ML
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases • Upper floors • Basement	ANO 2f NO	19 HES hord	
	b. Width of staircase Upper Floors Basements c. Protection of exits	1.5 mely	1.5 mln	ML
	Fire Check door Pressurization No. of continuous staircases to terrace	Negun	Provided Provided	Mr. Mr.
	e. Width of Corridor f. Door Size	3 my	3-35 mine 335 min	MI
3.	Compartmentation.			
	Fire check Door Sealing of electrical shafts	Muira	Provided	MK

	Fire rating of shaft door	2hm	2hu	ml	
	Water curtain Fire Dampers	MAL			
			horided	mil	
		required	Provided in DT cis	news MIL	
	Smoke Management System.				
	Basements	30 a/c per hour	fronted	MR	
	 Upper Floors 	12 a/c per hour	provided	MIL	
	Fire Extinguishers			- Iu	
	Total Numbers	A STATE OF THE STA	390	ma	
	Types		waterce from	MR	
	IS Marking	ISI Marked	yes	MR	
6.	First Aid Hose Reels				
	 Total numbers of each floor 		L 87 Acreta	l and	
	 Length of hose reel hose 	30 m	y-es	me	
	Nozzle diameter	5 mm	Yes	me	
7.	Automatic fire detection & alarming system.				
	Type of detectors	Required	Snike Meats	MIL	
	Location of Main Panel	GF	FBF Mar Ramp	MR	
	Location of Repeater Panel	D	Energy Contre	mR	
	Alternate source of power	D.G. Required	DadUPShow	me	
	Hooter's Location	Leguizedation	Everyfloor	MA	
3.	MOEFA	Legured	fronded	ma	
).	Public Address System.	Regulred	Providuel	ME	
10.	Automatic Sprinkler System.				
	Basement	Required	Provided	ml	
	Upper Floor	Required	horidal	ML	
	Sprinkler above false ceiling	Required	Provided	MA	
11.	Internal Hydrants	11			
	Size of riser/down-comer	150 mm	150 mm	ma	
	 Number of hydrants per floor 	reguin	101 (Total)		
	Hose Box	regum	32 Total	ml	
12.	Yard Hydrants.				
	Total Number of hydrants	Regum	13	ma	

13.	Pumping Arrangements					
	Ground Level					
	 Discharge of main pump 	2380 LPM	2280 LPM	mn		
	Head of Main pump	20 ml	Tomle	MK		
	Number of main pumps	Two	2 Provid			
	Jockey Pump out put	188LPM	18-8 CP10	ML		
	Jockey pump head	Jomhi	Jones	MK		
	Standby pump out put	2890 CPM	28501RM	Mil		
	Standby pump head	Zondi	Jomhi	MI		
	➤ Auto Starting/Manual stopping	July dent	Autoslail mount	ma		
	Pump House Access Terrace level	regum	Provided	MIL		
	Discharge of pump					
14.	Head of the pump	HK	1800m	MIL		
	> Power supply	MR	Domlin	MIL		
	1 - 1915-70-11 - 1	Regular	DG Resided	MIL		
	and a surring of pump	regum	y-es:	MIL		
14.	Underground tank capacity Out					
	➤ Draw-off connection	2 lock.	4.600024	MI		
	Fire service inlet	reguin	Privided	MR		
	Access to tank	Depun	Provide	mil		
	Charles Control and Control an	reguind	Brovid of	MI		
5.	Overhead Tank capacity	20,000	30,00014	MX		
	Exit Signage.	horided at	all floors.			
5.	Provision of Lifts.					
	Pressurization of Lift Shaft Pressurization of Lift Labby	Seguero	Provided	MR		
	Pressurization of Lift Lobby Communication In lift Car	u-	Provided	MK		
	Fireman's Grounding Switch	M.	Provided	MA		
		u-	fronded	MN		

1//10

	 Lift Signage 	Seguena	1 0 10 1	
17.	Standby power supply		horidad	mx
18.	Refuge Area. D.G. 100 Y. body from & d			\$
	➤ Total Area ➤ Location	reguin	1 Cae Squ fool	ML
19.	Fire Control Room	-11-	Front & Hub areq	MI
	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	Regular	Provided	0.4 0
		-14	Provided	MR
		-14	Provided	MA
	Sanding Floor Flans	-11	40	ML
20	Special Fire Protection Systems for	Lequireiglor	yes yes	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Signature of Inspecting Officer

Signature of Inspecting Office

Name D. P. Bhordway

Name

S. S. Kausluk

Designation Divisional Africe

Designation Asst Div Mich