

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE,  
NEW DELHI**

No: F6/DFS/MS/GH/2011/2991

Dated: 16/11/2011

**FIRE SAFETY CERTIFICATE**

Certified that the Euro International Guest House located at 904 - A, Gali Chandiwali, Main Bazar, Paharganj, New Delhi comprised of ground (01 guest rooms and reception), 1<sup>st</sup> floor (05 guest rooms), 2<sup>nd</sup> floor (05 guest rooms), 3<sup>rd</sup> floor (05 guest rooms), and 4<sup>th</sup> floor (04 guest rooms) was granted NOC by this department vide letter No. F6/DFS/MS/GH/2008/2509 dated 04-09-2008. The premises was re-inspected by the officer concerned of this department on 28-10-2011 in the presence of Sh. Ankit Mahajan and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 20 rooms with effect from .....16/11/2011 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire service subject to conditions printed overleaf.

Issued ...16/11/2011... at New Delhi by,

  
CHIEF FIRE OFFICER  
FOR DIRECTOR  
DELHI FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi - 110049
2. Shri Manish Kumar Chadha M/s Euro International Guest House located at 904 - A, Gali Chandiwali, Main Bazar, Paharganj, New Delhi
3. Commissioner, (MCD), Town Hall, Delhi-110006 (with the request to get the height of building verified and intimate to this department)

**Condition for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

**INSPECTION REPORT**

1. Name & address of the building : Euro International Guest House  
904-A, Gali Chandiwali, main Bazar  
Paharganj, New Delhi
2. Type of Occupancy : Residential (Guest house)
3. Type of Case : New Case/ Renewal ✓
4. Details of previous NOC : Letter No F6/DFS/M.S/GH/2009/2509 Dated: 04-09-2008
5. Fire Safety directives letter No : - N.A. -
6. Date of inspection : 28-10-2011
7. Name of the Inspecting Officers : D.S. Yadav
8. Name and designation of officers from the building side : Shri Ankit Mahajan
9. Year of Construction : 2000
10. Applicant's letter No. : Euro 11/12 dt 13-10-2011

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ISS/NEEA Requirement	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	• Road width	N.A.	N.A.	PSS Area.
	• Gate width	N.A.	N.A.	M.R
	• Width of internal road	N.A.	N.A.	M.R
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	one	one	M.R
	• Basements	N.A.	N.A.	M.R
	b. Width of staircases			
	• Upper Floors	100 CMS	100 CMS	M.R
	• Basements	N.A.	N.A.	—
	c. Protection of exits			
	• Fire check door	N.A.	N.A.	—
	• Pressurization	N.A.	N.A.	—
	e. No. of continuous staircases to terrace	one	one	M.R
	g. Width of Corridor	N.A.	N.A.	—
	h. Door Size	N.A.	N.A.	—

contd:-



Euro International Guest House  
 904A, Gali Chandiwali,  
 Main Bazar, Pahar Ganj, New Delhi.

3	<b>Compartmentation.</b>			
	• Fire check door	N.A	N.A	N.A
	• Sealing of electrical shafts	N.A	N.A	N.A
	• Fire Rating of shaft door	N.A	N.A	N.A
	• Water Curtain	N.A	N.A	N.A
	• Fire Dampers	N.A	N.A	N.A
4	<b>Smoke Management System.</b>			
	• Basements	30 a/c per hour	N.A	N.A
	• Upper floors	12 a/c per hour	yes (M.R) ✓	M.R
5	<b>Fire Extinguishers</b>			
	• Total numbers	10 Nos.	10 Nos ✓	M.R
	• Types		CO <sub>2</sub> & W.CO <sub>2</sub>	M.R
	• IS marking	ISI marked	Type ✓ yes ✓	M.R
6	<b>First-Aid Hose Reels.</b>			
	• Total numbers on each floor	one	one ✓	M.R
	• Length of hose reel hose	30 m	yes ✓	M.R
	• Nozzle diameter	5 mm	yes ✓	M.R
7	<b>Automatic fire detection and alarming system.</b>			
	• Type of detectors	N.A	N.A	N.A
	• Location of Main Panel	N.A	N.A	N.A
	• Location of Repeater Panel	N.A	N.A	N.A
	• Alternate source of power	N.A	N.A	N.A
	• Hooters' Location	N.A	N.A	N.A
8	<b>MOEFA</b>	N.A	N.A	N.A
9	<b>Public Address System.</b>	yes.	provided.	M.R
10	<b>Automatic Sprinkler System.</b>			
	• Basement	N.A	N.A	N.A

contd: ---

Euro International Guest House  
 904 A, Gali Chandivali main Bazar  
 - Palod Road, N. Delhi

	<ul style="list-style-type: none"> <li>• Upper Floor</li> <li>• Sprinkler above false ceiling</li> </ul>	N.A	N.A	N.A
		N.A	N.A	N.A
11	<b>Internal Hydrants</b>			
	<ul style="list-style-type: none"> <li>• Size of riser/down-comer</li> <li>• Number of hydrants per floor</li> <li>• Hose Box</li> </ul>	N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
12	<b>Yard Hydrants.</b>			
	<ul style="list-style-type: none"> <li>• Total number of hydrants</li> <li>• Hose Box</li> </ul>	N.A	N.A	N.A
		N.A	N.A	N.A
13	<b>Pumping Arrangements.</b>			
	<ul style="list-style-type: none"> <li>• Ground Level</li> <li>➤ Discharge of main Pump</li> <li>➤ Head of Main pump</li> <li>➤ Number of main pumps</li> <li>➤ Jockey Pump out put</li> <li>➤ Jockey pump head</li> <li>➤ Standby Pump out put</li> <li>➤ Standby Pump Head</li> <li>➤ Auto Starting/ Manual stopping</li> <li>➤ Pump House Access</li> <li>• Terrace level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the pump</li> <li>➤ Power Supply</li> <li>➤ Auto Starting of pump</li> </ul>	N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		N.A	N.A	N.A
		220 LPM	220 LPM.	M.R
		40 metres	40 metres	M.R
		yes.	yes.	M.R
		yes	yes	M.R
14	<b>Captive Water Storage for fire fighting.</b>			
	<ul style="list-style-type: none"> <li>• Underground tank capacity</li> <li>➤ Draw-off connection</li> </ul>	N.A	N.A	M.R
		N.A	N.A	M.R

contd.:-



Euro International Guest House

904 A, Gali Chandiwali

Main Bazar, Pahar Gazi, New Delhi

(4)

	<ul style="list-style-type: none"> <li>➤ Fire service inlet</li> <li>➤ Access to tank</li> <li>• Overhead Tank capacity</li> </ul>	N.A	N.A	N.A
		yes	yes	M.R
		2500 litres	2500 litres	M.R
15	Exit Signage.	yes	yes	M.R
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N.A	N.A	N.A
	• Pressurization of Lift lobby	N.A	N.A	N.A
	• Communication In lift Car	N.A	N.A	N.A
	• Fireman's Grounding Switch	N.A	N.A	N.A
	• Lift Signage	N.A	N.A	N.A
17	Standby power supply	yes	yes	M.R
18	Refuge Area.			
	➤ Total Area	N.A	N.A	N.A
	➤ Location	N.A	N.A	N.A
19	Fire Control Room			
	• Detector System Panel	N.A	N.A	N.A
	• Flow Switch Panel	N.A	N.A	N.A
	• PA System Panel	N.A	N.A	N.A
	• Batter backup	N.A	N.A	N.A
	• Building Floor Plans	N.A	N.A	N.A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N.A	N.A	N.A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

contd:--

Euro International Guest House

(5)

904 A Gali chandi wali, main Bazar  
Pahar Ganj, New Delhi

Signature of the Inspecting Officer

  
Signature of the Inspecting Officer

Name

Name D.S. Yadav.

Designation

Designation Assistant Divisional  
officer.