# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE,

No: GGOGS/MS/GH/2011/2929

Dated: 68/11/11

#### FIRE SAFETY CERTIFICATE

Certified that the guest house building in the name and style of M/s. New Amantran Guest House, located at 5129/X, Main Bazar, Pahar Ganj, New Delhi comprised of ground, first, second and third floor was granted NOC by this department vide letter No. F6/DFS/MS/EH/2008/683 dated 07-03-2008. The premises was re-inspected by the officer concerned of this department on 05-10-2011 in the presence of Mr. Gorav and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy with effect from .o. 2011 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire service subject to conditions printed overleaf.

Issued .08/.11../11. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi - 110049
- M/s. New Amantran Guest House, located at 5119, Main Bazar, Pahar Ganj, New Delhi

#### Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

## INSPECTION REPORT

1. Name & address	of the building NE	W AMANTA	DAN GUEST	Walla E
A P a d G G G G Pal	ncy Re	sidencial	(Gruest House	11.1.
<ol> <li>Type of Case</li> </ol>		Case/ Renewal	Chasonouse	Loaging h
4 Details of previo	us NOC Letter	No Ec/mela	alcula ala	
<ol> <li>Fire Safety direct</li> </ol>	tives letter No - N	CA -	5/GH/2008/ Dat	ed: 22-09-2
<ol> <li>Date of inspection</li> </ol>	n o	5-10-2011		
<ol><li>Name of the Insp</li></ol>	pecting Officers:	HARAM WO	2 2 1 1 1 1 1	
8 Name and design	nation of officers	ern.	SINGH YAD,	40.
from the building		Qu' GOSAV	(manages)	
<ol><li>Year of Construct</li></ol>	The state of the s	Eios to 19	on anager	
10. Applicant's letter	No. 37	SEE / ANIA	0011	4,
Minimum S	tandards on fire	Guest Hous	Provided at site	d New Doche
	fire safety U/R 33	Requirement	Provided at site	
Access to building		assigni cincin		MR/NMR
Road width				
III FOR EXAMPLE & COURT	I.	N. A	N. A	M-R
Gate width		N.A	N.A	M.R
• Width of in		N. A	N.A.	N.A
Number, Width,	Type & Arrangement	of Exits		<u> </u>
a Number of stairc	ases			
<ul> <li>Upper Floo</li> </ul>	rs	one	8ne	M. R
<ul> <li>Basements</li> </ul>		Nº A	N. A	-N.A -
b. Width of staircas	ses	N. A	NA.	W.A.
Upper Floor	rs	N. A		1
• Basements		N. A	101 cms 6, to fiss. 86 cms F to tessas	7.
c. Protection of exit	ts	1 6	N. A.	N.A
• Fire check of	loor	11		
Pressurization		MA	N.A	NA
	s staircases to terrace	N.A	N.A	N.A.
THE REPORT OF THE PARTY OF THE				
g Width of Corrido	or i	N. A	N. A	N-A
h. Door Size		N.A	N.A	N-A

contd:

## NEW ANANTRAN GUEST MOUSE, 5129, main Bagal, Pahas Gand, NEW Delki

	s of green	N. A	NA	N.A	
(	Compartmentation.	N.A	N.A	N.A	
	Fire check door		N.A	N-A	
	Sealing of electrical shafts  Fire Pating of shaft door.	N. A	N.A	N.A	
	<ul> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> </ul>	N.A	N.A	NA	
	Fire Dampers	N-A	N.A	NA.	
5	Smoke Management System.				
	Basements	30 a/c per hour	N. A	N.A	
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	yes	M.R	
	Fire Extinguishers	17.	- 14		
	<ul> <li>Total numbers</li> </ul>	Eight	Eight !	m.R	
	<ul><li>Types</li><li>IS marking</li></ul>	Tupe ISI marked	Eight Con Con Type Marked	M.R.	
1	First-Aid Hose Reels.				
	Total numbers on each floor	N-A	N-A	N.A	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	N. A	N-A	
	Nozzle diameter	5 mm	N. A.	N.A	
7	Automatic fire detection and alarmin	ng system.			
	Type of detectors	N.A	N. A	N.A	
	Location of Main Panel	N. A	N.A	N.A	
	Location of Repeater Panel	N.A	N. A	N.A	
	Alternate source of power	N-A	N.A	N. A	
1	Hooters' Location	N. A	N.A	N. A	
8	MOEFA	N.A.	N.A	N.A	
9	Public Address System.	N. A	N. A	NA	
10	Automatic Sprinkler System				
1.0	Basement	N. A	N. A	N.A.	

### NEW AMANTARAN GIVEST HOUSE 5129, main Bagas Pakas Gang New Delli

	Upper Floor	N.A	nt A	10.4		
	Sprinkler above false ceiling	land that	N.A	NA		
		N.A	N.A.	N.A.		
11	Internal Hydrants					
	<ul> <li>Size of riser/down-comer</li> </ul>	N.A	N. A	N. A		
	Number of hydrants per floor     Hose Box	N.A	N.A	N. A		
	- Hose Box	M. A	N.A.	N.A		
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	N. A	N.A	N.A		
	Hose Box	N-A	N.A	N. A		
13	Pumping Arrangements.					
	<ul> <li>Ground Level</li> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> </ul>	N. A	N.A.	NA		
		N.A.	N.A	NA		
		N.A	N.A	N.A		
		N. A	N.A	N.A		
	Jockey Pump out put	N.A	N-A	N.A		
	Jockey pump head	N.A	N.A	NA		
	<ul> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> <li>Terrace level</li> </ul>	N.A	MA	N.A		
		N.A	NA	MA		
72 to		N.A	N.A	NA-		
		N. A	N.A	NA		
		N. A	N.A	N.A		
	<ul> <li>Discharge of pump</li> <li>Head of the pump</li> </ul>	N.A	N.A	N.A		
	> Power Supply	N. A	NA	N.A		
	➤ Auto Starting of pump	N.A	NA	N.A.		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	N.A	N.A	N.A		
	> Draw-off connection	N.A	N.A	N.A.		

contd:-

NEW AMANTARAN GUEST HOUSE 5129 Nain Bagal Pakal GAND, N. Delle

	<ul> <li>Fire service inlet</li> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>	N. A N. A	N.A N.A	M. A	
15		N. A	N.A	N.A N.A	
16	Exit Signage. Provision of Lifts.	_	yes	M.R	
			V		
	Shaft	NA	N. A	N.A	
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> </ul>	N-A	N.A	N.A	
	Fireman's Grounding Switch	N. A	N.A	N.A	
	Lift Signage	N.A	N.A	N.A	
7		N.A	N.A	N.A.	
8	Standby power supply				
0	Refuge Area.				
	Total Area	N.A	N. A	N. A	
9	> Location Fire Control Room	N.A	N. A	N.A	
	Detector System Panel	N.A	N-A	N.A	
	Flow Switch Panel     PA System Page	MA	N.A	N.A	
d	A System Panel	NA	N.A	N.A	
	Datter backup	N.A	N-A	N.A	
S	Bulluling Floor Plans	N.A	N.A	N.A.	
100	pecial Fire Protection Systems for rotection of special Risks, if any:	N.A	N. A	N.A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

NEW AMAMTARAN GUEST MOUSE

Siza main Bagol, Parascand New Balling

Signature of the Inspecting Officer

Designation

Name

Signature of the Inspecting Officer

Name DEARAM VIR SINGH YEDAV.

Designation Agistant Divisional