May kindly see the letter No. RJS/87/2011 dated 06-06-11, received from the Principal, Ramjas School (Primary Section), located at Anand Parbat, New Delhi -110005, regarding issue of NOC from fire safety and means of escape in respect of above school.

In this connection it is stated that the school building in question was inspected by undersigned on 22.06.2011 with a view to ensure the compliance of the Fire Safety guidelines on accordance with the Delhi Fire Service Act 2007 and Rules 2010, provisions contained in NBC of India (Part-IV). Mrs. Rajni Arora was also present.

During the course of inspection it was observed that the school building (Primary Section) is comprised of ground floor only. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The building is properly ventilated. The room's allocation in the school is as under-

Ground floor - Admin block, Computer lab, Examination room, General science labs, Audio visual room, Gyam hall, Store and class rooms etc. (total 30 rooms).

The school building is protected by the following fire safety arrangements as under:-

1.	Access to building	: Available.
2.	Number, Width, Type and Arrangements of exits:	Ground Floor only
3.	Protection of Exits by means of fire check door(s) and or pressurization.	: Not required.
4.	Compartmentation	: Not required
5.	Smoke Management System	: Not required
6.	Fire Extinguishers	: ABC type cap. 5 kg & WCO ₂ type cap. 9 ltrs each.
7.	First Aid Hose Reels	: Not required.
8.	Automatic fire detection and alarming system	: Not required.
9.	MOEFA	: Not required.
10.	Public Address system	: Not required.
11.	Automatic Sprinkler System	: Not required.
12.	Internal hydrants and yard hydrants	: Not required.
13.	Pumping Arrangements	: Not required.
14.	Captive Water storage for fire fighting	: Not required.
15.	Exit Signage	: Provided.
16.	Provision of lifts	: Not required.
17.	Standby power supply	: Provided.
18.	Refuge Area	: Not required.
19.	Fire Control Room	: Not required.
20.	Special Fire Protection Systems for protection of special risks	: Not required.

The system was checked / operated and the performance found satisfactory at the time of inspection. In view of above satisfactory fire safety and means of escape arrangements provided in the school premises NOC may be considered from fire safety point of view in above said building.

DFA is put up for approval and signature please.

n. och

Maly 9 28/6/10.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI THEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No 66/065/005/2011/1563

Dated 13/07/11

FIRE SAFETY CERTIFICATE

Certified that the building of Ramjas School (Primary Section), Anand Parbat, New Delhi 110 005 comprised of Ground floor only and having total 30 rooms (Admin, Block, Computer Lab, Examination room, General Science Labs, Audio Visual room, Gym hall, Store and Class rooms etc.) owned/occupied by management of Ramjas School (Primary Section), Anand Parbat, New Delhi -110 005 have complied with the fire prevent on and fire affects requirements in accordance with the circular issued by the Director of Education, Govt, of NCT of Delhi, dated 01.3.2011 and verified by the officers concerned of Delhi Fire Service on 22.6.201 in the presence of Mrs. Rajni Arora (Principal, Ramjas School, Primary Section), and that the building is fit for occupancy class "educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on ... 13 / 0.7 / 11 at New Delhi.

Chief Fire Officer
For Director
Delhi Lire Service

Copy to:

- Principal Ramjas School (Primary Section) Anand Parbat, New Delhi – 110 005.
- Director of Education Govt of NCT of Delhi, Old Secretariat, Delhi - 110/054.

Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained staff should be available round the clock.
- Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for regularization of unauthorized construction, if any.