GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO. [F6] DF3 MS 2011 EH 3059 DATED: 18/11/2011

FIRE SAFETY CERTIFICATE

Certified that the M/s PVR Directors Cut Restaurant building at Ambience Mall, Vasant Kunj, New Delhi- is running at the 3rd floor, comprised of three tier basement, ground plus three upper floors was granted NOC by this department vide letter no. F6/MS/DFS/2008/3282 Dated 28.11.2008 for mall. The premises re-inspected by the officers concerned of Fire Service on 01.11.2011 in the presence of Mr. Manish Parashar (RGM-Projects), of the restaurant and that the building is fit for occupancy class D "Restaurant Building" in the mall at 3rd floor with effect from..... 18 1/2017 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rule, 2010, as mentioned below.

Issued on 18/11/2-1) at New Delhi by

Chief Fire Officer
For Director
Delhi Fire Service

Copy To:-

 The DHO(South Zone), Office of Deputy Health Officer, M.C.D. Health Department South Zone, Green Park, New Delhi.

 The Manager PV3 Directors Cut Restaurant at 3rd Floor, Ambience Mall, Vasant Kunj, New Delhi-

Conditions for the validity of fire safety certificate

- All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye laws.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in

1		ISPECTION REPOR		1. 7. 1.
1	Name & address of the building	M/s PVR Resturant Ltd at 3rd Floor Ambience Mall, Vasant Kun New Delhi		
2	Type of Occupancy	Mercantile *F*		
3	Type of case	New for Resturant		
4	Details of previous NOC	F6/MS/DFS/2008/3282 Dated 28.11.2008		
5	Fire safety directives letter No	F6/MS/DFS/BP/2004/30		
6	Date of inspection		O Dates 20:12:2004	
9	Date of Hispertion	01.11.2011 Dv. CFO Santok Singh, I	D.O. (South) D.P. Bhardwa	i ADO/BCE
7	Name of the inspecting Officers	S.S.Kaushik		5
8	Name and designation of officers	Mr.Mainesh Parasjar (Ri Narian (Mall Fire Officer	GM-Projects PVR Rest.). ()	& Mr. Ram
	from the building side			
9	Year of construction	2008		
-	2 24 242 = 31	DHO/HD/SZ/2011/D-826	n4 n7 2011	
10 . NO.	Applicant's letter No. Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR / NMR
1	Access to building 1) Road width		Teversor and the	1000
	2) Gate width	18 mtrs	Provided	MR
	3) Width of internal road	5mtrs	Provided	MB
0		6 mt/s	Provided	MR
2	Number, width Type & arrangement of a	The same of the sa		
	a. Number of staircases	29 Nos.		190 MI
	1. Upper floors	Required	14 Nos Provided by Mall	
	basements Width of staircase	Required	29 Nos.Provided by Mall	MR
	Upper floors		Personal deposit and the Anna	
	2 basements	1.5 mtrs	Provided by Mall	MR
	c. Protection of exits	1,23108	Provided by Mail	MR
	1. Fire check door	Required	Provided	MB
	2. Pressurgation	Required	Provided by Mall	MB -
	d. No. of continuous staircase to terrace		12 Nos. Stairs Provided	MR
	e. Width of corridor	4 mirs	Provided by Mall	MR
	f. Door size	1.5 mtrs (2 No. Exit)	Provided for Restaurant	MR
3	Compartmentation.	The state of the s	T TO TO SO TO THOUSANDIN	5411.5
	1. Fire check door	Required	Provided	MR
	2. Sealing of electrical shafts	Required	Provided by Mall	MR
	3. Fire Rating of shaft door	Required	Provided by Mall	MR
	4. water curtain	Required	Provided by Mall	MB
	5. Fire dampers	Required	Provided by Mall	MB
4	Smoke Management system.			
	basement	30 a/c per hour 12 a/c per hour	Mechanical Ventilation Provided by Mall	MR
	upper floors		Mechanical Ventilation Provided by Mall	MR
5	Fire Extinguishers		The state of the s	elicitis ()
	total numbers		12 Nos	MR
	Types		ABC, Cd2.	MR
	ISI marking	ISI	Yes	MR
6	First-Ald Hose Reels.		4 = = = = = = = = = = = = = = = = = = =	
	total numbers on each floor	20 Nos	Provided by Mail	MR
	Length of Hose real hose	30 m	Provided by Mail	MR
	Nozzle Diameter	5 mm	Provided by Mail	MB

7	Automatic fire detection and alarmin	- 1 3 1 1 - 2 0 - 1 1	Provided (Smoke & hea	at) MR
	Type of detectors	Required Not Required	Provided by Mail	MR
	location of Main Panel	Not Required	Provided by Mall	MR
	location of Repeater panel	Required	Battary Backup	MR
	Alternate source of power	Staircase	Provided by Mall	MB.
	hooter's location	Not Required	Provided by Mall	MR
8	MOEFA	Required Required	Provided by Mair	MR
9	Public Address System.	Hedrined	T-toyland	IVII L
0	Automatic Sprinkler System.	Required	Provided by Mall	MR
	basement		Provided by Mall	MB
	upper floors	Required	Provided by Mall	MR
	sprinkler above false celling	Required	I roylood by Water	Parit C
11	Internal Hydrants	Not Required	Provided by Mall	MB
	Size of riser/down-corner	Not Required	Provided by Mall	MR
	Number of Hydrants per floor			MR
1550	hose Box	Not Required	Provided by Mall	DVIPE
12	Yard Hydrants.	Not Demoleral	Provided by Mall	MB
	total number of hydrants	Not Required	Provided by Mall	MR
1000	hose box	Not Required	Introvided by (via))	100.7
13	Pumping arrangements			
	1. Ground level	2280 LPM	Provided by Mall	MR.
	a. Discharge of main Pump	70 Mtr	Provided by Mall	MR
	b. Head of main pump		- 1 10 t 10 t 20 t 10 t 10 t 10 t 10 t 10	MR
	c.Number of main pumps	Two	Provided by Mall	MR
	d jockey pump out put	180 LPM	Provided by Mall	MB
	e.jockey pump head	70 Mtr	Provided by Mall	
	f. Standby Pump output	2280 LPM	Provided by Mall	MR
	g Stanby Pump head	70 Mtr	Provided by Mall	
	h.Auto Starting/Manual stopping	Required	Provided (Both)	MR
	pump house access	Required	Provided by Mail	Tivin
	2.Terrace level	ONW LIDAY	Provided by Mall	MB
	a. Discharge of pump	900 LPM		MB
	b. head of the pump	40 mtr	Provided by Mall	MR
	c. Power supply	Required	Provided by Mall	MR
	d. Auto starting of pump.	Reguired	Provided by Mall	Tiviry
14	Captive water storage for fire fight	ling		
	Underground tank capacity	5,00,000 Ltrs	Provided by Mail	MR
	a. Draw-off connection	Not Required	Provided by Mall	MR
	b. fire service inlet	Not Required	Provided by Mall	MB
	c.Access to tank	Not Required	Provided by Mail	MR
	Over head tank Capacity	30,000 ltr	Provided by Mall	MR
15	Exit Signage.	Required	Provided	MB
16	Provision of lifts.			
	a. Pressurization of lift shaft	Required	Provided by Mall	MR
	b. pressurization of lift lobby	Required	Provided by Mall	MR
	c communication in lift car	Required	Provided by Mall	MR
	d. Fireman's grounding switch	Required	Provided by Mall	MR
	e. Lift signage	Required	Provided by Mall	MR
17	Standby power supply	Required	Provided by Mall & F	Resta MR
18	Refuge Area.	Not Required		
10	total area			
	location			

19	Fire control room			
b. Flow switc c. PA system d. Batter bac	a, detector system Panel	Not Required	Provided by Mall	MR
	b. Flow switch Panel	Not Required	Provided by Mall	MR
	c. PA system Panel	Not Required	Provided by Mall	MR
	d. Batter backup	Required	Provided by Mall	MR
	e. Building floor plans	Not Required	Not Required	MB
20	Special Fire Protection systems for protection of special risks, if any:			

The fire protection systems provided in the building were checked and found functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule. The grant of Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/ May be reccomeded for the said resturant subject to conditions give in the letter

Accordingly DFA is put up for your approval and signature please.

Signature of the inspecting officer

Name

D. P. Bhardwaj

Designation : Divisional Officer (South)

Signature of the Inspecting Officer

Name

S.S. Kaushik

Designation

ADO (BCP)