GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/0F5/ms/2011/3036

Dated : | 7 | 11 | 11

FIRE SAFETY CERTIFICATE

Certified that the guest house in the name & style M/S S.K.Eastend Party Hall, Star City Mall, Mayur Vihar-1, Delhi-91 at ground floor floor of Star City Mall, owned/occupied by M/s S.K.Eastend Party Hall have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 22.09.11& 24.10.11 in the presence of Sh. Inder Sharma (GM)of the banquet /party halland that the building is fit for occupancy Group –D (Assembly building) with effect from 1.2.1.1. for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Chief Fire Officer Delhi Fire Service

See Land

To.

Dy.Health Officer
M.C.D,Shahdara
South Zone,Delhi.

:-in reference DHO/SHAH./SOUTH/2011/1035 dated 10.09.11

Copy to:-

M/S S.K.Eastend Party Hall, Star City Mall, Mayur Vihar-1, Delhi-91

CONDITIONS

- All the means of escape shall be kept free of all type of obstruction all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- Basement Shall be used as per B.B.L.
- 6. This NOC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

M/Gc/ved Pol

INSPECTION REPORT

1. Name & address of the building :S.K.Eastend Party Hall, Star City Mall, Mayur Vihar-1, Delhi-91.

: Assembly(Banquet hall at grade level)

3. Type of Case

: New Case for Banquet hall

4. Details of Previous NOC

F.6/DFS/MS/2007/1287 dated 08.05.2007(For main building)

Fire Safety directives No

: F6/DFS/MS/2011/2167 Dated 06.09.11

6. Date of Inspection

: 22.09.11

7. Name of the Inspecting Officer: DO Virendra Singh

8. Name of the designation of Officer

From the building side

: Sh.Inder Sharma(GM)

9. Year of Construction

: 2006

10.Applicant's letter No.

: DHO/SHAH./SOUTH/2011/1035 dated 10.09.11

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	NBC	Provided at Sit	e Remarks MR/NMI	
1	Access to building	Requirement			
	 Road width Gate width 	6 Mtrs	6 Mtrs. —	MR -	
	 Width of internal road 		6 Mtrs	MR	
2	Number, Width, Type and Arrangement			*********	
	Upper Floor Basement B. Width of Staircases Upper Floor Basement C. Protection of exits Fire check door Pressurization e. No. of continuous staircases to terroor	Required	Provided	MR	
	g. Width of Corridor h. Door Size	2.0 Mtrs	2.0 Mtrs	MR	
	Compartmentation.	2.0 Mtr.	2.0 Mtr.	MR	
	 Fire check door 	Required Provided			
	 Sealing of electrical shafts 	Required Required	Provided /	MR	
	 Fire rating of shaft door 	2 hrs.	Sealed /	MR	
	Water curtain	Not Required	2 hrs.	MR	
	 Fire Dampers 	Required		****	
5	moke Management System.	required	Provided	MR	
- 11	 Basement 	30n/e was t			
	Upper floor	30a/c per hour	provided /	MR	
F	ire Extinguisher	12 a/c per hour	do	MR	
	Total numberstypes	6 no. ABC & Co2	6 No. /	MR	
	IS marking	ISI marked	ABC & Co2	MR	
Fi	rst-aid-Hose Reels.	ioi marked	ISI marked	MR	

	 Total numbers of ground floor 	1 no.	Provideed	MR ~		
	 Length of hose reel hose Nozzle diameter 	30 m	Provided	MR c		
	L SO MATERIALITATION THE	20 m	Provided	MR -		
		5 mm	Provided	MR _		
7	Automatic fire detection and alarming system.					
	 Type of detectors Location of main panel Location of repeater panel Alternate source of power 	Heat & smoke	Provided	MR -		
		1 st basement	Provided	MR		
		Security Room	Provided	MR		
		Battery & DG Set	Provided	MR		
	Hooters's location	Staircase	Provided	MR		
8	MOEFA	Required	Provided	MR -		
9	Public address System.	Required	provided	MR -		
10	Automatic Sprinkler System.	Required	Provided	MR		
	basement	Required	Provided in entre basement	MR		
	upper floor	Required	Provided	MR		
	 sprinkler above false ceiling 	Required	Provided	MR		
11	Internal Hydrants		1,1,4,10,4,4,4	1/5462(52)		
	size of riser/down-comer	150 mm	150 mm	MR _		
	Number of hydrants per floor	one	one	MR		
	Hose Box	one	one	MR		
12	Yard Hydrants.	6107				
	Total number of hydrants	опе	one	MR		
	Hose Box	one	one	MR		
13	Pumping Arrangements.			17.00		
	Ground Level	2850 LPM	2850 LPM	MR		
	 Discharge of main Pump 	2850 LPM	Provided	MR		
	 Head of Main Pump 	70 Mtrs.	80 mtrs	MR		
	 Number of main pumps 	Two	2 No.	MR		
	Jockey pump out put	one 180 LPM	One 180 LPM	MR		
	➢ Jockey pump head	70 Mtrs.	80 mtrs.	MR		
	 Standby pump out put 	2850 LPM	2850 LPM	MR		
	Standby pump Head	70Mtrs	80 Mtrs.	MR		
	Auto Starting / Manual stopping	Auto	Provided	MR		
	Pump House Access	Required	Provided	MR		
	Terrace Level					
	➤ Discharge of pump	Required	Provided	MR		
	Head of the Pump	do	39 Mtrs.	MR		
	Power supply	do	Provided	MR		
	Auto Starting of pump	Required	Manual	MR		
14	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	2,00,000 Ltrs.	2,00,000 Ltrs.	MR		

	> Draw-off connection	Required	Provided	MR
- 272	> Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	 Overhead Tank capacity 	250,000 Ltrs.	250,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			19115
	 Pressurization of Lift Shaft 	Required	provided	MR
	 Pressurization of Lift lobby 	Required	Provided	MR
	 Communication in lift car 	Required	Provided	MR
	 Firemen's grounding switch 	Required	Provided	MR
	 Lift Signage 	Required	Provided	MR
17	Standby power supply	Required	1000 KVA	MR
18	Refuge Area.	************		Terrore
	 Total area 	********	/44	
	 Location 		******************	
19	Fire Control Room			
	 Detector system panel 	Required	Provided	MR
	 Flow switch panel 	Required	do	MR
	PA system panel	Required	do	MR
	Batter backup	Required	do	III Willer
	 Building Floor Plans 	Required	do	MR
20	Special Fire Protection systems for	Required for	The state of the s	NMR
	protection of special Risks, if any:	HTLT panels	Provided	MR

The fire protection systems provided in the building were tested checked and found functional at the of inspection.

Keping in view the non compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010/

Signature of the inspecting Officer

Name

Designation

Name VIRENDAA SINGH

Designation DO