

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

No. F6/DFS/MS/EH/2011/2862

Dated: 03/11/11

FIRE SAFETY CERTIFICATE

Certified that the **Sampoorna Restaurant** (a unit of Panchshila Rendezvous/Super Engineering Works.) located at F-20, UGF, Janak Palace, Janak Puri, New Delhi-110058. The restaurant is running at Upper ground floor only. Above restaurant was issued NOC vide this office letter No.F.6/DFS/MS/EH/2008/2464 dated 29.08.2008 owned/ occupied by Sh. Arvind Ghei have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of fire service on 22.10.2011 in the presence of Sh Virender Singh Nagi. There is no additional construction and that the building/ premises is fit for occupancy class Group D Assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....03/11/11..... at New Delhi



Chief Fire Officer
Delhi Fire Service



Copy to: -

1. The Deputy Health Officer
Municipal Corporation of Delhi
West Zone Rajouri Garden, N.D
(Ref. No-D-899/HD/WZ, dated 10.08.11)
2. Mr. Arvind Ghei (Owner)
Sampoorna Restaurant,
F-20, UGF, Janak Palace,
Janak Puri, New Delhi - 110058.

Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : Sambharna Restaurant, F-20, UGF, Jomat Pakar, J.P. Park, No. D-58
2. Type of Occupancy : Restaurant
3. Type of Case : New Case/Renewal
4. Details of Previous NOC : Letter No. F-6/DFS/MS/EH/08/2464 Date 29.08.08
5. Fire Safety directives letter No : N/A
6. Date of inspection : 22.10.2011
7. Name of Inspecting Officer : D.O H.L. Aneja & A.O P.S. Ashiya
8. Name and designation of officers
From the building side : Sh. Virender Singh Nagi
9. Year of Construction : Before 2007
10. Applicant's letter No. : Nil dated 29.08.2011

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	• Road width	Accessible	09 mtr	MR
	• Gate width	-	145cm	MR Being old Cape!
	• Width of internal road	-	06 mtr	- do -
2.	Number, Width, Type & Arrangement of Exits			
a.	Number of staircases	Two	Two	MR
	• Upper Floors	Two	Two	MR
	• Basements	Two	Two	MR
b.	Width of staircases			
	• Upper Floor	125cm	120cm, 135cm	MR Being old Cape
	• Basements	-	150cm	- do -
c.	Protection of exits			
	• Fire check door	N/A	-	-
	• pressurization	N/A	-	-
d.	No. of continuous staircases to terrace	-	One	-
e.	Width of Corridor	-	245cm	MR
f.	Door Size	-	92cm x 195cm	MR
3.	Compartmentation			
	• Fire check door	N/A	-	-
	• Sealing of electrical shafts	-	Sealed	-
	• Fire Rating of shaft door	N/A	-	-
	• Water Curtain	N/A	-	-
	• Fire Dampers	N/A	-	-
4.	Smoke Management System			
	• Basements	30 a/c per hour	Exhaust Fans are provided	MR
	• Upper floors		Natural Ventilation	MR

		12 a/c per hour	—	—
5.	Fire Extinguishers			
	• Total numbers	06 Nos	Provided	MR
	• Types	CO ₂ , WCO ₂ , A-B-C	- do -	MR
	• IS marking	ISI marked	Yes	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose reel hose	30 m	- do -	MR
	• Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming system			
	• Type of detectors	—	Smoke detector's provided	MR
	• Location of Main Panel	N/A	—	—
	• Location of Repeater Panel	—	—	—
	• Alternate source of power	—	D.G Set of 75 KVA	MR
	• Hooters' Location	Required	Provided at different location.	MR
8.	MOEFA			
		Required	Provided	MR
9.	Public Address System			
		Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Upper Floor	—	Provided	MR
	• Sprinkler above false ceiling	—	—	—
11.	Internal Hydrants			
	• Size of riser/down-comer	Required	100mm	MR
	• Number of hydrants per floor	Required	Provided	MR
	• Hose Box	- do -	- do -	MR
12.	Yard Hydrants			
	• Total number of hydrants	Required	Provided	MR
	• Hose Box	- do -	- do -	MR
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	—	2400 LPM	MR
	➤ Head of Main pump	—	88 m	MR
	➤ Number of main pumps	—	Two	MR
	➤ Jockey Pump out put	—	240 LPM	MR
	➤ Jockey pump head	—	88 m	MR
	➤ Standby Pump out put	—	2400 LPM	MR
	➤ Standby Pump Head	—	88 m	MR
	➤ Auto Starting/Manual stopping	—	Both	MR

	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	-	Approachable	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	Approx. 2,00,000 Ltr	200000 Ltr	MR
		-	-	-
		-	Provided	MR
		-	-	-
		-	-	-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	-	-	-
		-	-	-
		-	Provided	MR
		Required	Provided	MR
		- do -	- do -	MR
17.	Standby power supply	Required	Dist. Set Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	-	-	-
		-	-	-
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	-	Provided	MR
		-	-	-
		-	Provided	MR
		-	Provided	MR
		-	-	-
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	-	-

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to ^{Renewal} grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ ~~issue shortcomings as noted at serial numbers.....~~

Note:- The Restaurant having two exits.


Signature of Inspecting Officer
Name H. I. Aneja
Designation Divisional Officer



Signature of Inspecting Officer
Name P. S. Dahiya
Designation Asstt. Divisional Officer.

~~Dy C/O~~

3/12



1/11


FT
M. S. K.

1/11

M. S. K.

~~CFD~~
MS

FT

1/11

ft

1/11

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to ^{Renewal} grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ ~~issue shortcomings as noted at serial numbers.....~~

Note:- The Restaurant having two exits.



Signature of Inspecting Officer

Name H. I. Aneja

Designation Divisional Officer



Signature of Inspecting Officer

Name P. S. Dahiya

Designation Asstt. Divisional Officer.