

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI -110001**

No F6/DFS/MS/GH/2011/1948

Dated 12/08/11

**FIRE SAFETY CERTIFICATE**

Certified that the Guest House Beyond Inn at A – 91, Malviya Nagar, New Delhi is being run at first to third floor with 11 Guest Rooms of the bldg. which comprise of basement, ground & three upper floors, basement & ground floor are others property, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 1-7-2011 in the presence of Mr. Nitin Verma. and that the premises is fit for occupancy of Guest House at 1<sup>st</sup> to IIIrd floor with effect from 12-8-2011 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed overleaf.

Issued on 12/08/11

at New Delhi.



Chief Fire Officer  
Delhi Fire Service



Copy to :-

1. Mr. Nitin Verma  
Beyond Inn at A – 91,  
Malviya Nagar, New Delhi.
2. The Additional Comm. of Police (Lic.)  
First Floor, Police Station,  
Defence Colony, New Delhi.

- Ref:- 1 Letter No. -NIL dated 15/6/11 (Dy 6325)  
 2 Letter No 25226-31/Addl.CP/Kic.(H) dt. 9/6/11

With ref. above quoted letters, premises been inspected by ADO (NP) on 1.7.11 in the presence Mr. Nitin Verma.

During inspection, it was observed that Prop. intends to run Guest House at first to third fl. with 11 rooms. The bldg. comprises basement, ground three upper floors. The bldg. abuts on 80' wide road & bldg. is accessible to fire engines. The bldg. is provided one staircase of 1.25 mtr. width. The Prop. have given the photocopies of bldg. Plans (sanctioned) placed in which reveals that bldg. was regularised in March. Occupancy floorwise was seen during inspection under.

Basement	- Lying vacant	} (132.23m <sup>2</sup> )
Ground	- Lying vacant	
First floor	- 04 G) Rooms, Rec.	} Others Propert
Second fl.	- 04 G) Rooms Office.	
Third fl.	- 03 G) Rooms Laundry, Toilet	
Total - 11 G) Rooms.		

Detail of fire protection measures as per 20 po  
 has been seen under.

- |     |                                  |   |                            |
|-----|----------------------------------|---|----------------------------|
| 9.  | M.O.E.F.A                        | — | Not required.              |
| 10. | P.A. System                      | — | Not required.              |
| 11. | Automatic Sprinkler System       | — | Not required.              |
| 12. | Internal Hydrant & Yard hydr.    | — | Not required.              |
| 13. | Pumping Arrangements             | — | Not required.              |
| 14. | Captive water storage            | — | Not required.              |
| 15. | Exit Signs                       | — | Provided.                  |
| 16. | Provision of lift                | — | Not required               |
| 17. | Stand by power supply            | — | Not required but provided. |
| 18. | Refuge Area                      | — | Not required.              |
| 19. | Fire Control Room                | — | Not required.              |
| 20. | Sp. fire protection for Sp. risk | — | Not required.              |

The above stated fire protection arrangements were checked and found functional at the time of inspection.

In view of the above, issuance of fire Safety Certificate is recommended and accordingly draft fire safety certificate is put up for approval. Submitted please.

Asishanda  
21/8/11

DO (BCP) [Signature]  
3/8/11