## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2011 / 1910

Dated 09/08/11

## FIRE SAFETY CERTIFICATE

Certified that the IGI Airport Metro Express Line Station at IGI Airport near T-03 comprised of undercroft, platform, concourse, mezzanine, ground floor, owned / occupied by Delhi Airport Metro Express Pvt Ltd. was issued Fire Safety Certificate vide this office letter No. F6/DFS/MS/2010/3200 Dated 18.11.2010 have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 for the remaining two side platforms and verified by the officers concerned of Fire Service on 30.07.2011 in the presence of official of Metro Airport Line and that the two side platforms are fit for occupancy class Metro Station with effect from -D9/D9/H----- for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on - 59 / 58 / 1./ at New Delhi by

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Mens

## Copy to: -

- The Director (DAMPEL), Sector-21 Dwarka, Near Sector – 08 Metro Station, New Delhi.
- Director (Works), DMRC Ltd., Metro Bhawan, Connaught Place, New Delhi.

Note\*:- For general fire safety directives please see overleaf.

## Ref:- Letter No.DAME/AMEL/-P1/DFS/GEN/2011/3714 dated 08.07.2011

Sub: Inspection report from fire safety point of view in respect of balance areas of IGI underground metro station of airport metro express line at IGI Airport near 1-3 building-two side platform.

With reference to above quoted letter, premises have been inspected by DCFO & ADO (SJ) in the presence of Sh. Rajiv Jain and Mr. Bhandari on 16.07.2011. During the inspection, the shortcomings communicated by this department vide letter no. 16/DFS/MS/2011/1495 dated 07.07.2011 were checked and it was observed that the all the shortcomings have been rectified and the status of the fire safety system is as under.

	Access to building	Provided
	Number, Width, Type and Arrangement	Provided
1	of exits.  Protection of Exits by means of fire check	Provided
1	door (s) and or pressurization.	
1	Compartmentation.	Provided
5	Smoke Management System.	Provided
6	Fire Extinguishers.	Provided
7	First-Aid Flose Reels.	Provided
8	Automatic fire detection and alarming	Provided
(0)	System	
9	MOLFA	Provided
	Public Address System.	Provided
10	Automatic Sprinkler System.	Provided
12	Internal Hydrants and Yard Hydrants.	Provided
15	Pumping Arrangements.	Main Pump (4500 lpm). Stand
138	THE STATE OF THE S	by pump (4500 lpm), Jokey
		pump (180 lpm) all pump
		head 80 mtrs.
14	Captive Water Storage for fire fighting.	Provided
15	Exit Signage	Provided
16	Provision of Lifts:	Provided
17	Standby power supply	Provided
18	Rufuge Area.	Provided
10	Fire Control Room	Provided
20	Special Fire Protection Systems for Protection of special Risks.:	r Provided

The afore and fire fighting arrangements were checked and found functional during inspection. Hence the said IGI underground Metro Station near T-03 is considered safe from the safety point of view and accordingly fire safety certificate is put up

As approved, FT letter is but up for your Signature Pl. letter is put-up for ergn-pl