GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/OFS/MS/EH/2012/1475

Dated: 25/04/12

FIRE SAFETY CERTIFICATE

Certified that the M/S Chaupal Restaurant at F-3/11-12, Main Road (Parts), Krishna Nagar, Delhi-51, is running at ground & first floor building comprised of ground plus two upper floors was granted NOC by this department vide letter no.F.6/DFS/MS/EH/09/451 dtd.13.02.2009. The premises was reinspected by the officer concerned of this department on 12.04.12 in the presence of Sh.I.R. Malhotra (G.M) of the restaurant and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the ground & first floor of building is fit for occupancy class D "Restaurant Building" with effect from 25... (29...) 12... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 25/04/12 at New Delhi by

Chief Fire Officer Delai Fire Service

Depty Health officer Shahdara (South) zone, Karkardooma, Delhi.

In reference letter no.DHO.Shd (S)/2012/2121 dtd.27.03.12

Copy to:-

Shri B.B.Suri, M/S Chaupal Restaurant F-3/11-12,Main Road(Parts), Krishna Nagar,Delhi-51

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall

be responsible.

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.

5. This certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

Sto redbal

	INSPE	CTION REPORT			٦		
1.Nar	ne & address of the building: Chaupal Reat	aurant at F-3/11-1	2. Main Road(Part	s) Krishna Nagar			
	Delhi-51.	•	,	o,, Krisilia Nagar,			
	Type of Occupancy : Assembly at ground & first floor.(Eating House) Type of Case : Renewal						
4. De							
	6. Date of Inspection : Old requirement : 12.04.12						
7. Na	ame of the Inspecting Officer: ADO Suresh	Singh					
	ame of the designation of Officer		2 nos. MR 2 nos. MR 1 no. of 1.2 m& 1 no. of 1.0 m 1 no. of 1.0 m 1 no. of 1.0 m 2 nos. 1.0 m 1 no. of 1.0 m 2 nos. 1.0 m 1 no. of 1.0 m 2 nos. 1.0 m 3 no. of 1.0 m 4 no. of 1.0 m 5 no. of 1.0 m 6 no. of 1.0 m 7 no. of 1.0 m 8 no. of 1.0 m 8 no. of 1.0 m 9 no. of 1.0 m 1 no.				
	m the building side : Sh.I.R.Malhot	ra (GM)					
9. Yea	ar of Construction : 2005						
10.Ap	plicant's letter No : DHO.Shd.(S	S)/2012/2121 dtd.	.27.03.12				
	Minimum Standards on fire prevention			Remarks MR/NMR	1		
	and fire safety U/R33	Requirement		Activity Willy			
1	Access to building				-		
	 Road width 		6 Mtrs.	MR			
	Gate width						
	 Width of internal road 	ting only tips that they have not only tips tips	and the state of t	The star age was too too too too.			
2	Number, Width, Type and Arrangement o	f F. da	the car are the sea one can are any age	and part of the state of the state of			
	a. Number of Staircases						
	Upper Floor	2 nos.					
	Basement	2 nos.	2 nos.	MR			
	B. Width of Staircases	4.0.1.					
	b. Width of Staircases	1.2 M		MR old	La		
	Upper Floor	4011					
	o opper Floor	1.2 M		MR			
	Basement		1no.of 1.0m				
	c. Protection of exits	No. 400 400 400 400 400 400 400 400 400 40	and due too too too too too had not also also too too	600 day and 600 (00 (00 (00 (00 (00 (00 (00 (00 (00			
	Fire check door	No. 40 NO 10	100 day day and not not not also day the say and		-		
	Pressurization			THE RES AND ADD THE THE THE THE THE THE THE			
	e. No. of continuous staircases to terrace			THE RES TO SEE OUR SEE OUR SEE OUR SEE OUR SEE			
	g. Width of Corridor	100 000 day not not not not not not one on our not day on our not		THE SALE AND			
	h. Door Size	and the size of the total wife wife the total control and the size of the control total	400 and				
	11. DOOT SIZE	1.5 Mtrs.	2 nos.1.5 Mtrs.	MR			
			& 1.1 Mtrs.	100000000			
3	Compartmentation.	Required	Provided				
	Fire check door	that day one was not the first that the same one one one and	and any time and and time time time and time and	THE RES THE REP REP TO THE RES THE RES THE RES THE			
	 Sealing of electrical shafts 	the car are the same and and sale upo top the last data data day may may may	vites are the other with some and disk with other other	AND THE THE THE WAY HAVE NOT HER THE WAY HO			
	 Fire rating of shaft door 	AND NO.		100 400 400 day on our out on the day on the last out			
	 Water curtain 	******					
	 Fire Dampers 	Wild was now one cale also says talk any talk and talk and talk and talk and talk and	No. and the same had not say that the same had not say the	***************************************			
1	Smoke Management System.	ı	L				
	Basement						
	Upper floor	00					
j	Fire Extinguisher						
	Total numbers	02 no.	02 No	B.4.D.			
	THE PARTY OF THE P	0Z 11U.	U3 NO.	IVIK			

	• types	ABC & Co2	ABC & Co2	MR			
	 IS marking 	ISI marked	ISI marked	MR			
6	First-aid-Hose Reels.		io markea	14117			
	 Total numbers of each floor 	1no.	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	 Nozzle diameter 		TTOVICE	IVIIX			
		5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors						
	Location of main panel	100 CO 10					
	 Location of repeater panel 	and the same that any					
	Alternate source of power			SUP DOWN SIZE AND NAME AND NAME AND NAME AND ADDRESS OF SIZE AND A			
	The state source of power						
	Hooters's location						
3	MOEFA	Required	Provided	MR			
9	Public address System.	Required	provided	MR			
10	Automatic Sprinkler System.	Required	Provided	MR			
	• basement						
-	upper floor	Required	Dunidad				
	sprinkler above false ceiling	Required	Provided	MR			
1	Internal Hydrants						
-	size of riser/down-comer	100 mm	100				
			100 mm	MR			
	Number of hydrants per floorHose Box	1 no.	1 no.	MR			
2	Yard Hydrants.	1 no.	1 no.	MR			
	Total Hamber of Hydrants			more some vande verde verde vinder vinder vinder vinder vinder vinder			
.3	TIOSC DOX						
.5	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump						
	Head of Main Pump			400 MM			
	Number of main pumps	***					
	> Jockey pump out put	ME AND	44 40 10 10 10 10 10 10 10 10 10 10 10 10 10				
	> Jockey pump head	FIG. 502 603 604 604 607 607 607 607 607 607 607 607 607 607	-07 CO	400 MO AND			
-	> Standby pump out put	THE THE THE THE CHI	Near maps such value made maps maps made and mode stop maps made	MICH SEA FOR SEA			
	Standby pump Head	See that the case opin and the tree too the table the time that the tree too	THE NAME AND ADDRESS OF THE PART WAS AND ADDRESS OF THE ADDRESS OF	the day the last opt top our risk age and age ass			
	> Auto Starting /Manual stopping	5	which came and which and come game under some came came who wide when	the new year way and also have take one age age			
	> Pump House Access	THE ME HE	with case was their with relative per year, who will not their their their	the star and and the star and the star and			
	Terrace Level						
	Discharge of pump	450 lpm	450 lpm	MR			
	Head of the Pump	40 M	40M	MR			
	> Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
А	Captive Water Storage for Fire Fighting.						
4							

Chopel Restaurant

	Draw-off connection	there was not not not not not not one one one one one one one one one		for our oil do dot dat dat old old oil on oil oil oil oil oil oil
	Fire service inlet	NAME AND ADD ADD ADD ADD ADD ADD ADD ADD ADD		
1	Access to tank			NO AND
	 Overhead Tank capacity 	5000 Ltrs.	5000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		11011000	14111
	 Pressurization of Lift Shaft 			
	 Pressurization of Lift lobby 			
	 Communication in lift car 			
	 Firemen's grounding switch 			
	Lift Signage	400 day 400 km tag 100 day 600 min 400 day 600 day 600 day 600 day 600 day		THE THE COST COST COST COST COST COST COST COST
17	Standby power supply	Required	Provided	MAD
18	Refuge Area.		Frovided	MR
	Total area	THE NAME HOW HOME AND HOST ONE HOME THAN THAN HOME HOME		
	Location			This did not the test too too too use
19	Fire Control Room			after som one case som som com som one case
e e	Detector system panel			
	Flow switch panel			and the first one of the sale and the sale and the
	PA system panel			
			AT 40 40 40 40 40 40 40 40 40 40 40 40 40	
	Batter backup	400 ENG COS	the fact that will have the first that who was the first that will have	and the first day has the sea and the sea and the
20	Building Floor Plans	was not not upo upo upo non men men men upo non upo men	war ner net ver der rein tied net net net her fen ber war ver net	filer mar you you you also have been mad you upon
20	Special Fire Protection systems for	Now have now may may may may may have may have may have may have may may	and the new new new new new new new new new ne	NOT CONT AND THE THE TAX TOO TOO TOO TOO
	protection of special Risks, if any:			

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name

Suresh Sugh

Name

Designation

ADO

Designation

DO(R)

Submitted

approval

please.

20/41/ In