GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/MS/DFS/GH/2012/1527

Dated: - 27/04/12

FIRE SAFETY CERTIFICATE

Certified that the Malhotra Guest House located at 2911, Sir Seyed Ahmed Road Darya Ganj, New Delhi-110002 comprised of ground floor (Commercial Use), 1st floor (06 guest rooms + Reception), 2nd floor (Owner Residence), 3rd floor (Owner Residence) Total 06 guest rooms was granted NOC by this department vide letter No. F6/MS/DFS/GH/2009/843 dated 24-03-2009. The premises was re-inspected by the officer concerned of this department on 23-04-2012 in the presence of Sh. Qamar Ali Khan and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 06 guest rooms with effect from 2.7.1.2.1...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 2.7/04./.!. at New Delhi by.

CHIEF FIRE OFFICER
FOR DIRECTOR
DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Shri Qamar Ali Khan M/s Malhotra Guest House located at 2911, Sir Seyed Ahmed Road Darya Ganj, New Delhi-110002

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECT	TION REPORT	4 44 40 0	au cie		
Malkotea Guest House, 2911, six						
1. Name & address of the building: Seyed Alamed Road Dazya Gang						
2	2. Type of Occupancy Residential, (Guest Mouse)					
3	Type of Case : New Co	ase/Renewal				
4	Details of previous NOC : Letter N	10 F6/ms/2FS	7 G. 11/09/Dated	1:24-03-09		
5	The balety directives letter 100	VA -	1843			
6	Date of inspection	23-01-20	12			
7	Name of the Inspecting Officers: Date	gm vie sin	Sh yadal ()	4.80)		
8	. Name and designation of officers	*				
	from the building side Me. Qamas Ale Khan					
	Year of Construction : 198	2 (starting	year)			
	O. Applicant's letter No.	11 dated	19-09-2012			
S.	Minimum Standards on fire	NBC	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Requirement	n	MR/NMR		
1	Access to building	-		PSS OFER		
	 Road width 	Accessible	05 to 06 mts	m.R.		
	Gate width	N.A -	-N.A -	-N.A-		
	Width of internal road	-N.A -	- N.A -	-NA-		
2	Number, Width, Type & Arrangement of	of Exits	· · · · · · · · · · · · · · · · · · ·			
	a. Number of staircases					
*	 Upper Floors 	-	Recove Gto To	st) m.R		
	 Basements 	- N.A -	- N.A-	- MA-		
	b. Width of staircases					
×	Upper Floors		Rec = go ems	n. P		
	• Basements		ison Allesnate	Staucase		
2	c. Protection of exits					
	Fire check door	N.A				
	 Pressurization 					
	e. No. of continuous staircases to terrace			m . o		
	g. Width of Corridor		one	- 10 a		
	h. Door Size	N.H.	-N.A-	N.H -		
		-11.H-	- // -	- KT -		

Malhotea Guest House 2311 Sik Sexed Ahmed Road, Dasya Gary Delli-110002

			2 2 2	old
				call
3	Compartmentation.			
	• Fire check door	N.A		
	 Sealing of electrical shafts 	- 10-71		
	 Fire Rating of shaft door 			
	 Water Curtain 			
	• Fire Dampers			
4	Smoke Management System.			
	Basements	30 a/c per hour	-1.1	
	Upper floors	12 a/c per hour	- N. A -	fort n
-		22 die per nour	Waster Dega	xauon pr
5	Fire Extinguishers			
	 Total numbers 		There (3)	M-R
	• Types		W.C02=2	M·R
	 IS marking 	ISI marked	co2 = /	M-A.
6	First-Aid Hose Reels.		yes	////(-
	Total numbers on each floor		-N.A-	N. O
	 Length of hose reel hose 	30 m	-N.A-	-N.A
	Nozzle diameter	5 mm	-N.A -	- 12-0
7	Automatic fire detection and alarming	system.	- // - //	- NA
	Type of detectors	. N.A		
	 Location of Main Panel 			
	A STATE OF THE STA			
	Soution of Repeater Paner			
	Alternate source of power		2	
	Hooters' Location			
3	MOEFA	N.A		
)	Public Address System.	N.A		
0	Automatic Sprinkler System.			
	Basement	/. /		

conta.

Makkotea Guest Mouse 2811, sie seyd Ahmed Road, Dalya Garo, 3

				olde
	• Upper Floor	N-A		
	Sprinkler above false ceiling			
	Internal Hydrants			
	Size of riser/down-comer	N-A		
	Number of hydrants per floor			8
	• Hose Box			
	Yard Hydrants.			
		-N.A		
	Total number of hydrantsHose Box		/	
			,	
	Pumping Arrangements.			
	Ground Level	N'A		
	Discharge of main Pump			
	➤ Head of Main pump			
	Number of main pumps			TO THE PARTY OF TH
	Jockey Pump out put			
	Jockey pump head			
	> Standby Pump out put		6	
	Standby Pump Head			
	Auto Starting/ Manual			
	1 a a x 2			
	stopping		,	23
	> Pump House Access			
	Terrace level Disabarga of nump	- N.A		
	Discharge of pump	7		1
	Head of the pump			4
	Power Supply Auto Starting of sums			
	Auto Starting of pump			
1	Captive Water Storage for fire fighting.			
	 Underground tank capacity 	Nº A		
	> Draw-off connection	/		conta

malkotea Guest Morse,
2911, sie seged Akoned Road,
Delle -110002.

				PSS ALSA
	> Fire service inlet	N. A		PSS M
	> Access to tank			
	Overhead Tank capacity	/		9 8
15	Exit Signage.	Yes	yes	m.R
6	Provision of Lifts.			and the second s
	Pressurization of Lift Shaft	N.A		
	 Pressurization of Lift lobby 			
	Communication In lift Car			
	• Fireman's Grounding Switch		3	
	• Lift Signage			
17	Standby power supply	- N.A.	N.A -	- w.A -
18	Refuge Area.			
	> Total Area	-N.A		
	> Location			
19	Fire Control Room			
	Detector System Panel	N'A		
	• Flow Switch Panel			
	PA System Panel			
	Batter backup			17
	Building Floor Plans			
20	Special Fire Protection Systems for	- NA		
	Protection of special Risks, if any:			
		1		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

molliter Guest House

29/1 sie seged Ahmed Road, (5)

29/1 Delys Gang, Delhi-1/0002. Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dhalm vie singh yalow. Name Designation Acristant Siricional (contact) Designation Do. (content) for oulle