GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 1633

Dated: 04/05/12

FIRE SAFETY CERTIFICATE

Certified that the Lav-Kush International Guest House located at 2279(1/2), 80, 81, Rajguru Road, Chuna Mandi, Pahar Ganj, New Delhi comprised of ground floor (reception + staff room + shops + 04 guest rooms), 1st floor (04 guest rooms), 2nd floor (05 guest rooms + Store room) and 3^{rd} floor (02 guest rooms + Store room) Total 15 granted NOC by guest rooms was this department vide F6/MS/DFS/GH/2009/1212 dated 04-05-2009. The premises was re-inspected by the officer concerned of this department on 24-04-2012 in the presence of Sh. Rajender Vij and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 15 guest rooms with renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .04/.of.//.2.. at New Delhi by

Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Shri Rajender Vij M/s Lav-kush International Guest House, 2280, Rajguru Road, Chuna Mandi, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

		TION REPORT	ternational .	Quest House						
	Name & address of the building 22	10 (1/2) 2	280, 2281 Ro	aj Guru Road						
2	Type of Occupancy Cha	na mandi,	Pakas Gan	, New Dellis.						
1	Residential (quest house)									
7 to 10	4. Details of previous NOC $\frac{Renewal}{F_6/M \cdot S/DFS/G_1M/2009/12/2} dated 04-05-200$									
1	5. Fire Safety directives letter No - N. A-									
1	6. Date of inspection $24-04-20/2$									
7	7. Name of the Inspecting Officers: Dhasm vie singh yadar (A.D.o)									
7. Name of the Inspecting Officers: Dhasm vis singh yadar (A.D.o) 8. Name and designation of officers from the building side. She Razin des Kumas vij.										
from the building side										
9. Year of Construction —N.A.—										
1	O. Applicant's letter No. (2/2	06/Addl.c.f.	/Lie (h) dated	Vew Selle 28-219						
S.	Minimum Standards on fire	PSS ASEA	Provided at site	Remarks						
No.	prevention and fire safety U/R 33	Requirement	A VINICUM SILL	MR/NMR						
1	Access to building			old ease						
	Road width	-N.A-	-N.A -	-N.A-						
	• Gatè width	-N-A-	-NA-	-N.A-						
	Width of internal road									
2	Number, Width, Type & Arrangement	of Exits								
	a. Number of staircases									
	 Upper Floors 	070	one	m·R						
	Basements	= N.A.	-N.A-	- N-A-						
	b. Width of staircases									
	Upper Floors		81 Cms to 85 Cms.	me						
	• Basements	- N.A -	-NA-	- NA -						
	c. Protection of exits			- " "						
	Fire check door	-NA-								
	 Pressurization 		- N.A-	-N.A-						
	e. No. of continuous staircases to terrace	- N-A -	-N.A-	- N.A -						
	g. Width of Corridor		one	M.R.						
	h. Door Size	- N.A-	- N.A-	- N.A-						
	A. DOOL DIZE	- N.A-	- N.H-	- N.A -						

contd:

Luv. Kush Intel national
2279 (1/2), to to Ray Gueu Road,
chuna mandi Pakok Gand, New Delli Moss.

3 Compartmentation. Fire check door Sealing of electrical shafts 13 Fire Rating of shaft door Water Curtain Fire Dampers 4 Smoke Management System. Basements 30 a/c per hour Upper floors 12 a/c per hour 5 Fire Extinguishers Total numbers OB MR Types Water Con, DCP MR IS marking ISI marked Yes MR 6 First-Aid Hose Reels. Total numbers on each floor 01 01 MR Length of hose reel hose 30 m Yes MR Nozzle diameter 5 mm 408 MR 7 Automatic fire detection and alarming system. Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 8 **MOEFA** Yes Yes 9 Public Address System. Yes Automatic Sprinkler System. 10 Basement N.A. N.A. MA

LW-KUSh International
2279 (1/2) 80 81 RAJ GURU Road, 3)
Chura mandi, Pahar Ganz New Delli.
110055

-		old case			
	• Upper Floor	- N.A	- NA -		
- 1	Sprinkler above false ceiling	-NA-	- NA-	-NA-	
1	Internal Hydrants				
	Size of riser/down-comer			+	
	 Number of hydrants per floor 		J. A		
	Hose Box				
12	Yard Hydrants.				
-	Total number of hydrants				
	Hose Box		XI.A		
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump		/		
	> Head of Main pump				
	a source of main paints				
	> Jockey Pump out put		V. H.		
	> Jockey pump head				
	> Standby Pump out put				
	Standby Pump Head	/.			
	➤ Auto Starting/ Manual				
	stopping				
	➤ Pump House Access				
	Terrace level	450 LPM	Yes	MR	
	Discharge of pump	30 mts.	4-es	mR	
	Head of the pumpPower Supply	Yes	Yes	mR	
	➤ Auto Starting of pump			mR	
14	Captive Water Storage for fire fighting.	Yes	Yes	777	
2	Underground tank capacity	NA	NA	N.A	
	> Draw-off connection	NA	N.A	NA	

Luv- Kush Integnational
1279 (1/2) po 81 Rag Gueu Road,
chuna mandi pahar Grand,
were Della-11085.

			olo	l case			
	> Fire service inlet	XI.A	MA	NA			
	> Access to tank	N.A.	N. A.	N.A			
	 Overhead Tank capacity 	2500 Litter	2500 Ctrs	mR.			
15	Exit Signage.	Yes	Yes	mR.			
16	Provision of Lifts.						
	 Pressurization of Lift Shaft 						
	Pressurization of Lift lobby						
	Communication In lift Car						
	• Fireman's Grounding Switch		N.A-	8 2			
	• Lift Signage						
	Lift Signage			8 - A1 ₂			
1.7	Standby power supply	Yes	Yes	MR			
18							
	> Total Area	NA	NA.	N.A.			
	> Location	MA	NA	NA			
19	Fire Control Room						
	Detector System Panel	T					
	Flow Switch Panel						
	PA System Panel		N-A	, s			
	Batter backup						
	Building Floor Plans						
20	Special Fire Protection Systems for		11 0				
	Protection of special Risks, if any:	N. A	70, 11	Nº H			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

(UV - KUSA International
22.79 (1/2), So 81 Ray Guell Road,
chuna mande pakas Grand
New Delli-1/055.

Signature of the Inspecting Officer

Name

Designation

Do /centsel)

15/12

Signature of the Inspecting Officer

Name Thalm vie single yeller.

Designation Assistant Divisional
afficel (conted)