GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 167/

Dated: 09/05/12

FIRE SAFETY CERTIFICATE

Certified that the Shanti Niwas Guest House located at 159, Kucha Ghasi Ram, Chandni Chowk, Delhi-110006 comprised of ground floor (reception + 08 guest rooms), 1st floor (residence), 2nd floor (residence) Total 08 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2857 dated 13-10-2008. The premises was re-inspected by the officer concerned of this department on 04-05-2012 in the presence of Sh. Parmod Kumar and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 08 guest rooms with effect from ... a. S. J. e. L. 2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued . a \$./o.t./!!: at New Delhi by.

CHIEF FIRE OFFICER DELHI, FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Shri Mahabir Parshad M/s Shanti Niwas Guest House, 159, Kucha Ghasi Ram, Chandni Chowk, Delhi-110006

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

| 1 22 | | 43 | | | |
|---|---------------|-------------------|---------------|--|--|
| Name & address of the building: Shan | ti xline | | | | |
| 2. Type of Occupancy Po | 11/4/was 674e | 8+ House, 189, K | ucha Ghasika | | |
| 1. Name & address of the building: Shanti Niwas Guest House, 189, Kucha Ghasika 2. Type of Occupancy 3. Type of Case 4. Datails of Shanti New Case/ Renewal | | | | | |
| 4. Details of previous NOC : Letter N | Jo Echoula 1 | | | | |
| 5. Fire Safety directives letter No: | ALL COLDESIMS | 24/2009/9857 Date | d: 13-10-2008 | | |
| O. Date of inspection | | | | | |
| of the hispecting Officers | 14-05-2012 | | | | |
| a configuration of others | Dis Yada | v (A.D.O) | | | |
| from the building side | D . 1 1 | | | | |
| 9. Year of Construction | Parmod Kui | nar | | | |
| A CAPATICANT'S letter No. | NA- | | | | |
| Minimum Standards on fire | | 03-05-2012 | | | |
| prevention and fire safety U/R 33 | NBC | Provided at site | Remarks | | |
| Access to building | Requirement | P.S.S. Areg. | MR/NMR | | |
| • Road width | | | 1 | | |
| | MA | MA | MA | | |
| Gate widthWidth of internal road | NA | NA | NA | | |
| | NA | NA | NA | | |
| Number, Width, Type & Arrangement o | f Exits | | /4*(| | |
| a. Number of staircases | | | | | |
| • Upper Floors | one | one | MR | | |
| * Basements | NA | MA | NA | | |
| b. Width of staircases | | * | 7071 | | |
| Upper Floors | 90 cms | 0.4.4.40 | | | |
| Basements | NA | 90.CMS | M.R | | |
| c. Protection of exits | /48 | NA | NA | | |
| • Fire check door | 1011 | | | | |
| • Pressurization | MA | NA | NA | | |
| e. No. of continuous staircases to terrace | NA | NA | NA | | |
| g. Width of Corridor | 01 | 01 | MR | | |
| h. Door Size | MA | NA | MA | | |
| >001 0120 | NA | NA | NA | | |

contd:

Shanti Niwas Gruest House, 189 Kucha Ghasi Ram, Chandni Chowk, Delhi-6

Old Case

| Cor | upartmentation. | | , sa | | |
|-----|---|------------------------------------|---|------------|--|
| | Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers | | NA | | |
| Sı | noke Management System. | | | | |
| | BasementsUpper floors | 30 a/c per hour 12 a/c per hour | - N.A - - N.A - | - NA - | |
| E | ire Extinguishers | | | | |
| | Total numbersTypes | 101 multod | 04 Water Co2 & D.C.P | MR. MR. | |
| 6 | • IS marking ISI marked Yes MK First-Aid Hose Reels. | | | | |
| | Total numbers on each floor Length of hose reel hose Nozzle diameter | 30 m 5 mm | NA NA | NA NA | |
| 7 | Automatic fire detection and alarmin | ig system. | | | |
| | Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power | | NA | | |
| | Hooters' Location | | | NA | |
| 8 | MOEFA | MA | NA | NA | |
| 9 | Public Address System. | | | | |
| 10 | Automatic Sprinkler System. | MA | MA | NH | |

Shanti Niwas Gruest House, 1801, Kucha Ghasi Ram, Chandni Chowk, Delhi-6

old Copse Upper Floor Sprinkler above false ceiling Internal Hydrants 1 Size of riser/down-comer Number of hydrants per floor Hose Box NA 12 Yard Hydrants. Total number of hydrants Hose Box XIA 13 Pumping Arrangements. Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head ➤ Auto Starting/ Manual stopping > Pump House Access Terrace level > Discharge of pump Head of the pump Power Supply > Auto Starting of pump 14 Captive Water Storage for fire fighting. Underground tank capacity Draw-off connection MA

contd:

Shanti Hiwas Guest House, 159, Kucha Gihasi Ram, Chandni Chowk, Delui - 6

Old Case

| | Fire service inlet Access to tank Overhead Tank capacity | | MA | |
|---|--|-----|-----|----|
| 5 | Exit Signage. | 408 | Yes | mR |
| | Provision of Lifts. Pressurization of Lift Shaft | | | |
| | Pressurization of Lift lobby | | | |
| | Communication In lift Car | | NA | |
| | Fireman's Grounding Switch Lift Signage | | | |
| 7 | Standby power supply | | | |
| 8 | Refuge Area. | Yes | Yes | mR |
| | Total AreaLocation | | NA | |
| 9 | Fire Control Room | | | |
| | Detector System Panel Flow Switch Panel PAi System Panel | | NA | |
| | Batter backup Building Floor Plans | | 771 | |
| 0 | Special Fire Protection Systems for Protection of special Risks, if any: | NA | NA | NA |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

| , Mar | Shanti Miwas Gyest House, 159 Chandri Chowk, Delhi-6 | Old Case (5 |
|-------|---|---|
| | Signature of the Inspecting Officer | Signature of the Inspecting Officer |
| | Name Designation | Name Dhalm vie sinch yadou |
| | Do Centeal / S/3/12 | Designation Assistant Divisional afficel (center) |