GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001 No. 66/265/ans/ Hospital/2012/1822

Dated 21/05/12,

FIRE SAFETY CERTIFICATE

Certified that the Dr. Gupta Nursing Home & Hospital, 25, Raj Block, Naveen Shahdara, Delhi-32 by M/S Dr. Gupta Nursing Home & Hospital, comprised of basement ground plus three upper floors was granted NOC by this department vide letter No.F.6/MS/DFS/2009/2506/HR/NOC/63 dated 15.12.09. The premises was re-inspected by the officer concerned of this department on 26.04.12 in the presence of Mr. U.P.Sharma and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group C (Institutional building) with effect from 21./.55./12. Renewed for a period of three years, subject to conditions printed overleaf.

Issued on 2//of/12 at New Delhi by

Chief Fire Officer Delhi Fire Service

To

Dr. Saurabh Srivastava (Medical Superintendent) Dr. Gupta Nursing Home & Hospital, 25, Raj Block, Naveen Shahdara, Delhi-32

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This NOC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. Basement shall be used as per BBL.

INSPECTION REPORT

1. Name & address of the building : Dr. Gupta Nursing Home & Hospital, 25, Raj Block, Naveen

Shahdara, Delhi-32.

2. Type of Occupancy

: Institutional

3. Type of Case

: Renewal

4. Details of Previous NOC

: Letter No- F.6/MS/DFS/2009/2506/HR/NOC/63 Dated 15.12.09

5. Fire Safety direction letter No

: Old requirements

6. Date of Inspection

: 26.04.12

7. Name of the Inspecting Officers: : Suresh singh (ADO)

8. Name of the designation of Officer

from the building side

: Mr. Umesh Prasad Sharma

9. Year of Construction

: 1979

	. 19/9					
10.A	pplicant's letter No : Nil	-				
S.No	Minimum Standards on fire prevention and fire safety U/R33	Old as Cleard Requirement	Provided at Site	Remarks MR/NM		
1	Access to building					
	Road width	6 m	6 m	MR		
	Gate width					
	Width of internal road					
2	Number, Width, Type and Arrangement o	f Exits		1000 1000 1000		
	a. Number of Staircases	2 no.	2 no.	MR		
	Upper Floor		***************************************			
	Basement B. Width of Staircases Upper Floor Basement c. Protection of exits Fire check door Pressurization e. No. of continuous staircases to terrace g. Width of Corridor	2 no.	2 no.	MR		
			1.8 & 0.9 m	MR		
			1 & 0.9 m	MR		

			1 no.	MR		
			2.7 m	MR		
	h. Door Size		1 m	MR		
	Compartmentation.	Required	Provided			
	Fire check door					
	 Sealing of electrical shafts 					
	Fire rating of shaft doorWater curtain					
	Fire Dampers		-			
	Smoke Management System.	N/A	L			
	Basement	and the second s				
	Upper floor	12 a/c per hour				

5.	Fire Extinguisher	Required				
	Total numbers	Required (10)	Provided (10)	MR		
	Types	Co2 & ABC	Co2 & ABC	MR		
	IS marking	ISI marked	ISI marked	MR		
6	First-aid-Hose Reels. Required					
	Total numbers of each floor	T	provided (oy)	MR		
	Length of hose reel hose	Required (oy)	provided (oy)	MR		
	Nozzle diameter	5 mm	•			
7	Automatic fire detection and alarming sys		provided	MR		
	Type of detectors Heat & Smoke Provided MR					
	Location of main panel	Ground Floor	Provided	MR		
	Location of repeater panel		1 2 2 4 1 3 7750 ANDRO			
	Alternate source of power			••••••		
	Hooters's location	***************************************				
8	MOEFA					
9		***************************************	yes	••••••		
10	Public address System.		yes			
10	Automatic Sprinkler System. basement	T	T			
	1, Design Common Control of the Cont	Required	Provided	MR		
	upper floor	••••••				
	sprinkler above false ceiling			••••••		
11	Internal Hydrants					
	size of riser/down-comer	100 mm	100 mm	MR		
	Number of hydrants per floor	one	one	MR		
	Hose Box	one	one	MR		
12	Yard Hydrants.					
	Total number of hydrants					
	Hose Box					
13	Pumping Arrangements.	Required	1	L		
	Ground Level					
	Discharge of main Pump					
	Head of Main Pump					
	Number of main pumps					
	Jockey pump out put					
	Jockey pump head					
	Standby pump out put					
	Standby pump Head	•••••				
	Auto Starting / Manual stopping					
	Pump House Access					
	Terrace Level			***************************************		
	Discharge of pump	450 LPM	2 no. 450 LPM	MR		
	➤ Head of the Pump		2 1101 430 El IVI			
		40 m	Provided	MR		

(Gupta Mursing Home)

-				
	Power supply			
	Auto Starting of pump			
14	Captive Water Storage for Fire Fighting.	Required		
	Underground tank capacity			
	Draw-off connection		***************************************	
	Fire service inlet	***************************************		••••••
	Access to tank	***************************************	***************************************	
	Overhead Tank capacity	***************************************		
15			50,000 Liters	MR
	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Yes		
	Pressurization of Lift Shaft			
	Pressurization of Lift lobby			
	Communication in lift car Firemen's grounding switch Lift Signage			
2				
47				
17	Standby power supply		Yes	
18	Refuge Area. N/A			
	Total area Location			
40				
19	Fire Control Room	N/A	1	
	Detector system panel			
	Flow switch panel PA system panel Batter backup			
	Building Floor Plans			
20		••••••		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A		
				A

The fire protection systems provided in the building were test checked at the time of inspection and found functional.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Bo (Exst) SIV, Now dhousare bldg is basement Signature of the Inspecting Officer by the crumer three only. Fourth floorisdemolululare Surem Supply Submitted for approval please. Designation ADD

Dycko (Ningl