GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No F 6/DFS/MS/2012/ Hotel /1858

Dated 22/05/12

FIRE SAFETY CERTIFICATE

Certified that the The Janpath Hotel, located at Janpath, New Delhi - 110001, comprised of Small Basement + Ground + Five upper floors was granted NOC by this department vide letter No F 6 / MS / DFS / HOTEL / 2011 / 750 dated 26.04.2011. The premise was re-inspected by the officer concerned of this department on 03.05.2012 in the presence of Mr. Rajiv Chopra (GM) and Mr. Sandeep Singh (Asstt. Manager) found that the said Hotel have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group A Sub Division A-5, "Hotel Building" with effect from 2.2. [ass.]. For a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. 2.2./ ø5.//2..... at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. The Sr. Manager (E&M), Hotel Janpath, Janpath, New Delhi.
- 2. The Addl. Comm. of Police (Lic) First Floor, Police Station Defence Colony, New Delhi.

Conditions for the validity of fire safety certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire protection measures shall be maintained in perfect working conditions all the times as seen during inspection.
- 3. All the staff members must know the correct method operation of fire fighting system.
- 4. Any lapse rendering fire fighting system/equipment non-functional shall be risk and responsibility of the management.
- 5. This inspection report may not in any way be treated as regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. Smoke management system should completed with in six months.

	INSPECT	TON REPORT	- 1-4	200 2012			
1	Hoi	el Jan Path,	Jan Path, Ne	ou seche-/or			
1.	Name & address of the building:	-		**			
2		potel					
	Type of Case : New Case/ Renewal						
	4. Details of previous NOC : Letter No F6/MS/DFS/Hotel/2011/F50 Dated: 26-04-11						
5	outery directives letter No: -N.	A	- Duto				
6	: 0 3	3-05-2012		a 20			
	Name of the Inspecting Officers (1) Do. A	tul Gass (ii)	ADO BLOSOM UC	single water			
8	and designation of officers	ai Panie	o la	and the second			
	from the building side	Ei Sandeep	fefer G.M.	4 22			
	Year of Construction : PRI	08 to 1960	753/1	Monte			
). Applicant's letter No. :		102-05-2012	old			
S.	Minimum Standards on fire	NBC/SB/	Provided at site	Remarks			
No.	prevention and fire safety U/R 33	Requirement	a so that at site				
1	Access to building			MR/NMR old case			
	 Road width 		MORE THAN 12 M	,			
	• Gate width		7.00 may 12 M	5 M.R			
	 Width of internal road 	- N-A	- N.A -	-N.A -			
_		-N.A-	- N.A -	-N.A -			
2	Number, Width, Type & Arrangement of	f Exits					
	a. Number of staircases						
	Upper Floors		Two	m·R			
	· Basements small basement		one	M·R.			
	b. Width of staircases			1. 10			
	Upper Floors	14.0		P. C. C.			
	Basements	- 10. H	- N.A-	-N-A-			
	c. Protection of exits	- N.A -	- N.A -	-N.A -			
	• Fire check door			at a second			
			yes	M.R			
	• Pressurization	- N.A -	- N.A -	- N-A -			
	e. No. of continuous staircases to terrace		Two	- M.R-			
W =	g. Width of Corridor	-N-A-	- N.A-	-NA-			
	h. Door Size	- N. A -	- N.A -	- N.A-			

contol:

C.				
Con	partmentation. Fire check door	yes	yes	m.R.
	• Sealing of electrical shafts	yes	ys	M.R. M.R.
	• Fire Rating of shaft door	- NA -	M.A -	- N. A -
	Water Curtain	- N.A	- N-6) -	N.D.
	• Fire Dampers	N-A -	- N-A	-NeA -
Sn	ioke Management System.			
	Basements	30 a/c per hour	- N.A	-N.A-
	• Upper floors	12 a/c per hour	-N-H	10.01
F	ire Extinguishers		172	m·R
	• Total numbers		ABC & W. Cog	M'R M.R
	• Types	ISI marked	Yes Yes	M.R.
	IS marking	101 markou		
]	First-Aid Hose Reels.		TwoEM	de M.R
	Total numbers on each floor Length of horse real horse.	30 m	Twofm	M.R
	Length of hose reel hoseNozzle diameter	5 mm	yes	m·R
7	Automatic fire detection and alarmin	g system.		
	 Type of detectors 		Smoke	M. R
	 Location of Main Panel 		George flow	love m R
*****	 Location of Repeater Panel 			
	Alternate source of power		4.1.5/6	they mik
	Hooters' Location		Near stair	
0	MODEL	yes	yes	M·R
8	MOEFA Public Address System.	yes	yes	M-R
9	And the state of t			10.4
10	Automatic Sprinkler System. Basement Yeal of cons	- N.A.	- N.A	1.0

Hotel janpath Janpak

care

				care
	Upper FloorSprinkler above false ceiling	-N.A-	- yes -	- N.A -
11	Internal Hydrants	2 N. A -	-N.A-	-N.A-
	Size of riser/down-comer			
	 Number of hydrants per floor 	100 M.M.	100 MM	m-A
	• Hose Box		05	M.R
12	Yard Hydrants.		65	M-A
	 Total number of hydrants 			100
c w ^g	Hose Box		7	M.R
13	Pumping Arrangements.		7	MR
				///(
	• Ground Level	1 A E		
	Discharge of main Pump Head of Main main		2850 LPM	mek
	Head of Main pumpNumber of main pumps		2850 LPM 70 mts	m. R
		one	One	m.R
	Jockey Pump out putJockey pump head		380 LPM	M.R
	Standby Pump out put		55 m 188	M-R
	> Standby Pump Head			
	> Auto Starting/ Manual			
	stopping	yes	yes	MR
	> Pump House Access	Yel	Ves	NE CONTRACTOR OF THE CONTRACTO
	• Terrace level	-N. A -	7-	14.4
	Discharge of pump	. N. A		
	Head of the pumpPower Supply			y Wits
	> Auto Starting of pump			
4	Captive Water Storage for fire fighting.			
	Underground tank capacity		200	
2	> Draw-off connection	2100	2,00,000 410	s M.R
,		yes	yes	M.K

conta:

Hotel Jan path, Jan path, New Delli- 110001

case

	Fire service inlet	yes		_
	Access to tank	The same of the sa	yes	M-R
	 Overhead Tank capacity 	yes	ys	m.R
5			10,000 Lites	c M.R
6	Exit Signage.	yes	yes	M.R
	Provision of Lifts.	Total = 511		14 40 000
	Pressurization of Lift Shaft	-NA-	-N.A -	- N.A -
	Pressurization of Lift lobby	-N.A -		
	 Communication In lift Car 		-N.A-	-N.A-
	• Fireman's Grounding Switch	yes	yel	M.R.
		Yes	Ves	m.A
-	Lift Signage	yes	yes	
7	Standby power supply	70.	(1) 1500 KVA	m.A
8	Refuge Area.		(2) 600 KVA	M.R
	> Total Area			
	> Location	-N.A-	-N.A-	-N.A -
9	Fire Control Room	-N.A-	-N.A -	-NA-
		1		
	Detector System Panel	yes	yes	n.R
	 Flow Switch Panel 	yes	yel	n.L
	 PAl System Panel 	Yes		
	Batterybackup		yes.	MR
		Yes	yes	M.R
0	Building Floor Plans Special Fire Protection G	Yes	yes	m.R.
	Special Fire Protection Systems for	-N.A-	- N.A -	-NA-
	Protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers....

Note: Building constructed prior to 1960

contal :-

Hotel Jan path Jan path, New Dellis-110001

19

n John

Signature of the Inspecting Officer

Name Thaten vie single yados

Designation peristant Divisional
Officer
(certeal)

Signature of the Inspecting Officer

Name

Designation 3/05/12