## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/OFS/MS/School/2012/1902 Dated: 24/05/12

## **FIRE SAFETY CERTIFICATE**

Certified that the Govt.Girls Sec.School at Mandawali,Delhi-92,comprised of ground plus one upper floor owned/occupied by Govt.Girls Sec.School have complied with the fire prevention and fire safety requirements in accordance with with the circular issued by the Director of Education dtd.01.03.2011and verified by the officer concerned of Fire Service on 27.04.2012 in the presence of Smt Nisha Singh, Principal, of the school and that the building is fit for occupancy class B' Educational Building' with effect from A. J. J. L. for a period of three years , subject to conditions printed overleaf.

Issued on 24/05/2 at New Delhi by

Chief Fire Officer Delhi Fire Service

To,

Principal
Govt.Girls Sec.School
Mandawali,Delhi-92

Copy:-

- The Joint Director of Education (Land & Estate) Directorate of Education, Lucknow Road, Delhi -54.
- 2. Principal
  Govt Boys Sec.School
  Joshi Colony, Mandawali,
  Delhi-92

## **CONDITIONS:**

1. All the means of escape shall be kept free of all type of obstruction all the type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management

shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This NOC may not be treated in any case for regularizations of unauthorized

construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

## INSPECTION REPORT

1	Name & address of the building: G.G.S.S.S. School, Mandawali, Delhi								
2									
3	3. Type of Case : New Case/ Renewal								
4	Details of previous NOC : Letter No Dated:								
5	Fire Safety directives letter No: F. 16   Estate   Cc   Ps   7298 to 3398 dtd 1.3.11								
	5. Date of inspection : 18/11/11								
7	7. Name of the Inspecting Officers: Do Vikendya Singh								
	8. Name and designation of officers								
	from the building side : Smt. Nishe Singh ( Bincibal)								
9	9. Year of Construction : 1998								
10	O. Applicant's letter No.	dte	1 18/11/11						
S.	Minimum Standards on fire	Cyrula	Provided at site	Remarks					
No.	prevention and fire safety U/R 33	Requirement		MR/NMR					
1	Access to building								
	Road width		6 M	-MR					
	Gate width								
	Width of internal road								
2	Number, Width, Type & Arrangement of Exits								
	a. Number of staircases	3 Nos.	2 Nos.	NMR					
	Upper Floors	3 Nos.	2 Nos.	NMR					
	• Basements								
	b. Width of staircases			r					
	Upper Floors	1.5 M	1.5 M	MR					
	Basements								
	c. Protection of exits								
	Fire check door								
	<ul> <li>Pressurization</li> </ul>								
	e. No. of continuous staircases to terrace	l Nos.	Not Provided	MAR					
	g. Width of Corridor	1.5 M	1.5 M ·	MR					
	h. Door Size	1.6 M	(.0 M	MR					

			e e				
3	Compartmentation.						
3	<ul> <li>Fire check door</li> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> <li>Fire Dampers</li> </ul>						
4				* * * * * * * * * * * * * * * * * * * *			
4	Basements     Upper floors	30 a/c per hour 12 a/c per hour					
5	Fire Extinguishers	<u> </u>	(3)				
	<ul><li>Total numbers</li><li>Types</li><li>IS marking</li></ul>	12 Nos	14 Nos Anc 2 Cor 151	MR MR MR			
6	First-Aid Hose Reels.						
	<ul> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	30 m 5 mm		1			
7	Automatic fire detection and alarming s	ystem.					
	<ul> <li>Type of detectors</li> <li>Location of Main Panel</li> </ul>						
	<ul> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>						
	- Hoolers Location						
8	MOEFA						
9	Public Address System.						
10	Automatic Sprinkler System.  Basement		V				

•	• Upper Floor				· f		1
	Sprinkler above false ceiling	S		:			
11	Internal Hydrants		, <sup>1</sup> a		1		
	Size of riser/down-comer		3	_ = = = = = = = = = = = = = = = = = = =			
	Number of hydrants per floor						
	Hose Box				1.		
12	Yard Hydrants.					1 2 2	
	Total number of hydrants						
	Hose Box				· .		
13	Pumping Arrangements.						
	Ground Level						
	> Discharge of main Pump			1			
	> Head of Main pump						-
	> Number of main pumps		1				
	> Jockey Pump out put	7.	-				1
	> Jockey pump head				-	+	1
	> Standby Pump out put						-
	> Standby Pump Head			<u></u>			
	> Auto Starting/ Manual				ļ		-
	stopping	- B				5 g a	
	> Pump House Access				1	1	
	Terrace level						
	> Discharge of pump					<b>.</b>	
	➤ Head of the pump						
	➤ Power Supply						
	> Auto Starting of pump						
14	Captive Water Storage for fire fighti	ng.	/				
	Underground tank capacity				1		
	> Draw-off connection		<i>y</i> .				

(GGSS Mandavale)

. 1					
	> Fire service inlet				
	> Access to tank				
	<ul> <li>Overhead Tank capacity</li> </ul>			4.243.	
15	Exit Signage.				
16	Provision of Lifts.				
	Pressurization of Lift Shaft				
	Pressurization of Lift lobby				
			4.1	7	
	Communication In lift Car			aya b	
•	<ul> <li>Fireman's Grounding Switch</li> </ul>				
	• Lift Signage				
				- 4	
17 -	Standby power supply	(1)			
18	Refuge Area.		1. 1. 1.		
(	> Total Area				
	> Location				
19 .	Fire Control Room				
	Detector System Panel				
	Flow Switch Panel				
	PAi System Panel				
	Batter backup				
	Building Floor Plans		a 建建立t		
20	Special Fire Protection Systems for		1.00		
785	Protection of special Risks, if any:		1- 8-41	le See	
			\ \ \		/
-					L

The fire protection systems provided in the building were test checked and found functional at the of inspection.

(GGSS Mandawali)

