

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DLEHI-110001.

No. F.6/DFS/MS/EH/2012/ 1884

Dated: 24/05/12

**FIRE SAFETY CERTIFICATE**

Certified that the **M/s Stylish Hotels Pvt. Ltd. (Berco's Restaurant)** located at First Floor, Manish Metro Plaza-I, Plot No-1, Pocket-5, Sec-12, Dwarka, New Delhi-110075. The building comprised of ground floor plus three upper floors. The restaurant is running at First floor only. Above Restaurant was issued NOC vide this office letter No.F.6/DFS/MS/EH/2009/316 dated 03/02/2009 based on circular No.F.6/DFS/MS/EH/2005/718 dated 04.11.2005 owned/ occupied by M/S Stylish Hotels Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of fire service on 17.05.2012 in the presence of Sh. Raj Kumar Dhawan (Director). The building / premises is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....24/05/12..... at New Delhi.

  
CHIEF FIRE OFFICER  
For DIRECTOR  
DELHI FIRE SERVICE

Copy to:-

- 1 The Deputy Health Officer  
Municipal Corporation of Delhi  
West Zone Rajouri Garden, N.D
- 2 Sh. Raj Kumar Dhawan (Director)  
M/s Stylish Hotels Pvt Ltd. (Berco's Restaurant)  
Manish Metro Plaza-1, 1<sup>st</sup> floor, Plot No-1, Pkt.-5,  
Sec-12, Dwarka, New Delhi-110075.



Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on **[www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)**

### INSPECTION REPORT

1. Name & address of the building : M/S Stylish Hotels Pvt Ltd (Barco's Restaurant), Manish Metro Plaza
2. Type of Occupancy : Assembly (Restaurant) 1st Floor, Plot No-1, Sec-12, Dwarka, No. D
3. Type of Case : New Case/Renewal
4. Details of Previous NOC : Letter No. F-6/DPS/MS/EH/09/316 Date 03.02.09
5. Fire Safety directives letter No : N/A
6. Date of inspection : 17.05.2012
7. Name of Inspecting Officer : D.O H.L. Aneja & A.D.O P.S. Dahiya
8. Name and designation of officers  
From the building side : Sh. Raj Kumar Dhawan (Director)
9. Year of Construction : Before 2009
10. Applicant's letter No. : Nil dated 22.03.12

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks
1.	Access to building			MR/NMR
	• Road width	Accessible	18mtr	MR
	• Gate width	-	120cms	MR, Being Old Case
	• Width of internal road	-	06mtr	MR
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	One	One	MR, Being Old Case
	• Upper Floors	- do -	- do -	- do -
	• Basements	-	-	NO Basement
	b. Width of staircases			
	• Upper Floor	-	122cms to 125cms	MR, Being Old Case
	• Basements	-	-	NO Basement
	c. Protection of exits			
	• Fire check door	N/A	-	-
	• pressurization	N/A	-	-
	d. No. of continuous staircases to terrace	-	One	-
	e. Width of Corridor	-	165cms	-
	f. Door Size	-	139cms x 196cms 152cms x 205cms	-
3.	Compartmentation			
	• Fire check door	N/A	-	-
	• Sealing of electrical shafts	N/A	Sealed	-
	• Fire Rating of shaft door	N/A	-	-
	• Water Curtain	N/A	-	-
	• Fire Dampers	N/A	-	-
4.	Smoke Management System			
	• Basements	30 a/c per hour	-	NO Basement
	• Upper floors		Natural/Ventilation	MR



		12 a/c per hour	-	-
5.	Fire Extinguishers			
	• Total numbers	Four	Provided	MR
	• Types	A.B.C Cap-Stk	-do-	MR
	• IS marking	ISI marked	ISI marked	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose reel hose	30 m	-do-	MR
	• Nozzle diameter	5 mm	-do-	MR
7.	Automatic fire detection and alarming system			
	• Type of detectors	Required	Provided	MR
	• Location of Main Panel	-	-	-
	• Location of Repeater Panel	-	-	-
	• Alternate source of power	-	D G Set 785KVA	-
	• Hooters' Location	-	-	-
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-do-	-do-	MR
10.	Automatic Sprinkler System			
	• Basement	-	-	No Basement
	• Upper Floor	Required	Provided	MR, Only at Restaurant Floor.
	• Sprinkler above false ceiling	N/A	-	-
11.	Internal Hydrants			
	• Size of riser/down-comer	Required	100 M.M	MR
	• Number of hydrants per floor	-	One	MR
	• Hose Box	-	One	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	-	-
	• Hose Box	N/A	-	-
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	-	-
	➤ Head of Main pump	N/A	-	-
	➤ Number of main pumps	N/A	-	-
	➤ Jockey Pump out put	N/A	-	-
	➤ Jockey pump head	N/A	-	-
	➤ Standby Pump out put	N/A	-	-
	➤ Standby Pump Head	N/A	-	-
	➤ Auto Starting/Manual stopping	N/A	-	-
		N/A	-	-

Manish Metro Plaza, 1st Floor, Plot No-1,  
Sec-12, Dwarka.

	<ul style="list-style-type: none"> <li>➤ Pump House Access</li> <li>• Terrace level</li> <li>➤ Discharge of pump</li> <li>➤ Head of the pump</li> <li>➤ Power Supply</li> <li>➤ Auto Starting of pump</li> </ul>	N/A	-	-
		450 LPM, 180 LPM	450 LPM, 180 LPM	MR, Being Old Case
		30 M Each Required	30 M Each Provided	MR MR
		-	Both	MR
14.	<b>Captive Water Storage for fire fighting</b>			
	<ul style="list-style-type: none"> <li>• Underground tank capacity</li> <li>➤ Draw-off connection</li> <li>➤ Fire service inlet</li> <li>➤ Access to tank</li> <li>• Overhead Tank capacity</li> </ul>	N/A	-	-
		N/A	-	-
		N/A	-	-
		N/A	-	-
		-	5000 Ltr	MR, Being Old Case
15.	<b>Exit Signage.</b>	Required	Provided	MR
16.	<b>Provision of Lifts.</b>			
	<ul style="list-style-type: none"> <li>• Pressurization of Lift Shaft</li> <li>• Pressurization of Lift lobby</li> <li>• Communication In lift Car</li> <li>• Fireman's Grounding Switch</li> <li>• Lift Signage</li> </ul>	N/A	-	No lift
		N/A	-	-
		N/A	-	-
		N/A	-	-
		N/A	-	-
17.	<b>Standby power supply</b>	Required	Provided	MR
18.	<b>Refuge Area.</b>			
	<ul style="list-style-type: none"> <li>➤ Total Area</li> <li>➤ Location</li> </ul>	N/A	-	-
		N/A	-	-
19.	<b>Fire Control Room</b>			
	<ul style="list-style-type: none"> <li>• Detector System Panel</li> <li>• Flow Switch Panel</li> <li>• PA System Panel</li> <li>• Batter backup</li> <li>• Building Floor Plans</li> </ul>	N/A	-	-
		N/A	-	-
		N/A	-	-
		Required	Provided	MR
		N/A	-	-
20.	<b>Special Fire Protection System for Protection of special Risks, if any:</b>	N/A	-	-

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to <sup>Renewal</sup> grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ ~~issue shortcomings as noted at serial numbers.....~~

Note:- The building is comprised of Ground Floor plus three upper floors. The upper floors are served by a single staircase having width 122cm to 125cm. The restaurant running at first floor of the building, the kitchen provided two exhaust fans. NOC letter No F.6/DFS/MS/09/316 dated 03.02.2009 based on circular No. F.6/DFS/MS/EH/2005/718 dated 04.11.2005.

  
Signature of Inspecting Officer

Name H. L. Aneja

Designation Divisional Officer

  
Signature of Inspecting Officer

Name P. S. Dahiya

Designation Asstt. Divisional Officer