## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/0FS/MS/ EH/2012/1988

Dated: 31 | 05 /12

## FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name and style of McDonald's at ground and first floor located at DMRC Station, ISBT, Kashmeri Gate, Delhi-110006 comprised of basement ground plus two floors was granted NOC by this department vide letter No. F6/DFS/MS/EH/09/1477 dated 26-05-2009. The premises was re-inspected by the officer concerned of this department on 18-05-2012 in the presence of Mr. D.N. Thakur (manager) and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for Class D (Assembly) occupancy with effect from .3.1...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .3.1.05./1.2. at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to:-

- 1. Shri Harish Sharma M/s Connaught Palza Restaurants Pvt. Ltd., 13A, Jor Bagh Market, New Delhi-110003
- 2. Dy. Health Officer, Municipal Corporation of Delhi, Health Department Civil Line Zone, 16, Rajpur Road, Delhi

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	the delication of the delicati			•8
	INSPECT	ION REPORT	*1	,
1	Name & address and the same of	Donalds Fa	amily Restaute plaza Restaute plaza Restaute DNN	usant 101 /7
2	Name & address of the building: Grant Type of Occupancy	and and fix	t flaza Res/al	Cants (P) 40
3	Vine of Com-	1/105/6	Eusant)	(15B1) DELH
4	Details of provide a second	18c/ Renewal		and the same of th
5	Fire Safety directions to	10. FG/MS/DES/	EH/09/1477 Dated	1: 2/ 25-2-
6	Fire Safety directives letter No :	A	t the said	1. 26-05-200
7	Name of the Impact:	8-05-2012	2	
8	Name of the Inspecting Officers:  Name and designation of officers	Parm vie sing	ch rada	
	from the total	• "	F	
9	Year of Countries:	. D. N. The	LUE (manag	rel \
1.0	O. Applicant's letter No.	V. A -		
S.	Minimum Standards on fire	VIL		old as
No.	Drevention and Give and Give	circular	Provided at site	Remarks
1	prevention and fire safety U/R 33	Requirement		MR/NMR
	Access to building			THE THINK
	<ul> <li>Road width</li> </ul>	Accessible	noce than ante	
	<ul> <li>Gate width</li> </ul>	- N.A.	The same of the sa	M.R
-	<ul> <li>Width of internal road</li> </ul>	and the same of th	-N.A-	N.A-
2	Number, Width, Type & A.	-N.A-	-N.A-	N.A -
	Number, Width, Type & Arrangement of a. Number of staircases	of Exits		
	• Upper Floors			
	Basements		Two	M.R
		-NA-	-NA-	- N.A -
	b. Width of staircases		1 200	
	• Upper Floors	-N.A-	-N.A-	
	Basements	-N.A-	-N.A.	-N.A-
	c. Protection of exits			70 77
	<ul> <li>Fire check door</li> </ul>	-N.A-		
	• Pressurization	-NeA-	-NA-	-N.A
	e. No. of continuous staircases to terrace	-NA-	-NA-	-NA -
	g. Width of Corridor	-NA-	-N-A-	-N-H-
	h. Door Size	- N-A -	-NA-	- p. A -
	,		100	11.

conta

Mc Donald's Family Restausant DMRC Station 1587 Kashmeli Gate

old are

			p3 p3		
Con	mpartmentation.				
	• Fire check door	N.A			
8 ,	<ul> <li>Scaling of electrical shafts</li> </ul>			the control of the co	
	• Fire Rating of shaft door				
	• Water Curtain				
	• Fire Dampers			•	
Sı	Smoke Management System.				
	• Basements	30 a/c per hour	-N. A-	-N.A-	
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	N.A-	M.A-	
	ire Extinguishers				
	<ul> <li>Total numbers</li> </ul>		EIGHT	MrR	
	• Types		ABC Type an	M.R.	
	IS marking	ISI marked	yes.	MR	
	First-Aid Hose Reels.				
	<ul> <li>Total numbers on each floor</li> </ul>	one	one	m.R.	
	<ul> <li>Length of hose reel hose</li> </ul>	. 30 m	yes	M.R	
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	yes.	M.R. M.R	
	Automatic fire detection and alarming system.				
	• Type of detectors	- N. H.	7		
	<ul> <li>Location of Main Panel</li> </ul>				
	<ul> <li>Location of Repeater Panel</li> </ul>			M N	
	• Alternate source of power		in the second se	and the state of t	
	Hooters' Location				
8	MOEFA	yes - N.A-	yes	M. R -N. A	
9	Public Address System.	- N.A-	- N.A -	-N.A	
10	Automatic Sprinkler System.				
IV	rationatic springer Systems	yes	yes	m.,	

contd-

Mc Donald's family Restaurant, DMRC Station, washmere Gate 1887. Della-110006.

old case

				old case
	<ul><li>Upper Floor</li><li>Sprinkler above false ceiling</li></ul>	yes. -N.A.	Jel.	M-R
11	Internal Hydrants	-N.A -	-N.A-	-N.A -
	<ul><li>Size of riser/down-comer</li><li>Number of hydrants per floor</li></ul>	-NA-	-N-A-	-NA-
	• Hose Box		one	M.A
12	Yard Hydrants.		one	MAR.
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	-N.A-	-N-A-	100
13	Pumping Arrangements.	-NA-	WiA-	77.77
2	* Ground Level		10 /11	~A-
	<ul> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> <li>Terrace level</li> </ul>	N	A	
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	40 mtes Electric	450 LPM 40 Mts	M.R.
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	and the second s	Hactric	MA
14	Captive Water Storage for fire fighting	yes	yes	ps.R
		Я		
. *	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	N.A		

cental:

Mc Donal's Family Restaurant Grand & Frist flow Dm RC 1587, Kashareli Grate Delli-110006

old cale

			otal
<ul> <li>Fire service inlet</li> <li>Access to tank</li> <li>Overhead Tank</li> </ul>	Yes	yes	m-R
Exit Signage.  Provision of Lifts.	Yel	10,000 lites	M-R M-R
Pressurization of Pressurization of Pressurization of Communication Fireman's Ground Lift Signage	f List lobby In list Car	A	
Standby power supply Refuge Area.	DG- uls	sett D.G. set	m.L
> Total Area > Location > Fire Control Room	N-	A Tolling	
<ul><li>Detector System</li><li>Fldw Switch F</li></ul>	em Panel N	-A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Receping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Mc Donald's family Restausant Glound and frist floor DMRC 15BI Kashmeli Gate Dolli Mong Signature of the Inspecting Officer Signature of the Inspecting Officer Name Name Thair via single yalow Designation Designation Assistant Division Do Central centeal)