GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No: F6./DFS/MS/GH/2012/ 2105

Dated: 12/06/12

FIRE SAFETY CERTIFICATE

Certified that the Hari Kiran Guest House located at 4220, Tel Mandi, Pahar Ganj, New Delhi-110055 comprised of Ground floor (Reception + 04 guest rooms), 1st floor(05 Guest rooms), 2nd floor (06 Guest rooms), 3rd floor (06 Guest rooms) and terrace floor (mumty, water tank and open terrace) Total 21 Guest Rooms owned / occupied by M/s Hari Kiran guest house have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 15-05-2012 in the presence of Mr. Ashok Kumar Gupta (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses with effect from 12-15-6/12-------- for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .12./.06./.1.2. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049

2. Sh. Ashok Kumar Gupta M/s Hari Kiran Guest House, 4220, Tel Mandi, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECT.	TION REPORT	quest House	4220,
1	Name & address of the building:	mandi, Paka	& Gand, Neu	Selle-110053
	Type of Occupancy			
3	Type of Care	sideme de Co.	uest House)
4	1/Platte Of pensil 3 to -	ase/Renewat		
5	Fire Safety directions Law 33	No N.A.	Date	:d:
6	Date of inspection	N.A -		8
7	Name of the Inspecting Officers: Name and designation of officers	15-05-20	12	
8	Name and designation of officers	alm vu sing	h yadan Asoft	Divisional of
	II Dim the built it			
9	Year of Construction	HShok	Kumar Guj	sta (owner)
10		2004		The state of the s
S.	Minimum Standards on fire	344-40/Adde	c. Plice (b)	It N. Delli: 9-3
No.	prevention and fire safety U/R 33	NBC/882	Provided at site	Remarks
		Requirement	en francisco de la composición dela composición de la composición dela composición de la composición d	MR/NMR
	Access to building			P.SS. ARIA
	 Road width 		4.5 Mtes	1 11.0
	• Gate width		1.50 mtes	74 /
	 Width of internal road 	-N.A-	13-1165	
2	Number, Width, Type & Arrangement of	JV.H >	-N.A-	-N.A-
	a. Number of staircases	of Exits		
	• Upper Floors			
	* Basements		one ,	m-R
	b. Width of staircases	NA -	-NA-	-NA-
				1
-	• Upper Floors		01-40N to 1.50	M M. D
	* Basements	-NA-	-N.A-	-N:1-
	c. Protection of exits			<i>7. A</i> -
	 Fire check door 	-N.A-	- N.A-	- 01 2
	 Pressurization 	-N.A-	- N.A-	-N.A-
	e. No. of continuous staircases to terrace	// // -	ALTERNATION OF THE PROPERTY OF	-10-14-
	g. Width of Corridor		92 cms to 1500	M·K.
	h. Door Size		70 cm3 x 220 cm	M.R.
2			, , , , , , , ,	r re

contd:

Hate Kikan Guest House, 4220, Telmandi, Pakar Gant, New Delki-110053

Co	mpartmentation.		Ya	8 9	
	• Fire check door	-N-A-	-NA	-NA-	
2	 Sealing of electrical shafts 	-N-A-	-N.A -	-N.A-	
0.2	• Fire Rating of shaft door	-NA-	Carter and	- N. A -	
	 Water Curtain 	-N-A-	-N.A-	-NA-	
	• Fire Dampers	-M.A -	-N.A-	-N.A-	
S	moke Management System.				
7	• Basements	30 a/c per hour	-N.A - Natural vention	- N.A-	
= ×	• Upper floors	12 a/c per hour	Natural vention	steen M. K	
1	Tire Extinguishers			A	
- 1,	 Total numbers 	_	Eight A.B.C. E cog Type	M.R.	
	• Types	-	A.B.C. E.	M.R.	
	IS marking	1SI marked	yes	M.R.	
6	First-Aid Hose Reels.				
10°0 1	 Total numbers on each floor 	one	one	M.R	
	 Length of hose reel hose 	30 m	yes	yes.	
	Nozzle diameter	5 mm	yes	yes.	
7	Automatic fire detection and alarmin	g system.			
	 Type of detectors 	= N.A			
	Location of Main Panel		/		
# .	• Location of Repeater Panel				
	Alternate source of power		/		
9.	Hooters' Location				
8	MOEFA	yes	m. yes	M. R	
9	Public Address System.	yes.	yes	m· K	
10	Automatic Sprinkler System.				
	Basement	-N.A-	-N-A-	-N.A	

contil:

Hari kiran quest Horse, 4220, Telmandi, Pahas Ganz, New Delli-11005

	Upper FloorSprinkler above false ceiling	-N.A-	- N.A-	-N.A-
11	Internal Hydrants	-N-A-	- N.A-	NA
				10-14-
	 Size of riser/down-comer Number of hydrants per floor Hose Box 	- N.A.		
12	Yard Hydrants.			
	Total number of hydrantsHose Box	- N.A		1
13	Pumping Arrangements.			
	• Ground Level			
	Discharge of main Pump	- N. A		
	> Head of Main Pump		o o	
	around of Main pump			
	main pumps	•		
	> Jockey Pump out put			
	> Jockey pump head			
	Standby Pump out put			
	> Standby Pump Head			
	> Auto Starting/ Manual			
	stopping			P, 1
	Pump House Access			jet."
	* Terrace level			
	Discharge of pump	450 LPM	(450 LPM)	
	> Head of the pump	30 mtec	7	M.K
	Power Supply	Electricity	- 30 Miles	M. P.
	> Auto Starting of pump	A	Hectriciz	MA
1	Captive Water Storage for fire fighting.	yes	yes	M.R
	 Underground tank capacity 			
. 4	> Draw-off connection	1.4	- N.A -	-N.A-

. contd:-

Hari Riran Guest nouse 4220, Telonoundi, Pakar Ganz, New Delli-110053

	Fire service inletAccess to tank	yes	yes	M.R.
	Overhead Tank capacity	yes.	yes	W-R
5	Exit Signage.	yes	Sooo litter	M·R
	Provision of Lifts. Pressurization of Lift Shaft	N. F		W-K
	Pressurization of Lift lobby Communication In lift Car			
	Fireman's Grounding Switch Lift Signage			
7	Standby power supply Refuge Area.		D.G.set	m.R
	> Total Area > Location	-N.A-	-N.A-	- N.A.
9	Fire Control Room	11.11	- N.A -	-N.A-
	Detector System PanelFlow Switch Panel	N.A. -N.A.	-N-A-	-N.A-
	PAi System PanelBatter backup	- N.A -	- N.A-	-N.A-
0	• Building Floor Plans Special Fire Protection Systems for	-W.A -	-N.A-	-N.A-
	Protection of special Risks, if any:	7. 77	- N.H -	- 10.05 -

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Hale Kilan Guest House, 4220, Telmandi, pahar Gang, New selli-1/0055 (5 Signature of the Inspecting Officer Signature of the Inspecting Officer Name (Dhason vie srigh yalow) Designation Designation Assistant Divisional Do. (cented)

Name