#### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2012/ 2112

Dated: 12/06/12

## FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Shervani Fort View located at 11, Sundar Nagar, New Delhi comprised of ground (05 Guest rooms + Reception + Dining & Drawing room), first floor (07 Guest rooms) & second floor (07 guest rooms) and was granted NOC by this department vide letter No. F.6/DFS/MS/GH/2009/1466 dated 26-05-2009. The premises was re-inspected by the officer concerned of this department on 25-05-2012 in the presence of Mr. Harish Sharma, manager of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class residential (guest house) for 19 rooms with effect from -12-106/12 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and, subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on 12/06/12 at New Delhi by.

Chief Fire Officer for Director
Delhi fire service

Copy to: -

- 1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi
- 2. The Manager, Hotel Shervani Fort View, 11, Sundar Nagar, New Delhi.

## Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

INSPECTION REPORT					
1. Name & address of the building: Holed Shervani fort view, 11 Sundar Nagar, New Delly  2. Type of Occupancy : Lodging House  3. Type of Case : Renewal  4. Details of previous NOC : Letter No. Policy Ms (4 H) 2009 (1466 Dated: 26/5 (2009))  5. Fire Safety directives letter No :  6. Date of inspection : 75/5 (2002)  7. Name of the Inspecting Officers : M.K.Chattopadhyay, ADO(HQ)  8. Name and designation of officers from the building side : Sharingh Sharma, Manager  9. Year of Construction : 1854  10. Applicant's letter No. : 14360 Addl-cp (45 (H) Daled 15/3/12)					
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	<ul> <li>Road width</li> </ul>	_	15 201	mr	
	Gate width	***		me.	
	Width of internal road			10	
2 Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	•	-		
	Upper Floors		01	MR beingold can	
	• Basements	0	-		
	b. Width of staircases				
	<ul> <li>Upper Floors</li> </ul>	-	1.25 mt	m 12 being cold con	
	<ul> <li>Basements</li> </ul>	<del></del>	_	-	
	c. Protection of exits	<u></u>	-	_	
	<ul> <li>Fire check door</li> </ul>				
	<ul> <li>Pressurization</li> </ul>				
	e. No. of continuous staircases to terrace				
	g. Width of Corridor	_	1.05mt	me	
	h. Door Size	_	0-90m1	mre	
		_	~	-	
3	Compartmentation.	Not required	-	~	
λ.	af - 05 rooms + Reception + Dr 1st floor - 07 rooms: 2nd floor - 07 rooms.	inary Executing re	פא עיל	y.	

# Hold Shervani Fort view, 11, Sundar Magar, New Delhi

	Fire check door				
	<ul> <li>Sealing of electrical shafts</li> </ul>				
	<ul> <li>Fire Rating of shaft door</li> </ul>				
	• Water Curtain				
	<ul> <li>Fire Dampers</li> </ul>				
4	Smoke Management System. Not required				
	• Basements	30 a/c per hour			
	• Upper floors	12 a/c per hour			
5	Fire Extinguishers	1000			
=	• Total numbers 06 • Types water $CO_2$ , $CO_2$	Waler CO, -3	provided	MR	
	• Types Water CO2, CO2	CO <sub>2</sub> -3	provided	MZ	
- N.S.	IS marking	ISI marked			
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	provided	MR	
	• Length of hose reel hose	30 m	provided	MR	
	Nozzle diameter	5 mm	provided	MR	
7	Automatic fire detection and alarmin	ng system.	system. Not required		
	Type of detectors	Smoke	provided	MR	
	Location of Main Panel	GF reception	provided	MR	
w:	Location of Repeater Panel		-	-	
	Alternate source of power	Required	provided	MR	
	Hooters' Location	Each floor Cosseider	provided	MR	
8	MOEFA	Not required		-	
9	Public Address System.	Not required	_	1	
10	Automatic Sprinkler System.	Not required			
	• Basement		-		
	Upper Floor	Not required	provided in waper	Me	
	Sprinkler above false ceiling	No false cuiling	-		
		A			
11	Internal Hydrants	Not required			

18

# Holel Shervann' Fort view, 11, Sundar Magar, Men Delly

/			9	
~	• Number of hydrants per floor			
9	• Hose Box			
12	Yard Hydrants. Not required	1		
	<ul> <li>Total number of hydrants</li> </ul>	01	provided	MR
	Hose Box	01	provided	Me
13	Pumping Arrangements.			
	<ul> <li>Ground Level</li> </ul>		5	
	Discharge of main Pump			
	Head of Main pump	,		
	Number of main pumps			
	Jockey Pump out put			
	Jockey pump head			
27	Standby Pump out put			0
	Standby Pump Head			
	Auto Starting/ Manual			
	stopping			
	Pump House Access			
	• Terrace level			
	Discharge of pump	_	450 LPIM	MR
	Head of the pump		35mt	MR
	Power Supply	Reguired	provided  provided	IVE
	> Auto Starting of pump	Required.	a provided	MR
14	Captive Water Storage for fire fighting.	•		5
	<ul> <li>Underground tank capacity</li> </ul>			
	Draw-off connection			
	Fire service inlet			
	Access to tank			
	<ul> <li>Overhead Tank capacity</li> </ul>	250013,	Provided & full	k) MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts. Not applicable		-	
	Pressurization of Lift Shaft	Mot requised		-
-		-		

10

# Holès Shervann' Fort view, 11, Sundar Magar, New Delha

	Pressurization of Lift lobby	Not required	-	-	
	Communication In lift Car		34		
	Fireman's Grounding Switch	Danisa	provided		
		Required	provided	MR	
	Lift Signage	Required	provided	MR	
17	Standby power supply	Required	128 KVA	MP	
18	Refuge Area. Not required				
	Total Area				
	> Location				
19	Fire Control Room				
	• Detector System Panel	Not required	provided at af reception	WIR	
	<ul> <li>Flow Switch Panel</li> </ul>	-	<u> </u>	_	
	<ul> <li>PA System Panel</li> </ul>	_	-	_	
	<ul> <li>Batter backup</li> </ul>	_	-	-	
	Building Floor Plans	-	~	-	
20	Special Fire Protection Systems for	Reguired	One ABOLY/2	MR	
5	Protection of special Risks, if any:	V	provided near & pomel'		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name (M.K. CHATTOPADHYAY)

Designation: - Assistant Divisional Officer

1-7 m.s.000