GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No F 6/DFS/MS/2012/EH/2/39

Dated 14/06/12

FIRE SAFETY CERTIFICATE

Certified that the "Milano" Restaurant situated at First floor (Ground floor has shops) located at M-89 & M-90, Connaught Circus, New Delhi was granted NOC by this department vide letter No F6/MS / DFS / EH / 2009 / 1177 dated 01.05.2009. The premises was re-inspected by the officer concerned of this department on 05.06.2012 in the presence of Mr. Pandey (G.M) and found that the Restaurant have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group D Assembly Building of with effect from 1.44 / 6.6 / 1.4... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on....14./s.6./12.... at New Delhi by.

Director
Delhi Fire Service

Copy to: -

- 1. The Medical Officer of Health, NDMC, Palika Kendra, New Delhi.
- 2. The Owner/Partner, Milano" Restaurant at M-89 & M-90, Connaught Circus, New Delhi

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Name & address of the building: "Milano" Restaurant, M-89 & M-90, Connaught Circus, 1.

New Delhi.

Type of Occupancy 2.

: Assembly

Type of Case 3.

: Renewal

Details of previous NOC 4.

: - F6/MS/DFS/EH/2009/1177 Dated 01.05.2009

5. Fire Safety directives Letter No.: N/A

Date of inspection 6.

: 05.06.2012

7.

Name of the Inspecting Officer: DO Atul Garg & ADO D.S. Yadav

Name and designation of Officer 8.

from the building side

: Mr. Pandey (G.M.)

Year of Construction 9.

: Before 1968

10. Applicant's/ NDMC letter No. : MOH/D/1190/CSI(Lic)SI-I Dated 03.05.2012

S	Minimum standards on fire	BBL	Provided at	Remarks MR/NMR
No	prevention and fire safety U/R 33	Requirements	site	
1.	Access of building			1.
	Road width	N/A	12 m	MR
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangeme	ents of exits		
	a. Number of staircases			
	 Upper floors 	02	02	MR
	Basements	N/A	N/A	N/A
	b. Width of staircases	-	-	-
	Upper floors	N/A	N/A	N/A
	Basements	N/A	N/A	N/A
	c. Protection of exits			7
	Fire check door	N/A	N/A	N/A

"Milano" Restaurant, M-89 & M-90 C.C. New Delhi

Old Case

	Pressurization	N/A	N/A	N/A	
	c. No of continuous staircase	01	01	MR	
	to terrace	01	01	IVIK	
	d. Width Of Corridor	N/A	N/A	N/A	
	e. Door Size	N/A	N/A	N/A	
3.	Compartmentation	1111	1		
	Fire check door	N/A	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	N/A	
	• Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4.	Smoke managements System				
••	Basements	N/A	N/A	N/A	
	Upper floors	12 a/c per hour	YES	MR (Fans Provided)	
5.	Fire Extinguishers				
J.	Total numbers	8	YES	MR	-
	Street (published Space Records) (Space ACTIVE COLOR Space Records Space)	WT, CO ₂ , DCP	YES	MR	
	• Types	W1, CO2, DC1	1 LS	TVIIC	
	IS marking	YES	YES	MR	
6.	First – Aid Hose Reels				
	Total numbers	02	02	MR	
	Length of hose reel hose	30 m	30 m	MR	
	Nozzle diameter	5 mm	5 mm	MR	
7.	Automatic fire detection and alarming				
,.	Type of detectors	Smoke	YES	MR	
	Location of Main Panel	Public Area	YES	MR	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	YES	YES	MR	
	Hooters' Location	9800 (ASS)			
	Tiooters Location	Public Area	YES	MR	
8.	MOEFA	YES	YES	MR	
9.	Public Address System	YES	YES	MR	
10.	Automatic Sprinkler System				
	Basements	N/A	N/A	N/A	
	Upper Floor	YES	YES	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants	11//1	11//1	11/12	
11.	Size of riser/down- comer	100 m	100 m	MR	
	Number of hydrants	02	02	MR	
	Hose Box	02	02	MR	
12		02		11111	
12.	Yard Hydrants	N/A	N/A	N/A	
	Total number of hydrants Hass Pay	N/A N/A	N/A	N/A N/A	
	Hose Box	1N/A	IN/A	11/71	

"Milano" Restaurant, M-894 M-90, C.C. New Delhi

13.	Pumping Arrangements			
10.	Ground Level			
	 Discharge of main pump 	N/A	N/A	N/A
	Head of main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	 Auto Staring/Manual stopping 	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace Level	N/A	IN/A	IVA
	Discharge of pump	000 T		
	Discharge of pump	900 Lpm 180 Lpm	N/A	N/A
	Head of the pump	40 m	YES	MR
	Power supply	YES	YES	MR
	Auto starting of pump	YES	YES	MR
14.	Captive water Storage for fire figh	nting		
	Under ground tank capacit		N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	> Fire service inlet	YES	YES	MR
	> Access to tank	N/A	N/A	N/A
	 Overhead Tank capacity 	15000 Ltr.	15000 Ltr.	MR
15	Exit Signage	YES	YES	MR
16.	Provision of Lifts			
	Pressurization of Lift Shafe	t N/A	N/A	N/A
	Pressurization of lift lobby		N/A	N/A
	Communication in lift Car		N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	YES	YES	MR
18.	Refuge Area			
	> Total area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire control room			
	> Detector system panel	N/A	N/A	N/A
	> Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
	> Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A

"Milano" Restaurant, M-89 4 M-90 C.C. New Delhi

Old care -

20.	Special Fire Protection Systems for	N/A	N/A	N/A
	Protection of special Risks, if any;		,	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name

Name O.S. yadav

Designation

Designation