GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 2225

Dated: 21/06/12

FIRE SAFETY CERTIFICATE

Certified that the President (Comfort Inn) Guest House located at 4/23-B, Asaf Ali Road, New Delhi-110002 comprised of basement (office & store), ground floor (reception + restaurant + kitchen), mezzanine floor (03 rooms for store purpose), 1st floor (09 guest rooms + 04 office/store room), 2nd floor (09 guest rooms + 04 office + store rooms) Total 29 nos rooms including 18 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1446 dated 25-05-2009. The premises was re-inspected by the officer concerned of this department on 12-06-2012 in the presence of Sh. Vinay Kumar and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 29 nos rooms including 18 guest rooms with effect from 2.1/2.26/...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 21.1.06.1.2. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. M/S President (Comfort Inn) Guest House located at 4/23-B, Asaf Ali Road, New Delhi-110002

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

JNSPEC"	LION REPORT	Therefore a gradual and the articles are a gradual and a g	
	President	Comfasti Inn) Guests una
When the party of	23-8, Asab	f Ali Road,	New Selli-
Type of Care	esidential (Quest House	2.)
. I VEW	asc/Renewal		
5. Fire Safety directives letter No :	No F6/DFS/MS/	GH/2009/144 Date	25-05-200
. W. Lidle Of ingreation	The state of the s		
7. Name of the Inspecting Officers: 8. Name and designation of officers from the building of the Inspection	-06-2012	The second secon	Secretary of the Control of the Cont
Name and designation of officers	Plasm vie s	ingh yaday (12 1
from the building side		()	720)
O. Year of Construction	Shri vinay	Kumaz.	
10. Applicant's letter No.	NA -		
	NIL	109 08 2012	the desired and the second are a second and a second and the secon
Minimum Standards on fire	NBC/BBL	Provided at site	old
prevention and fire safety U/R 33	Requirement	and at site	Remarks
Access to building			MR/NMR
Road width			
• Gate width		18 mtss	M.R
• Width of internal road	-N.A-	- N.A-	-N.A-
The second secon	-N.A -	- N.A -	- N.A -
Number, Width, Type & Arrangement	of Exits	7	No fil -
a. Number of staircases		The second secon	
* Upper Floors		02	
* Basements			
b. Width of staircases		Two stars case	M. R
* Upper Floors		ain ctair 1.17 mt	2/14
* Basements	- 8	ainstail 1.17 Mto 1.	testace M.R
	A	1.25 M & 1.05/ Ramp = 1.16 MZ	its M.R
c. Protection of exits		100 16 16 MC	
• Fire check door	-N.A-	_ N.A -	- 11.0 -
n Pressurization	-N.A -	- N.O -	- 21.0
c. No. of continuous staircases to terrace	//	7. 77	N'01 -
g. Width of Corridor	-N.A -	- 10	
h. Door Size	-N.A -	-N.A-	-N.A-
	1 1 -	-N.B	-N.A-

The President (comfort Inn) Guest House, 4/23-B, Asaf Ali Road, New Delli-110002.

Co	mpartmentation.		Eq.	
	• Fire check door	N-A		An Andrew Market and areas property and a second property of the sec
	 Sealing of electrical shafts 			
	• Fire Rating of shaft door			
	 Water Curtain 			
	* Fire Dampers			
Si	moke Management System.			
	• Basements	30 a/c per hour	ves Expense	far M
	• Upper floors	12 a/c per hour	yes estatest , vatural ventilation	M.K
Ji	ire Extinguishers			To the state of th
	 Total numbers 		Ten (10)	m.R
	Types		ABC & CO2Type	m.R
	• IS marking	ISI marked	yes.	M.R
j J	First-Aid Hose Reels.	•		
	 Total numbers on each floor 	one	one	m·R
	 Length of hose reel hose 	30 m	yes	m.R
	Nozzle diameter	5 mm	yes.	M.R.
7	Automatic fire detection and alarmin	g system.	and an amount to a second the contract of the	
	 Type of detectors 	MA		
	 Location of Main Panel 			
	• Location of Repeater Panel		/-	and the second s
	• Alternate source of power			
	Hooters' Location			
8	MOEFA	yes	Provided.	m.R
9	Public Address System.	yel.	Provided.	m.K.
10.	Automatic Sprinkler System.			M·R contd

The President (confort dan) Guest House 4/23-B, Asab Ali Road, New Delli-1/2002

	• Upper Floor			
	Sprinkler above false ceiling		Provided	N. A
1	Internal Hydrants	-N.A.	Provided -N.A-	n.A
	Size of ring / 1		the second secon	M.A
	Size of riser/down-comer	100 MM		
and a company	Number of hydrants per floor Hose Box		100 m.m.	m. A
	XOU DOX		Me	m. A
12	Yard Hydrants.	Yes	yel	and the same of th
		•		m.R
	* Total number of hydrants * Hose Box	-N.A-		***
13	Pumping Approx	-N.A-	-N.A-	- MA-
	Pumping Arrangements.	The second secon	-NA-	- NA -
	Ground Level			
2	Thomas of main Pump	-N.A		
	Head of Main pump		. 1	
	> Number of main pumps		The state of the s	
	> Jockey Pump out put			
	> locker w			
	. "Ockey pump head			
	Standoy Pump out put			
	> Standby Pump Head			
t 102 y	> Auto Starting/ Manual			the state of the s
	stopping	•	The second secon	1) (c) (c) (d) (c) (d)
	> Pump House Access			
	* Terrace level			
	M. D'	air hão IPM	Main 450 CPM	and the second s
	Discharge of pump		Tockey 180 LPM	M· R
	> Head of the pump	40 MES	40 mtsc	M-K
2 1	Power Supply	Lec teicity	Becterit	
	Auto Starting of pump	yes		MA
4 (aptive Water Storage for fire fighting.		yes	m. R
	• Underground tank capacity			Observed and the second management of
	> Draw-off connection		Provided	m.R.
	our confidential	Yes	Provided	MI O

the President (compet Inn) quest house 4/23-B, Araf Ali Road, New Selle'-110002

	Fire service inlet Access to tank	yes	yes.	
	Overhead Tank capacity	Yes	yes.	M.K
	Exit Signage,		30000 lite	es m.k
	rovision of Lifts.	Yes	Provided.	M. D
	Pressurization of Lift Shaft	one list	GF to 2nd floor.	
	Pressurization of Lift lobby	-NA-	-MA-	-N.A.
	Communication In lift Car	-N-A-	-N.A	-NA-
	Fireman's Grounding Switch	yes	yes.	M.R.
	* Lift Signage	Yes	Yes	M.R
		yes.	yes.	- State of the contract of the
	Cefuge Area.	yes	yes. D.G. set	m.R.
	and the same of th	And the second s		M·R.
	> Total Area > Location	- N.A		
11	ire Control Room			
	the state of the s	and the second s		San to the
	Detector System Panel	N.A		
	* Flow Switch Panel			
	* PAi System Panel	-		
	* Balter backup	,		
. 5	* Building Floor Plans			
1,3	pecial Fire Protection Systems for	- N. A -		
	rotection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Ecoping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

	The President	t (confect on	ed per se	
M				(فريم
Signatu Name	ure of the Inspecting Officer	Sign	nature of the Inspecting	Officer
Designa		,	gnation A Do Coc.	
	Do Coenteal) III	56/12		