GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 2 344

Dated: 29/6/13

FIRE SAFETY CERTIFICATE

Certified that the Saya Dx. Guest House located at 2213, Chuna Mandi, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 01 office + 02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor) and 4th floor (staff kitchen + 01 staff room) total 14 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1437 dated 22-05-2009. The premises was re-inspected by the officer concerned of this department on 20-06-2012 in the presence of Sh. Harish Arora (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 14 guest rooms with effect from ...27/.s.c./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 29.(0.6).1.2. at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Sh. Harish Arora M/s Saya Dx. Guest House, 2213, Chuna Mandi, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

1. Name & address of the building: Saya Dx. Guest House, 2213, Chuna Mandi,

Pahar Ganj, New Delhi-110055

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F6/DFS/MS/GH/2009/1437 Dated 22-05-2009

5. Fire Safety directives Letter No.: N/A

6. Date of inspection

: 20-06-2012

7. Name of the Inspecting Officer: Sh. D.S. Yadav

A.D.O.

8. Name and designation of Officer

from the building side

: Sh. Harish Arora

(owner)

9. Year of Construction

: N/A

10. Applicant's letter No.

: NIL Dated 20-06-2012

| S | Minimum standards on fire | BBL | Provided at | Remarks MR/NMR | |
|--|--|--------------|-------------------|----------------|--|
| No | prevention and fire safety U/R 33 | Requirements | site P. S.S Area | Old Case | |
| 1. | . Access of building | | | | |
| | Road width | N/A | N/A | N/A | |
| | Gate width | N/A | N/A | N/A | |
| | Width of internal road | N/A | N/A | N/A | |
| 2. Number, width, Type & Arrangements of exits | | | | | |
| | a. Number of staircases | | | | |
| | • Upper floors . | | 01 | N/A | |
| | Basementsb. Width of staircases | N/A | N/A | N/A | |
| e. | • Upper floors | | 84 cms. To 92 cms | MR old Co | |
| | • Basements | N/A | N/A | N/A | |
| | c. Protection of exits | | | | |
| | Fire check door | N/A | N/A | N/A | |
| | Pressurization | N/A | N/A | N/A | |

contal:

Saya Dr. Grest House, 2213, Chuna Mandi, Parter Grates, New Delly

| | d. No of continuous staircase | | | | | |
|------|---|-----------------|---------------------|---------------------------------------|--|--|
| | to terrace | | 01 | MR | | |
| | to terrace | | | | | |
| | e. Width Of Corridor | N/A | N/A | N/A | | |
| | f. Door Size | N/A | N/A | N/A | | |
| 3. | Compartmentation | 14/11 | 11/11 | 1,112 | | |
| ٥. | Fire check door | | | · · · · · · · · · · · · · · · · · · · | | |
| | The check door | N/A | N/A | N/A | | |
| | • Sealing of electrical shafts | N/A | N/A | N/A | | |
| | Fire Rating of shaft door | N/A | N/A | N/A | | |
| | Water Curtain | N/A | N/A | N/A | | |
| | Fire Dampers | N/A | N/A | N/A | | |
| 4. | Smoke managements System | 20 -/- 1 | | | | |
| | Basements | 30 a/c per hour | N/A | N/A | | |
| | Upper floors | 12 a/c per hour | Natural ventilation | MR | | |
| 5. | Fire Extinguishers | | | | | |
| | Total numbers | | | | | |
| | 2000 200 | | 10 | MR | | |
| | • Types | | Water Co2 & D.C.P. | MR | | |
| | IS marking | ISI marked | Provided | MR | | |
| 6. | First – Aid Hose Reels | | | | | |
| | Total numbers on each floor | | 01 | MR | | |
| | • Length of hose reel hose | 30 M | Provided | MR | | |
| Sal. | Nozzle diameter | 5 mm | Provided | MR | | |
| 7. | Automatic fire detection and alarming system | | | | | |
| | Type of detectors | N/A | N/A | N/A | | |
| | Location of Main Panel | N/A | N/A | N/A | | |
| - | Location of Repeater Panel | N/A | N/A | N/A | | |
| | Alternate source of power | N/A | N/A | N/A | | |
| | Hooters' Location | N/A | N/A | N/A | | |
| 8. | MOEFA | N/A | N/A | N/A | | |
| 9. | Public Address System | Yes | Provided | M/R | | |

cental.

Saya DR. Guest House, 2213, Chung Mandi, Pakar Gary, New Pelri

| 3. | Automatic Sprinkler System | | Ÿ | | | |
|-----|---|----------|------------------------|-------|--|--|
| 1 | Basements | 0 | | | | |
| | Basements | N/A | N/A | N/A | | |
| | Upper Floor | N/A | N/A | N/A | | |
| 11. | • Sprinkler above false ceiling Internal Hydrants | N/A | N/A | N/A | | |
| | Size of riser/down- comer | | | | | |
| | Number of hydrants per | N/A | N/A | N/A | | |
| | floor | N/A | N/A | N/A | | |
| 12. | Hose Box Yard Hydrants | N/A | N/A | N/A | | |
| | Total number of hydrants | | | | | |
| | Hose Box | N/A | N/A | N/A | | |
| | | N/A | N/A | N/A | | |
| 13. | Pumping Arrangements | | | 11/11 | | |
| | Ground Level | | | | | |
| | Discharge of main pump | N/A | N/A | N/A | | |
| | Head of main pump | N/A | N/A | N/A | | |
| | Number of main pumps | N/A | N/A | N/A | | |
| | Jockey pump out put | N/A | N/A | N/A | | |
| | Jockey pump head | N/A | N/A | N/A | | |
| | Standby Pump out put | N/A | N/A | N/A | | |
| | Standby Pump Head | N/A | N/A | N/A | | |
| | Auto Staring/Manual stopping | N/A | N/A | N/A | | |
| | Pump House AccessTerrace level | N/A | N/A | N/A | | |
| | Discharge of pump | | 225 LPM | MR | | |
| | > Head of the pump | 30 Mtrs. | 30 Mtrs. | MR | | |
| | ➤ Power supply | Electric | Electric | MR | | |
| | ➤ Auto starting of pump | | Switch provided at G.F | MR | | |

Saya Dx. Gyest House, 2213, Chuna Mandi, Pahar Gany, New Delhi.

| | ** 1 | >T/A | 27/4 | NT/A | | |
|-----|--|------|------------|------|--|--|
| | Under ground tank capacity | N/A | N/A | N/A | | |
| | > Draw of connection | N/A | N/A | N/A | | |
| | Fire service inlet | N/A | N/A | N/A | | |
| | > Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | | 2500 Ltrs. | MR | | |
| 15 | Exit Signage | Yes | Provided | MR | | |
| 16. | Provision of Lifts | | | | | |
| | > Pressurization of Lift Shaft | N/A | N/A | N/A | | |
| | Pressurization of lift lobby | N/A | N/A | N/A | | |
| | Communication in lift Car | N/A | N/A | N/A | | |
| | Fireman's Grounding Switch | N/A | N/A | N/A | | |
| | ➤ Lift Signage | N/A | N/A | N/A | | |
| 17. | Standby power supply | YES | Provided | MR | | |
| 18. | Refuge Area | | | 0 | | |
| | > Total area | N/A | N/A | N/A | | |
| | > Location | N/A | N/A | N/A | | |
| 19. | Fire control room | | | | | |
| | > Detector system panel | N/A | N/A | N/A | | |
| | Flow Switch Panel | N/A | N/A | N/A | | |
| | PA System Panel | N/A | N/A | N/A | | |
| | ➤ Batter backup | N/A | N/A | N/A | | |
| | Building Floor Plans | N/A | N/A | N/A | | |
| 20. | Special Fire Protection Systems for Protection of special Risks, if any; | N/A | N/A | N/A | | |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Service Rules 2010/issue shortcomings 7as noted serial numbers

contal:

Saya Dr. Grusst House, 2213, Chuna Mandi, Pathar Ganj, Hew Pelhi.

Signature of the Inspecting Officer

Name

Designation

86/12

Signature of the Inspecting Officer

Name D. S. yadav.

Designation Assistant Divisional
Obticel
(central)