GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2012/ 2351

Dated: 03/07/12

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Saka located at 782, Motor Market, Jama Masjid, Delhi comprised of ground (Commercial use), first floor (04 guest rooms + reception), second floor (04 guest rooms + 01 staff room) and third floor (04 guest rooms) was granted NOC by this department vide letter No. F.6/DFS/MS/GH/09/2373 dated 31-07-2009. The premises was re-inspected by the officer concerned of this department on 23-06-2012 in the presence of Mohd. Naseem, Manager of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class **residential (guest house)** with effect from $\frac{(31-32-1)(1-1)}{(1-1)(1-1)}$ for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on -0.3/02/12 at New Delhi by.

Chief Fire Officer for Director Delhi fire service

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

2. The Manager, M/s Hotel Saka, 782, Motor Market, Jama Masjid, Delhi

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1	1. Name & address of the building: Shaka Guest House, 782, Molos mkt, James					
	· ·	ging House		Delha .		
3	3. Type of Case : New C	ase/Renewal				
4. Details of previous NOC : Letter No. F6 DFs Ms GH 09 2373 Dated: 31 3						
5	5. Fire Safety directives letter No :					
6	501.1					
7						
8	3. Name and designation of officers					
	from the building side :	ld. Naseem	n, Manager			
ç	O. Year of Construction :	1967				
1	0. Applicant's letter No. : 31	275/Addlicp	Lic (H) daled	28/3/2012		
S.	Minimum Standards on fire	NBC	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Requirement		MR/NMR		
1	Access to building					
	Road width	Sb/ area	24 mt	me		
	Gate width		Directlyaceersbi	k ma		
	 Width of internal road 		Ison the rond			
		_				
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		,	6		
	 Upper Floors 	spl area	01	on a beingol		
	 Basements 					
	t. Width of staircases			_		
	• Upper Floors	stol area		MR		
	 Basements 		2 -			
	c. Protection of exits	2	9	=		
	• Fire check door	Not required				
	 Pressurization 	Not applicable				
	e. No. of continuous staircases to terrace	- Spouchole	01	me beingold		
	g. Width of Corridor			Caser		
	h. Door Size	-	2 00 1-	m R		
			9	MR		
			•			
3	Compartmentation.	Not required	*	-		

GF- Commercial use.

Ist floor - 04 Guest rooms of reception

and floor - 04 Guest rooms + 01 Staff rooms

3rd floor - 04 Equest rooms.

9

	• Fire check door					
	 Sealing of electrical shafts 					
	 Fire Rating of shaft door 	9				
	Water Curtain					
	• Fire Dampers					
4	Smoke Management System. Not					
	• Basements	30 a/c per hour				
	Upper floors	12 a/c per hour				
5 Fire Extinguishers						
	• Total numbers ${\mathcal{O}}_6$	water Coz-3	Provided	PMR		
	· Types, Walir Co, Co	CO2 -3	Provided	mR		
	IS marking	ISI marked	poonided	mp		
6	First-Aid Hose Reels.	4				
	Total numbers on each floor	Ol at 1st	provided	MR		
	 Length of hose reel hose 	30 m	provided	MR		
	 Nozzle diameter 	5 mm	provided	MR		
7	• Nozzle diameter 5 mm provided Mp. Automatic fire detection and alarming system. Not required:					
	Type of detectors					
	 Location of Main Panel 					
	 Location of Repeater Panel 					
	Alternate source of power					
	^			e e		
	Hooters' Location					
8	MOEFA	Not required		-		
9	Public Address System.	Required	Provided	MR		
10						
	• Basement	,				
	Upper Floor					
0.00	The state of the s					
Walter of the Control	 Sprinkler above false ceiling 					
11		sequired.				

1

Saka Cenest Honse, 782, molor met, Jama magjid Delle Number of hydrants per floor Hose Box required' Not 12 Yard Hydrants. Total number of hydrants Hose Box 13 **Pumping Arrangements.** Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level 225 LPM 225 LPM MR Discharge of pump 30mt 30m/ MR Head of the pump Power Supply Switch printer Auto Starting of pump MR near reception 14 Captive Water Storage for fire fighting. Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 25 00 /h boov i'deel MR

Required

15

16

Exit Signage.

Provision of Lifts.

Pressurization of Lift Shaft

19

MR

boovided

Saka Couest House, 782, Molor MKt, Jama Musfid, Delbi-6

	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 			
17	Standby power supply	NO -		-
18	Refuge Area.	quired.		
	Total Area			
	> Location			
19	Fire Control Room Not	required!		
	Detector System Panel	,		
	Flow Switch Panel			
	PA System Panel	9		
	Batter backup			
	 Building Floor Plans 			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One Co lyh fire extensuether povorded kear 9/panee	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name (M.K.CHATTOPADHYAY)

Designation ADO (HQ)