## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 27 44

Dated: 27/07/12

## **FIRE SAFETY CERTIFICATE**

Certified that the Avtar Guest House located at 3425, D.B.G. Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + office), Mezzanine floor (06 guest rooms + 03 store + 01 office), 1<sup>st</sup> floor (10 guest rooms) 2<sup>nd</sup> floor to 3<sup>rd</sup> floor (11 Guest rooms at each floor) and terrace floor (kitchen for staff +staff room {sealed}) Total 38 was granted NOC by this department vide F6/DFS/MS/GH/2009/1840 dated 23-06-2009. The premises was re-inspected by the officer concerned of this department on 19-07-2012 in the presence of Sh. Govind (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 38 guest rooms with effect from .2.7./....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 2.7/.02//... at New Delhi by.

CHIEF FIRE OFFICER
DELHJ FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049.
- 2. M/s Avtar Guest House, 3425, D.B.G. Road, Pahar Ganj, New Delhi-110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Avtar Guest House, 3425, D.B.G. Road, Pahar Ganj, New Delhi.

(Old Case) (PSS Area)

**INSPECTION REPORT** 

1. Name & address of the building: Avtar Guest House, 3425, D.B.G. Road,

Pahar Ganj, New Delhi-110055

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F6/DFS/MS/GH/2009/1840 Dated 23-06-2009

5. Fire Safety directives Letter No.: N/A

6. Date of inspection

: 19-07-2012

7. Name of the Inspecting Officer: Sh. D.S. Yadav

A.D.O.

8. Name and designation of Officer

from the building side

: Sh. Govind (manager)

9. Year of Construction

: N/A

Applicant's Aletter N

No	Minimum standards on fire	BBL	Provided at	Remarks MR/NI	MD
	prevention and fire safety U/R 33	Requirements	site	Remarks MR/M	VIK
	Access of building	requirements	Site		
	Road width	N/A	8,8,8		
			More than 18	MES M.R	
	Gate width	N/A	N/A	N/	A
	<ul> <li>Width of internal road</li> </ul>				
		N/A	N/A	N/	A
2.	Number, width, Type & Arrangeme	nts of exits		1, , ,	
	a. Number of staircases				
	• Upper floors	01	02	MR	
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A	
	b. Width of staircases				
	• Upper floors	·80 M tags	1.20 mus. & 2 staircase G.F. to		
			1 <sup>st</sup> floor 1 mtr.		MR
	<ul> <li>Basements</li> </ul>	N/A	N/A		N/A
	c. Protection of exits				
	<ul> <li>Fire check door</li> </ul>				
		N/A	N/A	N/A	
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A	
	d. No of continuous staircase	0.1			
	to terrace	01	01	MR	
	e. Width Of Corridor	N/A	N/A	* T / A	
16	f. Door Size	N/A	N/A N/A	N/A	
	Compartmentation	7.17.1	1 1/ / / 1	N/A	
	• Fire check door	N/A	N/A	3.7/4	
	<ul> <li>Sealing of electrical shafts</li> </ul>	11/71	IN/A	N/A	
		N/A	N/A	N/A	
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A	

	Avtar Guest House, 3425, D.B.G. Road, Pa			(Old Case) (PSS Area)
	Water Curtain	N/A	N/A	N/A
	Fire Dampers			
	The Dampers	NI/A	27/1	
4.	Smoke managements System	N/A	N/A	N/A
	Basements	30 a/c per		
		hour	N/A	27/1
	<ul> <li>Upper floors</li> </ul>	12 a/c per	Natural Natural	N/A
		hour	ventilation	MD
5.	Fire Extinguishers		Ventuation	MR
	<ul> <li>Total numbers</li> </ul>			
		/0	10	MR
	• Types	• • • • • • • • • • • • • • • • • • • •	Water Co2 &	IVIIC
			D.C.P.	MR
	<ul> <li>IS marking</li> </ul>			IVIIC
6.	Pine Ailty D	ISI marked	Provided	MR
0.	First – Aid Hose Reels			TVIIC
	<ul> <li>Total numbers on each floor</li> </ul>	one		
	a Laurett and	······	01	MR
	<ul> <li>Length of hose reel hose</li> </ul>	20.3.5		
	No-1-1	30 M	Provided	MR
	Nozzle diameter	_		
7.	Automatic fire detection and al.	5 mm	Provided	MR
7.	Automatic fire detection and alarmin  Type of detectors			
	• Type of detectors	N/A	N/A	N/A
	<ul> <li>Location of Main Panel</li> </ul>	27/4		
	Location of Wain Panel	N/A	N/A	N/A
	Location of Repeater Panel	DT/4		
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	Alternate source of power	NT/A	2.24	
	riternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	NI/A	
8.	MOEFA		N/A	N/A
9.	Public Address System	Yes	Provided	MR
10.	Automatic Sprinkler System	Yes	Provided	MR
	Basements	N/A	27/1	
	Upper Floor	N/A N/A	N/A	N/A
	Sprinkler above false ceiling	N/A N/A	N/A	N/A
11.	Internal Hydrants	1 N/ /1	N/A	N/A
	Size of riser/down- comer	N/A	27/:	
	Number of hydrants per	N/A N/A	N/A	N/A
	floor	IN/A	N/A	N/A
	Hose Box	N/A	<b>N</b> T/A	
12.	Yard Hydrants	IN/A	N/A	N/A
	Total number of hydrants	N/A	37/1	
	Hose Box		N/A	N/A
13.	Pumping Arrangements	N/A	N/A	N/A
	Ground Level			
	Discharge of main pump	N/A		1
	or main pump	IN/A	N/A	N/A
0.	Head of main pump	N/A	3.774	
	man partip	IN/A	N/A	N/A
	Number of main pumps	N/A	<b>3.</b> 774	
, a	Pampo	11/14	N/A	N/A
	Jockey pump out put	N/A	NT/A	abada So ka Lisada de
		11/1	N/A	N/A
1 - 7-20	Jockey pump head	NI/A	TA door	is to entertain and a soft

ò

	88 J.		The state of the s		(Old Case) (PSS Area)
	7	Standby Pump out put	N/A	N/A	11.2719 1.3111.011.011.011
		e e	N/A	N/A	N/A
	7	<ul><li>Standby Pump Head</li><li>auto Staring/Manual</li></ul>	D.	1771	N/A
	7	stopping	N/A	N/A	N/A
7			NI/A	-	
1		Pump House Access	N/A	N/A	N/A
		Terrace level			
		Discharge of pump	2.2.5.4.9.1	225 LPM	0
		Discharge of pump		223 LFIVI	MR
		Head of the pump	30 Mtrs.	30 Mtrs.	MR
		-			IVIIC
		Power supply	Electric	Electric	MR
	-0 4	A 4 - 4 - 1 - 2		Cruit 1	
	1.4	Auto starting of pump	••••••••	Switch provided at G.F	MR
	14.	Captive water Storage for fire fighting		ut O.1	
	1	Under ground tank capacity	N/A	N/A	N/A
		> Draw of connection	27/		IVA
		Braw of connection	N/A	N/A	N/A
		Fire service inlet	N/A	27/4	
			IN/A	N/A	N/A
		Access to tank	N/A	N/A	DI/A
		• Ometa 177	N. 100 1		N/A
		Overhead Tank capacity	2500 Lites	2500 Ltrs.	MR
	15	Exit Signage	X/		
			Yes	Provided	MR
	16.	Provision of Lifts			
		Pressurization of Lift Shaft	N/A	N/A	NT/A
		Pressurization of lift lobby		11/11	N/A
		Pressurization of lift lobby	N/A	N/A	N/A
		Communication in lift Car	27/4		
			N/A	N/A	N/A
		Fireman's Grounding	N/A	N/A	,°
		Switch		IN/A	N/A
		Lift Signage	N/A	N/A	N/A
	17.	Standby power supply	VEC		1771
L			YES	D.G. Set	MR
-	18.	Refuge Area			
		> Total area	N/A	N/A	NI/A
		> Location			N/A
		Location	N/A	N/A	N/A
	19.	Fire control room			
		Detector system panel	N/A	DI/A	
			11/2	N/A	N/A
		Flow Switch Panel	N/A	N/A	DI/A
		➤ PA System Panel		- 11.4.4	N/A
	4.	Zir System Fanel	N/A	N/A	N/A
		➤ Batter backup	NI/A		
		-	N/A	N/A	N/A
		➤ Building Floor Plans	N/A	N/A	27/
L				11/14	N/A

20.	Avtar Guest House, 3425, D.B.G. Road, Pah Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	(Old Case) (PSS Area)  N/A
	racection of special Risks, if any;			
-	The fire protection systems provided in to find the fire protection.	the building were	test checked and for	ound functional at the time
				the time time
ŀ	Keeping in view the substantial compl	ionee of the min		
I s	Keeping in view the substantial compleafety required under the rules it is reco	iance of the minimumended to gran	imum standards o t Fire Safety Certi	<b>a</b>
I s I	7-11.	iance of the min mmended to gran lissue shortcon	t Fire Safety Certi	n fire prevention and fire ficate under rule 35 of the
I s I	7-11.	innended to gran	t Fire Safety Certi	n fire prevention and fire ficate under rule 35 of the
I s I	7-11.	innended to gran	t Fire Safety Certi	n fire prevention and fire ficate under rule 35 of the

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Deason vie single yelow.

Designation

Designation Assistant Divisional offices