## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 2752\_

Dated: 27/07/12

## **FIRE SAFETY CERTIFICATE**

Certified that the De Hollywood Dx. Guest House, 8/6, 2157, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi-110055 comprised of basement (Storage) ground floor (Shops), 1<sup>st</sup> floor (08 Guest rooms + Reception + Office), 2<sup>nd</sup> floor (Office), 3<sup>rd</sup> floor (10 Guest rooms) 4<sup>th</sup> floor Sealed by MCD, Total 18 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1727 dated 11-06-2009. The premises was re-inspected by the officer concerned of this department on 19-07-2012 in the presence of Sh..Sunil Kumar Gulati (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 18 guest rooms with effect from 2.7./ 2.7.....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 27/22/12... at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049.
- 2. M/s De Hollywood Guest House, 8/6, 2157, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi-110055.

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	ECTION REPORT	od Ix, 8/6,	2/52				
1	Name & address of the building	20 //oeg	- 4, 1/0,	217F,				
. 2	Type of Occupancy	Deskoanaku G	supta Road,	Pa Ras Gan				
3	Type of C-							
4	A David Conewal							
5	Fire Safety diagrams:	er No. F6/m.s/ D.	FS/GH/2000 Date	d. 11-06-0				
6	Data of:	the street of th		7				
7	in this pection							
8	Name of the Inspecting Officers:	Dharm viz si	ish wadar.	The second of th				
0	Participat of OfficeL2	그 그렇게 되자 그 바이트 어느리는 날						
	from the building side	She sunil k	Lumas Gula	ti Commos				
	or constituction.	- N.A -		- Carree				
	). Applicant's letter No.	19942/Addl.c.	Phie last .	A 22				
S.	otanual us on the	· NBC	Provided at site					
No.	prevention and fire safety U/R 33	Requirement	a tovided at site	Remarks				
1	Access to building	and an amount	and the second s	old case				
	<ul> <li>Road width</li> </ul>	N.A		PSS. ALSO				
	• Gate width	the second section of the second section s	NA	N.A				
	• Width of internal road	N.A	N.A	N.A				
2		N.A	N.A	N.A				
Le manuel de la companya della companya della companya de la companya de la companya della compa	Number, Width, Type & Arrangeme	nt of Exits						
	a. Number of staircases							
	• Upper Floors	one.	on e					
	• Basements	one	one	m·R				
	b. Width of staircases		one	M·K				
	• Upper Floors	•		B - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
	• Basements		120 cms 10 1220	B W.E				
			110 cmg	M.R				
	c. Protection of exits							
•	Fire check door	N.A	N.A	N.O				
	• Pressurization	NA	NA	NA				
	e. No. of continuous staircases to terrac	ce one	one	M.R				
2.	g. Width of Corridor	N.A	NA	NA				
				1 01				

contd:

De Hollywood Greet House, 8/6, Degh Bandher Grepta Road, Pakar Grant, New Delli-110055

old

		1		PSS ALEA	
Cor	mpartmentation.				
	<ul> <li>Fire check door</li> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> </ul>	n	(· A		
	<ul><li>Water Curtain</li><li>Fire Dampers</li></ul>				
Sm	oke Management System.		The second secon	and the second s	
	<ul><li>Basements</li><li>Upper floors</li></ul>	30 a/c per hour 12 a/c per hour	Exhault Fans	ton M.R	
Fi	re Extinguishers				
	<ul><li>Total numbers</li><li>Types</li><li>IS marking</li></ul>	ISI marked	12 (Twelve ABC Type 5 kg) water con Type 4.	05 NO. R	
6 · Fi	rst-Aid Hose Reels.	151 Harket	yes.	W.K	
	<ul> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	0ne 30 m 5 mm	one yes	m·R m·R.	
7 A	Automatic fire detection and alarming system.				
	<ul><li>Type of detectors</li><li>Location of Main Panel</li></ul>				
	<ul> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>		N. A -		
8 <b>W</b>	10EFA	yes	Provided.	m.R	
	ublic Address System.	yes.	Provided.  Provided	M.R M.R	
	Automatic Sprinkler System.				
	• Basement	yes	Provided -	M.R	

contal: -

De hollywood Gust house \$ /6 Desa Bondau
Gupta Road, Pakas Gains view Delli-Hers
old case

Upper Floor Sprinkler above false ceiling 11 Internal Hydrants Size of riser/down-comer Number of hydrants per floor Hose Box 12 Yard Hydrants. Total number of hydrants Hose Box 13 Pumping Arrangements. Ground Level Discharge of main Pump > Head of Main pump > Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head > Auto Starting/ Manual stopping > Pump House Access Terrace level > Discharge of pump 220 LPM Head of the pump 30 Mbs. Power Supply Electric Auto Starting of pump 14 Captive Water Storage for fire fighting. Underground tank capacity. N.A > Draw-off connection NA

De- hollywood Guest house, 8/6, Desh Bandan Gupta Road, Pahal Ganz New Dellio-1100 58

* 1	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	yes.	Plandol Pecrided to Foo Atos	ns-R
	<ul> <li>Overhead Tank capacity</li> </ul>	yes-	Pearided	M-R
15	Exit Signage.	500061	ter for ates	mil
16	Provision of Lifts.	yes.	flavidas.	m.R
	Pressurization of Lift Shaft			
	4	an makes a part of the state of		
	Pressurization of Lift lobby			
	* Communication In lift Car	the state of the s		
	* Fireman's Grounding Switch		N. A	
	* Lift Signage			
17	Stan II			
18	Standby power supply		D.G. set	m.R
	Refuge Area.	And the second of the second o		the second section of the section of the second section of the section of the second section of the secti
	> Total Area	NA	N.A	
10	> Location	N.A	N.A	NA
19	Fire Control Room			NA
	Detector System Panel			
	Flow Switch Panel			
	• PA System Panel		N.A	
	hou 10 - Country, 15 - Selection 15 - Country 15 - Count	1		
	Batter backup			
20	Building Floor Plans			
20	Special Fire Protection Systems for			
	Protection of special Risks, if any:		N.A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

De- Holly wood Guest House, 8/6, Desa Bandher Grupta Road, Pahar Grand, New Delhi-11soss. Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dlasm vie singh yadar Name Designation Assistant Divisional Designation office (contral) Do. (certeal)