## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/2862

Dated: 06/08/12

## **FIRE SAFETY CERTIFICATE**

Certified that the Bhartia Guest House, 3439, Dariba Pan, Pahar Ganj, New Delhi-110055 comprised of ground floor (03 guest rooms + reception + shops + 01 office & 01 staff room), 1st floor (03 guest rooms + 01 staff room & 02 store rooms) and 2nd floor (04 guest rooms + 01 staff room) Total 10 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2299 dated 27-07-2009. The premises was reinspected by the officer concerned of this department on 23-07-2012 in the presence of Sh..Balbir Singh (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 10 guest rooms with effect from a.6./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 96/. val./12.. at New Delhi by.

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049.
- 2. M/s Bhartia Guest House, 3439, Dariba Pan, Pahar Ganj, New Delhi-110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPEC	TION REPORT	House, 3439	Dasiba Pan
	. Name & address of the building - Pa	las Gazz.	vew Delhi-1	1/0055
,	T C.O.	deing House		0
	Tung of Con-	ase/ Renewal V		
	T		4.1.1	
	Fire Safety directives letter No :		6.11/2009/22 9ate	d: 27-7-2009
(		N.A 3-07-2012		
-	Name of the Inspecting Officers De			the second of the second secon
{	Name and designation of officers	sem der singh		
		gi Ralking	ingl (owner)	4
g	Year of Construction	esting year 2	and (ou let)	
1	O. Applicant's letter No. 2076		c/h) of dited N	
S.	Minimum Standards on fire	NBC	Provided at site	Company of the second
NO.	prevention and fire safety U/R 33	Requirement	PSS Alla	Remarks
1 1	Access to building	2.04 an emeric	123 Her	M Cold Code
	Road width	1	0 . 4 . 6 . 6	
			On 1.5 Miles Gale	lood. M.R
	• Gate width	N.A	N-A	N.A
	<ul> <li>Width of internal road</li> </ul>	N.A	N.A	N.A
2	Number, Width, Type & Arrangement	of Exits		
	a. Number of staircases			
	<ul> <li>Upper Floors</li> </ul>	0/	0/	M·R
	<ul> <li>Basements</li> </ul>	N.A	N. A	N.A
	b. Width of staircases	The state of the s		
THE PARTY OF THE P	<ul> <li>Upper Floors</li> </ul>	a. on mtes	+	
	<ul><li>Basements</li></ul>	N. A	77cms to 89cms	A STATE OF THE PARTY OF THE PAR
	c. Protection of exits	JV. A	N. A	NA
	Fire check door			
	<ul> <li>Pressurization</li> </ul>	N. A	N.A	MA.
	e. No. of continuous staircases to terrace	N. A	N. A	N.A
	g. Width of Corridor	one	one	M-R
	h. Door Size	N. A	N.A	NA
· · · · · · · · · · · · · · · · · · ·	n. Door Size	N.A	N.A	N.A

contal:-

Bleetia Greet borre 3439 Dasipa Par Pales Gang. New Delli-

			PS.S	Alsa case
10	Compartmentation.			
	Fire check door			and again again ar second of "Madalathan and second in the second against 1000 days in common wa
	<ul> <li>Sealing of electrical shafts</li> </ul>			
	Fire Rating of shaft door		N.A	
	Water Curtain		\	Annual Control of the
	<ul><li>Fire Dampers</li></ul>			
6	Smoke Management System.			
	• Basements	30 a/c per hour	natural ventilation	N.A.
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour 🖊	latural ventelación	n'K
	Fire Extinguishers		06	n 0
-	<ul> <li>Total numbers</li> </ul>	06	ABC 5 Kg &	M.R
	<ul><li>Types</li></ul>	Tax 1	coz 4.5 Kg	M.R
	• IS marking	ISI marked	yes	/-/X
	First-Aid Hose Reels.	T		rang and some plates replaced in the statement of the sta
	Total numbers on each floor	20		
	• Length of hose reel hose	30 m	N. A	angularan kanamatan atau atau dan
	Nozzle diameter			And the second s
7	Automatic fire detection and alarming	system.		
	Type of detectors			
	Location of Main Panel			
. *	Location of Repeater Panel		N. A	
	Alternate source of power			
	• Hooters' Location			
arababas no propos	1100toto 2504mion			
8	MOERA	N.A	W. A	N.A
9 .	Public Address System.	N.A	N.A	W.H
10	Automatic Sprinkler System.		-14	010
	* Basement	N.A	N.A	N.O

Bhartea Guest house, 3439 Davida Par Upper Floor Sprinkler above false ceiling N.A Internal Hydrants 11 Size of riser/down-comer Number of hydrants per floor N. A Hose box 12 Vard Hydrauts. Total number of hydrants Hose Box 13 Pumping Arrangements. Ground Level Discharge of main Pump > Head of Main pump Number of main pumps Jockey Pump out put N.A > Jockey pump head Standby Pump out put > Standby Pump Head > Auto Starting/ Manual stopping > Pump House Access Terra e level Discharge of pump > Head of the pump > Power Supply > Auto Starting of pump Captive Water Storage for fire fighting. 14

Underground tank capacity

> Draw-off connection

contd:

Bhaetia Guest House, 3439, Decida Par Paper Gan, New Delli-110015

PSS Alsa old case

Fire service inlet  Access to tank  Overhead Tank capacity  t Signage.  Dission of Lifts.  Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage	M. A  M. A  N. A  Yes	N. A N. A Provided  N. A	N.A N.A M.A	
* Overhead Tank capacity  t Signage.  evision of Lifts.  Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage	N.A	N.A Provided	N.A	
t Signage.  Division of Lifts.  Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage		Peovided		
Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	yes		m·R	
Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage				
Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage				
Communication In lift Car Fireman's Grounding Switch Lift Signage				
Communication In lift Car Fireman's Grounding Switch Lift Signage		N.A	2	
Lift Signage		7.79		
Lift Signage		7		
			AMERICAN P. S. AMERICA SERVICE	
andby power supply	- yes	INVERTOR	M.R	
Refuge Area.				
> Total Area	N.A	N.A	N.A	
> Location	N.A	M.A	N.A	
Fire Control Room				
Detector System Panel	No.			
* Flow Switch Panel			· ·	
PA System Panel		N.A	&	
Batter backup	The state of the s			
Building Floor Plans				
•	N. A	N.A	N.A	
	<ul> <li>Control Room</li> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> </ul>	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> <li>ecial Fire Protection Systems for</li> </ul>	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> <li>ecial Fire Protection Systems for</li> </ul>	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Safety Certificate under rule 35 of the Delhi

## Blastes Guart mouse 3439 Dasiba Par, pulsas Gand, New Delhi -11 205

Signature of the Inspecting Officer

Name

Designation

Do. Ceenteal) (1)2

Signature of the Inspecting Officer

Name Dhaen vie singh yade

Designation Accistant Divisional
officel (certal)