SOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 2 884

Dated: 07/8/12

FIRE SAFETY CERTIFICATE

Certified that the Sun Flower Inn Guest House, 962, Gali Kumharan, Main Bazar, Pahar Ganj, New Delhi-110055 comprised of ground floor (03 guest rooms + reception) 1st floor to 2nd floor (06 guest rooms at each floor), 3rd floor & 4th (owner's residence) total 15 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2415 dated 04-08-2009. The premises was re-inspected by the officer concerned of this department on 26-07-2012 in the presence of Sh.Rajesh Kumar Sehgal (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 15 guest rooms with effect from . \(\frac{92}{25} \) \(\frac{1}{25} \) \(\frac{1}

Issued 97/.58./.12. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049.
- 2. M/s Sun Flower Guest House, 962, Gali Kumharan, Main Bazar, Pahar Gang, New Delhi-110055.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTI	ON REPORT	t linear a	20			
	529	geower Gill	est House, 9	Pakas Gand			
1.	Name & address of the building	prew	est House, 9 Main Bazal, Delli-1100	055.			
d.	Type of Occupancy : Lodging House.						
3.		se/Renewal	,				
4.	Details of previous NOC : Letter No	FG/DFS/MSB	74/2009/24/3Dated	04-08-09			
5.		A.A.					
	AT THE ART WHITE WAS A STATE OF THE ART AND A	-07-2012					
7.	Name of the Inspecting Officers 2,5	, yadar (A.1	00)	-			
8.	Name and designation of officers						
		The state of the s	umar sekgal	(Manages)			
	Year of Construction 1990 &: Star						
1			3-07-201	2 old co			
5.			Provided at site	Remarkacs A			
NO.	prevention and fire safety U/R 33	Requirement		MR/NMR			
1	Access to building						
	 Road width 	N. A	02 m tes appear M.R				
	 Gate width 	NA	N. A	NA			
- mar. q	 Width of internal road 	N.A	N.A	NA			
2	Number, Width, Type & Arrangement o	f Exits					
	a. Number of staircases						
	 Upper Floors 	one	one.	m-R			
	• Basements	N.A	N-A	N.A			
	b. Width of staircases						
	 Upper Floors 	0 + 80 Mts	01-conte	· M·R			
	Basements	NA	N. A	N.A			
	c. Protection of exits		Annual Control of the				
	Fire check door	NA	N. A	N. A			
	Pressurization	N-A	NA	N.A			
	e. No. of continuous staircases to terrace	one	one	M-R			
	g. Width of Corridor	N. A	NA	N.A			
i	0	N-A	p.A	N.A			

sun flower Inn quest Horse, 962, Gale Kumbolan main Bagar pakal Greens, ven Delli-11055

	pakal G			old case		
	ompartmentation.			£ 1, 8		
	• Fire check door		\	The state of the s		
	• Sealing of electrical shafts	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Manager of the state of the sta		
	Fire Rating of shaft door		1			
	Water Curtain		N.A			
	• Fire Dampers					
S	Smoke Management System.					
	• Basements	30 a/c per hour	- N. A - Natural ventilos	N.A		
	• Upper floors	12 a/c per hour	Natural ventila	teon M.R		
I	Fire Extinguishers			and the second s		
	Total numbers	lo(Ten)	10 Hen)	M-R		
	* Types		W.Coz & ABC	m·R		
	IS marking	ISI marked	Type Ves	M-R		
5 1	First-Aid Hose Reels.		700			
	Total numbers on each floor	one	one	M.R		
	 Length of hose reel hose 	30 m	yes	N.R		
	Nozzle diameter	5 mm	yes	m·R		
7	Automatic fire detection and alarming system.					
	 Type of detectors 	N H M H				
	• Location of Main Panel					
a para	• Location of Repeater Panel		N.A			
	Alternate source of power					
	 Hooters' Location 					
		A C C	11 0	N. A		
	MOEFA	N. A	M. A PEOVICE	p m-R		
9	Public Address System. (Inter com)	yes	pro-190			
10	Automatic Sprinkler System.	a / A	11. 1	11. A		
	* Basement	N-A	N-A	N.A		

sun flower Inn quest nouse, 962, Gali kumharan, main Bazar, fahar Gans, wew Delli 1/0015

	the discontinuous to an extension to an extension of the contract of the contr			old co			
The state of the s	• Upper Floor	N-A	N.A	PSS A			
	opiniater above false ceiling	N.A	N.A	NA.			
1 In	Internal Hydrants						
	Size of riser/down-comer						
Total Mill of C. C. Comme	 Number of hydrants per floor 						
	• Hose box	The second second second second second control of the second seco	N.A				
V	ard Hydrants.	Annual Control of Cont					
	And the second s		- Park	And the second s			
4	rotal number of nydrants	N-A	N. A	N.A			
Pi	* Hose Box	N.A	N.A	N.A N.A			
1.1	umping Arrangements.	The state of the s	The second section of the second section of the second section of the second section of the second section sec				
	* Ground Level	\	,				
	Discharge of main Pump		.,				
1	➤ Head of Main pump						
	Number of main pumps		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
	> Jockey Pump out put	The second secon		ē			
	> Jockey pump head						
and the second			N.A				
	a windo's tump out put						
	> Standby Pump Head						
and the second s	> Auto Starting/ Manual			97.			
A C. Streetwise Pre-	stopping						
The state of the s	> Pump House Access						
a distance of the second	Terra e level			\			
	> Lischarge of pump	180 LPM	180 LAM	M.R.			
	> Head of the pump	30 Mts	30 mtes	M.R.			
	-	Recterity	Electricity	MA			
	> Auto Starting of pump	/	switch Provider	M. R			
Ca	aptive Water Storage for fire fighting.		an ferria selle				
	Underground tank capacity	N-A	N-A	N.A			
	> Draw-off connection		N.A				

962 Gale Dem Rolan, Main Bagas pakas Gant New Dellan

Fire service inlet N. A N. A > Access to tank N.A Overhead Tank capacity 15 yes Provided Exit Signage. M.R 16 Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car N.A Fireman's Grounding Switch Lift Signage 17 1-G. set Standby power supply Ves m. R 18 Refuge Area. > Total Area N. A N.A > Location N. A 10 Fire Control Room Detector System Panel Flow Switch Panel N. A PAl System Panel Batter backup Building Floor Plans 20 Special Fire Protection Systems for N. A Protection of special Risks, if any:

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

sun flower Inn guest monse 962 Gale Unnharan, main Bazar Pahar Gans, ve a Delli-1/015

Signature of the Inspecting Officer

Name

Designation

Deto(02) life
20/67//L

Signature of the Inspecting Officer

Name Thasm vie singh yelow.

Designation Ascistant Divisional
obsides (central)