## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 2960

Dated: 14/08/12

## FIRE SAFETY CERTIFICATE

Certified that the Jindal International Guest House, 4/2, D.B.G. Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception), 1<sup>st</sup> floor (03 guest rooms + 01 office + 01 store room and sitting lobby), 2<sup>nd</sup> floor to 4<sup>th</sup> floor (12 Guest rooms at each floor), Terrace floor having kitchen for staff (found closed) Total 39 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1888 dated 26-06-2009. The premises was re-inspected by the officer concerned of this department on 30-07-2012 in the presence of Sh. Suresh Kumar Gupta (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 39 guest rooms with effect from 19. 19. 100. 2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued ./.4./.58.//2... at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049.

2. M/s Jindal International Guest House, 4/2, D.B.G. Road, Pahar Ganj, New Delhi-110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTION REPORT					
Tindal International Quest House,  Tindal International Quest House,  Same & address of the building 4/2, DBG Road, Pakas Game, Malle-						
				U		
2		Renewal	leuland	21 12-00		
2	Details of previous NOC : Letter No. F6/DFS/MS/GH/2009/Dated: 26-06-2009					
	our e Safety directives letter No : = N.A -					
8.	Name of inspection : 30-07-2012  Name of the Inspecting Officers : Dhasm vis singh yadov.					
Š	Name and designation of officers					
	from the building side Skal Suresa kumar Gupta.					
Ç.	Year of Construction : ST	tasting year	2007.	22. 11.2		
10	Applicanus letter No. :204-	39/Addl. C.f.	Lic)(1) dt new se	lli-the 20-04-12		
. !	Minimum Standards on fire	NBC	Provided at site	Remarks		
	prevention and fire safety U/R 33	Requirement		del care		
1	Access to building			4		
1	<ul> <li>Road width</li> </ul>	N.A	more than 18 Mile	es M.R		
	Gate width	N. A	NA	N. A		
	<ul> <li>Width of internal road</li> </ul>	NA	NA	N.A		
1	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	<ul> <li>Upper Floors</li> </ul>	one	one	M.R		
	• Basements	N. A	N. A	N.A		
	b Width of staircases	in administrating the appropriate and a second seco				
	* Upper Floors	0.80 Mts.	123 cms to 1250	M. R		
	* Basements	N.A	N.A.	NA		
	c. Protection of exits					
	Fire check door	N. A	NA	NA		
	Pressurization	N.A	NA	N.A		
	e. No. of continuous staircases to terrace	one	one	M.R		
	g. Width of Corridor	N.A	N-A	NA		
	h. Deor Size	N.A	NA	NA		

contd:-

Jindal International Guest House, 4/2, DBG Road, Pakar Gant, New Delli-110055

Co	Fire check door  Sealing of electrical shafts	· · · · · · · · · · · · · · · · · · ·	N· A	
	Water Curtain			
P R	Fire Dampers			
3	Smoke Management System.			
	<ul><li>Basements</li><li>Upper floors</li></ul>	30 a/c per hour 12 a/c per hour	N. A Natural pentillat	N. A.
	Fire Extinguishers		The second secon	
	Total numbers	12 NOS	12 NOS. Co2 Type & ABC Type	m·R m·R
	· Types		ABC Type	M·R
	<ul> <li>IS marking</li> </ul>	ISI marked	ye8	M-R
	First-Aid Hose Reels.		· ·	T
	• Total numbers on each floor	one	one	M·R M·R
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	yes	and the state of t
	Nozzle diameter	5 mm	ye8	N.K
7	Automatic fire detection and alarming	system.		
	<ul> <li>Type of detectors</li> </ul>			A
	<ul> <li>Location of Main Panel</li> </ul>			-
	<ul> <li>Location of Repeater Panel</li> </ul>	The second secon	N. A	
	. Alternate source of power			
	• Hooters' Location			
8	MOEFA	N.A	N.A	N.A
9	Public Address System. & intescom	yes	Provided	M.R
iv		0		as A
	* Basement	N. A	N. A	JV . 11

Jindal International Guest House, 4/2, D.B.G. Road, pakas Gang, New Salai-

The second second second	• Upper Floor	N.A	N.A	N.A	
	Sprinkler above false ceiling	N.A	N. A	N.A N.A	
11	Internal Hydrants				
	<ul><li>Size of riser/down-comer</li><li>Number of hydrants per floor</li></ul>				
An 0.10 a married	• Hose box		N.A		
k v	Yard Hydrants.				
	<ul> <li>Total number of hydrants</li> </ul>	M. A	N.A	N.A	
#	<ul> <li>Hose Box</li> </ul>	N. A	N.A	N.A	
13	Pumping Arrangements.				
	Ground Level		\		
	> Discharge of main Pump			1	
	> Head of Main pump				
	Number of main pumps		<u> </u>	And some sq. or 1	
	> Jockey Pump out put		N.A		
	> Jockey pump head				
	> Standby Pump out put		,		
	> Standby Pump Head				
	> Auto Starting/ Manual			3.7	
	stopping	, a	1		
	> Pump House Access	1		3	
	Terra e level				
	> Lischarge of pump	450LPM		M.R.	
	> Head of the pump	30 mt8s	30 m teg	M.R	
	> Power Supply	Electricity	Electricity	m.R	
V-100-00-00-00-00-00-00-00-00-00-00-00-00	> Auto Starting of pump		Switch Provia	bed M.R	
14	Captive Water Storage for fire fighting	•	av rust floor	<u> </u>	
	Underground tank capacity	NA	N.A	N.A	
	> Draw-off connection	N. A	N.A	N.A	

Jindal International quest House, 4/2, DBG Road, Palas Grang, New Delsti-1/0055.

			e la suit	
	Fire service inlet	N.A	N.A	N.A
	> Access to tank	N.A	N.A	N.A
	Overhead Tank capacity	5000 lite	5000 litees	M. R
	Exit Signage.	yes ·	Provided.	M.R
.6	Provision of Lists. (one Bift)			Control of the contro
	* Pressurization of Lift Shaft	N.A	N.A	N. A
	Pressurization of Lift lobby	N.A	N.A	N.A
ş 3	* Communication In lift Car	yes.	Provided	m·R
	Fireman's Grounding Switch	yes	Provided	M.R
	⋄ Lift Signage	. Yes	Peopled	M·R
17	Standby power supply	yes.	D. G. Set	M.R
1.8	Refuge Area.		1	
	> Total Area	N.A.	N.A	N.A
	> Location	N.A	N.A	N.A.
10	Fire Control Room	**		
	Detector System Panel		\ , , , , , , , , , , , , , , , , , , ,	
	• Flow Switch Panel			week for the second of the sec
1	PAl System Panel		N.A	**************************************
	<ul> <li>Batter backup</li> </ul>	Particular to the principal garage in the principal prin		
	Building Floor Plans			and former infromening proper than attractions a transfer proper security.
20	Special Fire:Protection Systems for			Service Co.
	Protection of special Risks, if any:	N.A	N.A	N.A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

 Jindal International Guest House, 4/2, DBG Road, Palas Gang, New Delhi 1/0055

Signature of the Inspecting Officer

. Carrie

Dissignation

D.C.F.O-I FOX 6/8/12 Signature of the Inspecting Officer

Name Mason vie eingh yader

Designation generate sivisional offices (central)