GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/3101

Dated: 27/08/12

FIRE SAFETY CERTIFICATE

Certified that the Mourya Dx. Guest House, 9919-9923, Gali No.-6, Multani Dhanda, Sadar Thana Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + shops + 02 guest rooms), 1st floor to 3rd floor (08 guest rooms at each floor) and 4th floor (02 guest rooms + 01 store room + kitchen for staff + D.G. set), total 28 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2478 dated 10-08-2009. The premises was re-inspected by the officer concerned of this department on 14-08-2012 in the presence of Sh. Jitender Mourya (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 28 guest rooms with effect from .2.7/.58./....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued ??/.o.\./1_. at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049: wrt...42100/Addl.CP/Lic.(H) dated 2.7.2012

2. M/s Mourya Dx. Guest House, 9919-9923, Gali No.-6, Multani Dhanda, Sadar Thana Road, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

Name & address of the building	Mourua	Dx. Guest Ho	we, 9919-23, Mu	I too Dhanda Ph	
2. Type of Occupancy		e House		Hewl	
Type of Case	-	e/ Renewal			
4. Details of previous NOC	: Letter No	F6/DFRIMSIBHI	2009/2010 Dated	10-08-2mg	
Fire Safety directives letter No	Fine C. C. 1. 1. 10-08-2009				
5. Date of inspection	Date of inspection				
Name of the Inspecting Officers: Sh. D.S. Yadav (A.D.O)					
8. Name and designation of officer	S		(A) D'0)	- entered to be a second to the second to the	
from the building side	Sh,	Titender 1	Nourya (oron	(ده	
9. Year of Construction	20	07 Storting	Year Referre	d & D.F.C.	
10. Applicant's letter No.			(H) dated New		
Minimum Standards on f	ire	NBC	Provided at site	Remarks	
prevention and fire safety U	/R 33	Requirement		MR/NMR OLL Case	
Access to building			The state of the s	Old Case	
• Road width		N.A	20 wide good	& M.R	
• Gate width		MA	NA	NA	
• Width of internal road		MA	NA	MA	
Number, Width, Type & Arra	ngement o	of Exits	g 9		
a. Number of staircases					
Upper Floors		0/	0/	mR	
• Basements		HA	NA	NA	
b. Width of staircases					
• Upper Floors		80 Cm3,	125 Cms	MR	
* Basements		NA	NA	NA	
c. Protection of exits		1011	77.1	1,401	
Fire check door		LΙΔ	NA	MA	
• Pressurization		MA	MA	NA	
e. No. of continuous staircases	to terrace	MA	and the second s	mR	
g. Width of Corridor		6/	0/	MA	
h. Door Size		MA	MA	MA	
11. 12001 5126		MA	/ 7/4	1 4 6	

Conta. -

Mourya Da. Guest House, 9919-23, Gali Ho-6, Multani Ohanda, Parhar Gan's New Delhi

And the latest property of				
Com	partmentation.	18		
	Fire check door	MA		
•	Sealing of electrical shafts	MA		The second secon
	Fire Rating of shaft door	NA	_	AND
	Water Curtain	MA		•
	Fire Dampers	NA	_	
Sm	oke Management System.			
	Basements	30 a/c per hour	MA	XIA
	• Upper floors	12 a/c per hour	Natural Ventilation	MR
	<u> </u>			
Fin	e Extinguishers	10	12 NOS.	MR
	Total numbers	12 NOS.	Water Coz & Coz	MR
	Types	Tat 1 1		MR
	IS marking	ISI marked	Provided	MK
6 Fi	rst-Aid Hose Reels.			. 0
	• Total numbers on each floor	0	01	MR
	• Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
$\frac{7}{A}$	utomatic fire detection and alarmin			
	 Type of detectors 	MA		
	Location of Main Panel	MA		
	• Location of Repeater Panel	MA		
	• Alternate source of power	MA		-
a production of	• Hooters' Location	MA		
8	MOEFA	Yes	Provided	MR
-	Public Address System.	Yes	Provided	me
10	Automatic Sprinkler System.			
10	Basement	NA		
			and handlestering in properties (handlester the de-follow) - military on the following in consisting a subsidiary and substitutes and the following in the foll	- 4.4

Conta, +

Monya Dr. Guest House, 9919-23, Gali No-6, Multani Dhanda, - Pahar Ganj, New Delhi

•				
; ;	• Upper Floor	NA		,
* The supple to	Sprinkler above false ceiling	MA		The second secon
11	Internal Hydrants		and the state of t	
	Size of riser/down-comerNumber of hydrants per floor	NA		
	* Hose box	NA		
		MA	•	
	Yard Hydrants.	4	The second second second second second	1 1000 P
	Total number of hydrants	NA		
	* Hose Box	NA		
	Pumping Arrangements.	The second secon		
	* Ground Level	NA		
	Discharge of main Pump	HA		
	> Head of Main pump			
	> Number of main pumps	MA		
	> Jockey Pump out put	MA		
	> Jockey pump head	NA	_	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		NA		
	Standby Pump out putStandby Pump Head	MA		
	> Auto Starting/ Manual	MA		
	stopping	0.4.4		
		MA		
	 Pump House Access Terra e level 	MA	_	
	> Lischarge of pump	225 LPM	225 LPM	mr 1
	 Head of the pump 	30 Mbs.	30 Mts.	mR
	> Power Supply	Electric	Electric	me
	Auto Starting of pump	-	Switch Provides	me
14	Captive Water Storage for fire fight	ing.	G:F	
Account of the contract of the	 Underground tank capacity 	MA		
	> Draw-off connection	NA		
	The second section of the second seco	the course becomes the second of the second	I are the same of	and the same of th

Mourya Da Guest House, 9919-23, Maltani Dhanda, Greli No-6, Pahar Ganj, New Delhi

The second secon		* a α ₄ X	
Fire service inlet	MA		
Access to tank	MA		
Overhead Tank capacity	2500 ltos.	2500 Urs.	mR V
Exit Signage.	Yes	Provided	mR
16 Provision of Lifts. Cone lift	G. to fourth	flore)	
* Pressurization of Lift Shaft	N.A	N. A	NA
Pressurization of Lift lobby	N.A	N-A	N.A
* Communication In lift Car	yes	Provided	M.R.
Fireman's Grounding Switch	yes.	Provided.	M-R
⁹ Lift Signage	yes.	Provided,	M-R
Standby power supply	408	N / C +	mR
8 Refuge Area.	100	D. G. Set.)
> Total Area	NA	_	The state of the s
➤ Location	MA		
10 Fire Control Room			
Detector System Panel	MA		
 Flow Switch Panel 	NA		
PAl System Panel	MA		
Batter backup	MA		
Building Floor Plans	NA		
Special Fire Protection Systems for Protection of special Risks, if any:	NA	_	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Service Rules 2010/ issue shorteonings as noted at serial numbers.

Contd. 1

Mourya Dx. Guest House, 9919-9 Seedar Thang Road, Pahar G	923, Gali No-6, Multani Dhanda, -
	14-08-12
Signature of the Inspecting Officer	Signature of the Inspecting Officer
Name	Name Dhaim vis singh yadar
Dysignation	Designation Assistant Divisional
Do for	Obsice (central)
DO. (R.D) Forwarded for	approved please.
Dy CFO (NDZ)	11 1 8 1 / 12