GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/2148

Dated: 2 9 / 68 / 12_

FIRE SAFETY CERTIFICATE

Certified that the Bless Inn Guest House, 2339-41, Rajguru Road, Chuna Mandi, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 02 shops + 05 guest rooms), 1st floor (10 guest rooms), 2nd floor (10 guest rooms) and terrace floor (01 staff rooms + D.G. Set), total 25 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/1904 dated 29-06-2009. The premises was re-inspected by the officer concerned of this department on 16-08-2012 in the presence of Sh. R.D. Narang (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 25 guest rooms with effect from .2.9/.96./....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to dompliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 2.5/.08.//... at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049: w. r. t. letter No. 27357/Addl./C.P./ Lic (H) dated 07-05-2012.
- 2. M/s Bless Inn Guest House, 2339-41, Rajguru Road, Chuna Mandi, Pahar Ganj, New Delhi-110055.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

i.	Name & address of the building Bless	Pun Guest House	2239-41 Raisen	Road Cl. m
1	Type of Occupancy Lodging	House	,2339- 4 1, Rajguru <i>Pai</i>	Par Ganj, Hew I
).		se/Renewal	-	
4.	T3		2009 / 1904 Dated	90-06-2009
5.	Fire Safety directives letter No :	VA	770	27-00-2001
6.	Data all	16-08-2012		C. 17 STOCK OWNER A
7.	Name of the Inspecting Officers : S	L. D.S. Yada	(A.D.O)	
8.	Name and designation of officers		and the second s	CONTRACTOR
	from the building side	R. D. Nas	ang (oroner)	
	Year of Construction 20	001 Starting	Year in D.F.S.	✓
			(H) New Delli; 1	aked 7/5/12
5.	Minimum Standards on fire	NBC/BBL	Provided at site	Remarks
XO.	prevention and fire safety U/R 33	Requirement	P.S.S Area	MR/NMR Old Case
-	Access to building			Secretary and the second of th
	 Road width 	- N-A-	More then 6 Mtss.	MR
	• Gate width	- NA -	MA	MA
	• Width of internal road	- MA -	MA	MA
2	Number, Width, Type & Arrangement (of Exits		TO SERVE MINE of the 1-bits decemberage in 1,500) recognized prime multi-place (1,500 to 10,000 persons, pri
	a. Number of staircases			
	 Upper Floors 	01	0/	ml
Value appearance of the same	• Basements	MA	NA	MA
A APPLICATION OF THE PERSON	b. Width of staircases			
-	 Upper Floors 	30 cms	105 Cms. to 113 cm	s mR
	* Basements	MA	MA	MA
	c. Protection of exits			
	Fire check door	MA	MA	NA
	Pressurization	MA	NA	NA
	e. No. of continuous staircases to terrace	01	01.	MR
	g. Width of Corridor	NA	NA	MA
	h. Door Size	MA	NA	MA

Bless Inn Guest House, 2339-41, Roggury Road, Chung Mandi, Parter. Ganj, New Delli-110055

old case

Co	mpartmentation.			**************************************
	• Fire check door	MA.		_
	• Sealing of electrical shafts	MA	-	
	• Fire Rating of shaft door	HA		MANUTE SELECTION OF SELECTION O
	Water Curtain	MA	-	
	Fire Dampors	NA	-	
5	moke Management System.			
	Basements	30 a/c per hour	N-A- Natural Ventilation	-N.A-
	• Upper floors	12 a/c per hour	Natural Ventilation	MR
I	Fire Extinguishers			
	 Total numbers 	08	08	mR
	* Types		water Coz & Coz	MR
	IS marking	ISI marked	water Coz & Coz Provided	MR
	First-Aid Hose Reels.			
	 Total numbers on each floor 	0/	0/	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided Provided	MR
7 Automatic fire detection and alarming system.				
	 Type of detectors 	NA		_
	• Location of Main Panel	NA		
i	• Location of Repeater Panel	MA		
,	Alternate source of power	NA		
٠	Hooters' Location	MA		
8	MOEFA	Yes	Provided	MR
9	Public Address System.	Yes	Provided	MR
	Automatic Sprinkler System.			

Bless Inn Guest House, 2339-41 Ras Gusa Road, chuna mandi, Pakar Bant, New Delli-110055

old case

-				ola Cas	
	• Upper Floor	NA	5100.1100	_	
and the part of th	Sprinkler above false ceiling	MA			
11	Internal Hydrants				274
	Size of riser/down-comer	MA			
	 Number of hydrants per floor Hose box 	MA			
	1,000 000	NA			
L	Vard Hydrants.		Company of the same of the sam	× × × × × × × × × × × × × × × × × × ×	
	 Total number of hydrants 	MA			
1	* Hose Box	LIA	-		
	Pumping Arrangements.	17			
	• Ground Level	NA			
	Discharge of main Pump	MA			
	> Head of Main pump	MA			
	Number of main pumps	NA			
	Jockey Pump out put	NA			
1	> Jockey pump head	NA			
	> Standby Pump out put	and the first and the second s			
	Standby Pump Head	MA			
	Auto Starting/ Manual	MA		- 1/2	×
	stopping	MA			
	Pump House Access		•		
i.	• Terra e level	180 LPM	100 1 000	m 0	ra/
	> Lischarge of pump		180 LPM.	MR	41
	· Head of the pump	30 Mts.	30 Mtrs	MR	1
	Power Supply	Electric	Electric	mk	以所
Company of the Compan	> Auto Starting of pump		Switch Provided at G. F.	MR	1
14	Captive Water Storage for fire fighting.	· · · · · · · · · · · · · · · · · · ·			
	Underground tank capacity	NA			
	> Draw-off connection	NA			

Bloss Inn Gruest House, 2339-41, Rajgury Road, Chung Mandi, Pahar Gan, New Delhi - 110055

and the second of the second				old case
	Fire service inlet Access to tank	NA NA		
	• Overhead Tank capacity Exit Signage.	2500 Utos.	2500 ltrs.	ML
16	Provision of Lifts.	Yes	Provided	mR
	* Pressurization of Lift Shaft	KIA.		
	Pressurization of Lift lobby	NA		
	* Communication In lift Car	NA		
	Fireman's Grounding Switch Lift Signage	NA		
1.7		NA		
	Standby power supply Refuge Area.	Yes	D. G. Sef	mR
The second secon	Total AreaLocation	MA		
10_	Fire Control Room			The second secon
	Detector System PanelFlow Switch Panel	MA		
	PA: System Panel	MA		
	Batter backup	MA		
	Building Floor Plans	MA		
20	Special Fire Protection Systems for Protection of special Risks, if any:	MA		

The fire protection systems provided in the building were test checked and found functional at the time inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Service Rules 2010/ issue shortcomings as noted at serial numbers.....

	Bless Inn Guest House, 2330 Granj, Hew Delhi - 1/00	7-41, Rajgury Road, Chuna Mandi, Pahar	Patient
			.0
_	Signature of the Inspecting Officer	Signature of the Inspecting Officer	
	Name	Name Dhasm vie singh yadal	ices
	Designation Do (conteal)	Designation Assistant Divisional alla (central)	
		approval please.	
	Du CAPO (NUZ)	22/8/012	