

7  
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110001.

No.F.6/DFS/MS/School/2012/ 3354

Dated: 13/08/12

FIRE SAFETY CERTIFICATE

Certified that the building of **Green Wood Public School** located at RZF-529, Raj Nagar-II, Netaji Subhash Marg, Palam Colony, New Delhi-110077 comprised of Ground Floor plus one Upper floor, having total 14 rooms (Including Class Rooms, Office, Reception, Comp. Room & Store etc) was issued NOC by this department vide letter No.F.6/DFS/MS/06/2264 dated 30.08.2006. The school building was inspected by the officer concerned of this department on 30.08.2012 in the presence of Smt. Kiran Patel (Teacher) and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Director of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 and that the building/premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on.....13/08/12..... at New Delhi.

  
CHIEF FIRE OFFICER  
DELHI FIRE SERVICE

Copy to: -

1. The Manager,  
Green Wood Public School,  
RZF-529, Raj Nagar-II, Netaji Subhash Marg,  
Palam Colony, New Delhi-110077.
2. Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi - 110054.



Following fire safety directives must be adhered to –

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)



May kindly see the letter No. Nil dated 01.03.2012 received from the Manager, Green Wood Public School, RZF-529, Raj Nagar-II, Netaji Subhash Marg, Palam Colony, New Delhi-110077, regarding renewal of Fire Safety Certificate in respect of above said school building.

In this connection it is stated that the school building in question was inspected by undersigned on 30.08.2012 with a view to ensure the compliance of the fire safety recommendations issued from the director of education vide circular No.F.16/Estate/CC/Fire.Safety/2011/3298 to 3398 dated 01-03-2011. Smt. Kiran Patel (Teacher) was also present.

During the course of inspection it was observed that the school building is comprised of ground floor plus one upper floor. The upper floor is served by two staircases having width 122 cms & 112 cms respectively. The building is directly approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The building is properly ventilated. The School premises was issued NOC vide this department letter No. F.6/DFS/MS/06/2264, dated 30.08.2006. The room's allocation in the school is as under: -

**Total 14 Rooms** (Including Class Rooms, Office, Reception, Comp. Room & Store etc.)

The school building is protected by the following fire safety arrangements are as under: -

1. **Access to the building:** Available.
2. **Numbers of Doors in a Class Room:** Single door is provided (All classes having students less than 45).
3. **Fire Extinguishers:** One Co2 type 2.5 kg cap. and one D.C.P type 05 kg cap. or one WCO2 type 09 ltr cap. with ISI marked are provided for every 300 sq.m of covered area on part there of subject to a minimum of two such extinguishers for every floor. In addition, one Fire Extinguisher each in Laboratory, near to the electrical installation and /or generator room is provided.
4. **Staircase:** - Provided two staircases having width 122 cms & 112 cms respectively.
5. **First Aid Hose Reel:** - Provided with proper boosting arrangements.

The Fire Extinguishers/Hose Reels were checked/operated and the performance found satisfactory at the time of inspection. In view of above said school premises may be considered safe from fire safety point of view for renewal of Fire Safety Certificate for running the school in above said building.

DFA is placed in the file for your perusal and signature please.

Divisional Officer (S.W)

*Submitted please*

*[Signature]*

*31/8/12*

*[Signature]*  
*31/8/12*