GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/2012/3232

Dated: 05/08/12

FIRE SAFETY CERTIFICATE

Issued on at New Delhi by

Chief Fire Officer Delhi Fire Service

To.

The Dy.Health Officer M.C.D,Health Daepartment Shahdara(South) Zone,Delhi.

Copy to:-

Sh.Satish Thappar(Director)
M/S Rajmahal Banquets & Hotels (P) Ltd.
2nd floor,Aggarwal Fun City Mall,Plot No.29-31,
CBD Shahdara,Delhi-92.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized

construction/ unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1RN-6

INSPECTION REPORT

1. Name & address of the building : Raj Mahal Banquets, at 2nd Floor, Aggarwal Fun City Mall ,

Plot No. 29-31, CBD Shahdara, Delhi

2. Type of Occupancy

: Assembly

3. Type of Case

: New

: Nil

4. Details of Previous NOC 5. Fire Safety directives No

: F.6/DFS/MS/2012/2698 dated 24.07.12

6. Date of Inspection

: 14.08.12

7. Name of the Inspecting Officer: Do Virendra Singh & ADO Suresh Singh

8. Name of the designation of Officer

From the building side

: Sh.Satish Thappar

9. Year of Construction

: 2005

	ar of Construction : 2005	2		
10.Ap	plicant's letter No :Dated 25.07.13		Danidad at Cita	Remarks MR/NMR
	Minimum Standards on fire prevention	NBC	Provided at Site	Remarks with with
	and fire safety U/R33	Requirement		
1	Access to building		20.54	Ta.40
	Road width	12 Mtrs	26 Mtrs.	MR
	Gate width	4.5 Mtrs.	5 Mtrs.	MR
	Width of internal road	and the second control of the second control	era yiga situ dan dak sila dak	Silver-Orien valles again, egain, espa-Aqui
2	Number, Width, Type and Arrangement of	Exits		
	a. Number of Staircases	03 Nos.	03 Nos.	MR
	Upper Floor	03 Nos	03 Nos.	MR
	Basement	03 Nos	03 Nos.	MR
	B. Width of Staircases	1.5 M	1.5 M	MR
	Upper Floor	1.5 M	1.5 M	MR
	Basement	1.5 M	1.5 M	MR
	c. Protection of exits			
	Fire check door	Required	Provided	MR
	 Pressurization 	Required	Provided	MR
	e. No. of continuous staircases to terrace	1 Nos.	2 Nos.	MR
	g. Width of Corridor	2.6 Mtrs	2.5 Mtrs	MR
	h. Door Size	3 nos. of 2.0	Provided	MR
		Mtr.		4.0
3	Compartmentation.	Required	Provided	The state of the s
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Sealed	MR
	Fire rating of shaft door	2 hrs.	2 hrs.	MR
	Water curtain		**********	40000000000000
	Fire Dampers	Required	Provided	MR
4	Smoke Management System.		1	
	Basement	30a/c per hour	provided	MR
	Upper floor	12 a/c per hour	do	MR
5.	Fire Extinguisher		-	ray yellowed year - necessary and an extension of the second of the seco
5.	Total numbers	06 no.	06 No.	MR
	The second secon	ABC & Co2	ABC & Co2	MR
	- C & C O	ISI marked	ISI marked	MR
	IS marking	Dillidiked	10,111011100	

1RN-7

6	First-aid-Hose Reels.	e i	1.	
	Total numbers of each floor	4 no.	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming syst	tem.		
	Type of detectors	Heat & smoke	Provided	MR V
	Location of main panel	Control Room	1 st basement	MR
	Location of repeater panel	Security Room	Provided	MR
	Alternate source of power	Battery & DG Set	Provided	MR
	Hooters's location	Different Location	Different Location	MR
8	MOEFA	Required	Provided	MR
9	Public address System.	Required	provided	MR
10	Automatic Sprinkler System.	Required	Provided	MR
	• basement	Required	Provided in entre basement	MR
	upper floor	Required	Provided	MR 🗸
	sprinkler above false ceiling	Required	Provided	MR 🗸
11	Internal Hydrants	<u> </u>		
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants per floor	04 nos.	04 nos.	MR
	Hose Box	04 nos.	04 nos.	MR
12	Yard Hydrants.			
	Total number of hydrants	3 nos.	3 nos.	MR
	Hose Box	3 nos.	3 nos.	MR
13	Pumping Arrangements.			*
	Ground Level	Required	Provided	MR
	Discharge of main Pump	2280 LPM	2280 LPM	MR
	Head of Main Pump	60 Mtrs.	60 mtrs	MR
	Number of main pumps	1 nos.	1 nos.	MR
	Jockey pump out put	450 LPM	450 LPM	MR .
	Jockey pump head	60 Mtrs.	60 mtrs.	MR
	> Standby pump out put	2280 LPM	2280 LPM	MR
	> Standby pump Head	60 Mtrs	60 Mtrs.	MR
	Auto Starting / Manual stopping	Auto	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace Level			
	Discharge of pump	`		
	> Head of the Pump			***************************************
	Power supplyAuto Starting of pump			
14	Captive Water Storage for Fire Fighting.			

IRN-8

/
[F]
1

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name SURESH SINGH

Designation AA6

Signature of the Inspecting Officer

Name VIRENDRA SINGH

Designation De (E)