GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001** Dated: 14/09/12

No. F6/MS/DFS/GH/2012/ 3368

FIRE SAFETY CERTIFICATE

Certified that the Silver Shine Guest House, 1323-1328, Sangtrashan Chawk, Pahar Gani, New Delhi-110055 comprised of ground floor (02 guest rooms + reception + office), 1st floor to 3rd floor (11 guest rooms at each floor), 4th floor (04 guest rooms + 07 staff rooms/store rooms) and 5th floor (sealed with bricks), total 39 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2056 dated 09-07-2009. The premises was re-inspected by the officer concerned of this department on 23-08-2012 in the presence of Sh. Rajinder Pal (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 39 guest rooms with effect from .1.4/.a §../...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 1.4/6.9./12. at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First/Floor, P.S. Defence Colony, New Delhi-110049 w.r.t. No.46618/Addl.C.P./Lic.(H) New Delhi dated 23-07-12
- 2. M/s Silver Shine Guest House, 1323-1328, Sangtrashan Chawk, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

<u> monn</u>	CTION REPORT	Annual An	The production of the second s
 Name & address of the building Silve Type of Occupancy Type of Case Details of previous NOC 		* * * * * * * * * * * * * * * * * * *	
2. Type of Occupancy	es Shine Guest		
3. Type of Care.	Igins House	Touse, 1323-28, S	angtrashan Cho
4 Details of previous NOC Letter	Case/ Renewal		Neu
5. Fire Safety directions NOC : Letter	No. Fologelmai		100
5. Fire Safety directives letter No : Letter 6. Date of inspection	HA	0H/2009/2056 Dat	ed: 69-07-2009
7 Name of the I	3-08-2012		
	Sh. D. C 1	1	
Name and designation of officers from the building side	5, 7	adar A.D.	
9. Year of Construction	Radioda	DA	
10. Applicant's letter No.	2007 State	Pal (owner)	
Minimum 1466/	8/Add Colo 10	Pal (owner) 1 Year	L
Minimum Standards on fire	NRC NRC	Hew Do Hi Late	ed 23-07-2012
and the safety U/R 33	Requirement	a vincu at site	Remarks
Access to building	x codan exitent	D.S.S. Area	MR/NMR Old Case
Road width			Old Case
* Gate width	MA	06 mts app	ex MR
• Width of internal road	MA	MA	MA
Number, Width T	MA	MA	and the same of th
Number, Width, Type & Arrangement of a Number of staircases	of Exits		MA
or bran cases			
• Upper Floors	0/		
Basements	MA	0/	MR
b. Width of staircases		MA	MA
• Upper Floors	0.0		
* Basements	80 Cms.	125 Cms.	MR 1
c. Protection of exits	MA	MA	MA
 Fire check door 			
Pressurization	MA	MA	MA
e. No. of continuous staircases to terrace	NA	MA	MA
g. Width of Corridor	01	01	And the second s
h. Door Size	MA	MA	MR L
	NA	NA	MA.

Contal:

海江

Silver Shine Guest House, 1323-28, Sangtrasan Chook, Poher Gani), New Delu;

Co	mpartmentation.		79	
	Fire check door	MA		
	 Sealing of electrical shafts 	MA		
	• Fire Rating of shaft door	MA		
	• Water Curtain	MA		-
	• Fire Dampers	MA		
<u>S1</u>	moke Management System.			
	• Basements	30 a/c per hour	MA	MA
2	• Upper floors	12 a/c per hour.	Natural Ventilation	MR
1	Fire Extinguishers			
	 Total numbers 	12 Nos.	12 Nos Water Col A.B.C	MR
	• Types		Type	MR
	• IS marking	ISI marked	Provided	mR
	First-Aid Hose Reels.			
	 Total numbers on each floor 	01	01	mR
	 Length of hose reel hose 	. 30 m	Provided	MK
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	ig system.		***
	• Type of detectors	MA		
	Location of Main Panel	MA		
	Location of Repeater Panel	MA		
, 1 ^ p	•. Alternate source of power	MA		2
•	Hooters' Location	MA		
8	MOEFA	Yes	Provided	MR
9	Public Address System.	Yes	Provided	MR
10	Basement	MA	MA	MI

Conta.

Silver Shine Guest House, 1823-28, Sangtrashan, Cheark, Pahaz Gani, New Dolli - 110085

	 Upper Floor 	-		
	Sprinkler above false ceiling	MA		
11/	Internal Hydrants	MA	73	
8	 Size of riser/down-comer Number of hydrants per floor Hose R 	MA		
	ход эгогг	MA		
12	Yard Hydrants.	XIA		
	Total number of hydrantsHose Box	MA		7
13	Pumping Arrangements.	MA		
	* Ground Level			
20 20	Discharge of main Pump	MA		
	> Head of Main pump	MA		
	Number of main pumps	MA		
	> Jockey Pump out put	MA		
	> Jockey pump head	MA		
	Standby Pump out put	KIA		
	Standby Pump Head	MA		
15	Auto Starting/ Manual	MA		
	stopping	XIA		8
	> Pump House Access	, 0,1		
	* Terrace level			
	Discharge of pump	225 LPM	225 LPM.	MR
	> Head of the pump	. 80 Mtrs.	30 Mtrs.	MR MANNEY
	o not supply	Electric	Electric	no
C	Auto Starting of pump		Switch Provided	mx
	aptive Water Storage for fire fighting	*	W. F	
\$.	 Underground tank capacity Draw-off connection 	NA		
No. of State	27 Connection	NA		

Conta. :

Pahar Gani, New Delli:

The second second second		li .		
	Fire service inlet		4	
	Access to tank	MA	79	
	* Overhead Tank capacity	HA		
15	Exit Signage.	2500 Ctrs.	2500 1+23.	MR
16	Provision of Lifts.	Yes	Provided	mR
100	* Pressurization of Lift Shaft	MA	10129	
	Pressurization of Lift lobby Communication In lift Car	NA.		
	Fireman's Grounding Switch	Yes	Provided	MR
The state of the state of	* Lift Signage	Y-es	Provided	MR
17	Standby power supply	Yes	Provided	mp
18	Refuge Area.	Yes	D. G. Set	MR
	> Total Area			
	> Location	MA		
19	Fire Control Room	MA		
-	Detector System PanelFlow Switch Panel	MA		
	* PAi System Panel	X/A		
	 Balter backup 	· MA		
	* Building Floor Plans	XA		
20	Special Fire:Protection Systems for	XIA		
8	Protection of special Risks, if any:	MA		
	The state of the s	** *	0	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Receing in view the substantial compliance of the minimum standards on fire prevention and lire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers....

W-

X-

SILver Shine Guest House, 1323-28, Sangtrashan, Chowk, Pahar Ganj, Mew Delhi-110055

Signature of the Inspecting Officer

Name

Designation

Submitted for approval please.

Signature of the Inspecting Officer

Name (D. S. yadar)

Designation Alo (3)