## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 3 2 6 5

Dated: 07/09/12

### FIRE SAFETY CERTIFICATE

Certified that the Sonu Guest House, 4563, Main Bazar, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 03 guest rooms), 1st floor to 3rd floor (03 guest rooms at each floor) total 12 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2042 dated 09-07-2009. The premises was re-inspected by the officer concerned of this department on 29-08-2012 in the presence of Mrs. Hasneet Kaur (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 12 guest rooms with effect from £7./29./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

#### Copy to:-

- of ~ men 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049 w.r.t. No.46475/Addl.C.P./Lic.(H) New Delhi dated 24-07-12
- 2. M/s Sonu Guest House, 4563, Main Bazar, Pahar Ganj, New Delhi-110055

#### Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPEC	TION REPORT	*		
1. Name & address of the building: Sonut. 2. Type of Occupancy 3. Type of Case 4. Details of previous NOC 5. Fire Safety directives letter No 6. Date of inspection 7. Name of the Inspecting Officers 8. Name and designation of officers from the building side 9. Year of Construction 10. Applicants but	Guest House, a single Renewal - No. FE/DPS/ms/S NA 19-08-2012 Sh. D.S. Ya. Hasneet A	34/2009/2042 Date	od: 9-7-2009	Dell
prevention and fire safety U/R 33  Access to building	NBC/BB4 Requirement	Provided at site P.S.S. Area	Remarks MR/NMR	
Road width Gate width Width of internal road Number, Width, Type & Arrangement of	·NA	More then 6 Mrs. App NA NA	Bild Cose.  DA. MR  XIA  NA	
a. Number of staircases  • Upper Floors	of Exits			
* Basements b. Width of staircases	NA	NA.	MR	
<ul> <li>Upper Floors</li> <li>Basements</li> <li>C. Protection of exits</li> </ul>	80 Cms. MA	80 Cmsn NA	MR V	
• Fire check door • Pressurization	- HA -			
e. No. of continuous staircases to terrace g. Width of Corridor h. Door Size	01 - NA - - HA _	0/	MR	

Contd. L

×1/39

# Sonu Guest House, 4563, Main Basar, Pahaz Gain, New Delas-110855

old case

1			The second secon	ola case	
Co	inpartmentation.				
	<ul> <li>Fire check door</li> </ul>	MA -			
	<ul> <li>Sealing of electrical shafts</li> </ul>	- HA-			
	<ul> <li>Fire Rating of shaft door</li> </ul>	- NA -			
	• Water Curtain	- NA -			
	• Fire Dampers	- NA - - NA - - NIA -			
5	moke Management System.				
	• Basements	30 a/c per hour	MA	MA	
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	Natural Ventilation	n MR	
	Fire Extinguishers		,	· p	
	<ul> <li>Total numbers</li> </ul>	08	08	MR	
	• Types		cor Type & w co.	2 M.R.	
	IS marking	ISI marked	Provided	MR	
5	First-Aid Hose Reels.				
	• Total numbers on each floor	0/	0/	m	
× *	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	mR	
	Nozzle diameter	5 mm	Provided Provided	MR	
7	Automatic fire detection and alarming system.				
	• Type of detectors	- MA			
	Location of Main Panel	- NA	_		
	Location of Repeater Panel	-NA			
	Alternate source of power	- MA			
	• Hooters' Location	- X14	2		
8	MOEFA	- MA			
9	Public Address System.	- NA			
1.0					
	Basement	- MA	7		

Cont. 1

Somu Gruest House, 4563, Main Bazar, Pahar Ganj, Hew Delhi-110055

	<ul> <li>Upper Floor</li> </ul>	•		old ca
	Sprinkler above false ceiling	- MA.		
11/	Internal Hydrants	- XA -	77	
	• Size of riser/down-comer			
	Number of hydrants per floor	- MA -		
1.52	• Hose Box	- HA -		
2	Yard Hydrants.	- MA		
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	- MA-		74
3	Pumping Arrangements.	- MA-		
	* Ground Level			2
	Discharge of main Pump	- MA -		
	> Head of Main pump	- NA-		
	> Number of main pumps	- NA -		
	Jockey Pump out put	-MA -		the same and a second s
	> Jockey pump head	-NA-		
8	Standby Pump out put	- XA -		
	Standby Pump Head	- NA -		
	Auto Starting/ Manual	-NA-		the state of the s
	stopping			- 0 V
	Pump House Access	- NA -		i i
	* Terrace level	- NA -		
	Discharge of pump	· 180 LPM	180 LPM	MR L
	> Head of the pump	. 30 mtrs.	30 Mtrs.	mp vi
	o not supply	Electric	Electric	ma
C	Auto Starting of pump		Switch Provided	
	aptive Water Storage for fire fighting.		at G.f.	/// \
	<ul> <li>Underground tank capacity</li> </ul>	- NA -		
	> Draw-off connection	-114 -		

Contd. !-

Sonu Guest House, 4583, Main Bazar, Pahaz Granj, New Delhi-10085

		į.	*	old case.
	Fire service inlet Access to tank	- NA -	**	2
	Overhead Tank capacity	- HA -		
	Exit Signage. Provision of Lifts.	Yes	2500 Ltrs. Provided.	MR \ MR
	* Pressurization of Lift Shaft	- NA -	• •	
	Pressurization of Lift lobby	- MA -		
	Communication In lift Car	NA -		
	Fireman's Grounding Switch	- HA -		
	* Lift Signage	- NA -		
17_	Standby power supply	Yes.	D.G. Sef	me
13	Refuge Area.		0.0, 20,	
	<ul><li>Total Area</li><li>Location</li></ul>	- HA -		
19		-AA		Y .
	* Detector System Panel	-NA -		4
	• Flow Switch Panel	- NA -	-	
	* PA System Panel	-NA -	-	
	Batter backup	-NA -		
	• Building Floor Plans	- NA.		:
2	Special Fire:Protection Systems for Protection of special Risks, if any:	- MA		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Ecoping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers...

Contd. -

4/42 Sonu Grest House, 4563, Main Baroz, Papar Gain, Hew Delli-110055 Signature of the Inspecting Officer Signature of the inspecting Officer Name Name Dhagu vil single yakou Designation Designation Assistant Divisional offices (conteal) Forwarded for approval please,

Nu
5/91