GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No.F6/DFS/MS/School/2012/34 o 2

Dated: 18/09/12

FIRE SAFETY CERTIFICATE

Certified that the Manohar Memorial Educational Society located at Plot No.11, Nelson Mandela Road, Near Gurudwara, Vasant Kunj.New 110070.comprised of Basement, Ground + 2 Upper Floors was granted NOC by this department vide letter No.F6/DFS/MS/2006/152 dated 17/01/06 The premises was reinspected by the officer concerned of this department on 30/08/12 in the presence of Mr. Yoginder and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group 'B' Education Building Schools up to Sr. Sec. Level with effect from -- 18/55/12---- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire subject to conditions printed below.

Issued 18/09//2---at New Delhi by.

Chief Fire Officer Delhi Fire Service

OC

Copy to:- (1) Manohar Memorial Educational Society,

Plot No.11, Nelson Mandela Road,

Near Gurudwara, Vasant Kunj, New Delhi-110070.

(2) Director of Education, Old Secretariat, Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of BBL.

- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- Name & address of the building:- Manohar Memorial Educational Society, Plot No.11, Nelson Mandela Road, Near Gurudwara, Vasant Kunj, New Delhi-110070.
- Type of occupancy:- Group 'B' Education Building Schools up to Sr. Sec. Level. Type of case:- Renewal

Details of previous NOC:- No.F6/DFS/MS/2006/152 dated 17/01/06

Fire safety directives No.- No

- Date of inspection:-. 30/08/12
- Name of the inspecting officer:- A.D.O. S.S. Kaushik 7.

8. Name & designation of officer

From the building side:- Mr. Yoginder.

Year of construction: 2004.

10. Applicant's letter No:- Nil. dated 16/08/12 Sanken Basement, Ground + 2 Upper Floors

	(Salikell)	30 a/c per hour	Exhaust fan	MR
	Smoke Management System 1) Basements (Sanken)	20 /		-
	5) Fire Dampers	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
delinearing	1) Fire check door	Required	Provided	MR
	Compartmentation			IVIIX
	F. Door size	Required	1.16 mtr.	MR
	E. Width of corridor	N/A	2.58 mtr.	MR
	to terrace	0 1	One	MR
	D. No. of continuous staircase	one	one	N/A
5 7	2. Pressurization	N/A	N/A N/A	N/A
	1. Fire check door	N/A	N/A	27/4
	C. Protection of exits		cms.	
			cms. & 136	=
		required	Provided 150	MR
0.00	2. Basements	Required	cms. old N	-
	T.	a 2	cms. & 127	10/2
		CIIIS.	cms., 136	
		cms.	Provided 150) MR
	1. Upper floors	Required 150	D	
	B. Width of staircase		2 Nos.	
		Z INOS.	Provided	MR
	2. Basements	2 Nos.	3 Nos.	22
		2 Nos.	Provided	MR
	1. Upper floors	231		
	A. Number of staircases	ement of Exits	0:	20
2.	Number, Width Type & Arrang	N/A	N/A	N/A
Consumer Property	3)Width of internal road		5.54 mtr.	MR
	2) Gate width	Required	12 mtr.	MR
	1) Road width	Required	12	
1.	Access to Building	-		MR/NMR
1.	Prevention and fire safety U/R 33	Requirement	site	T COLLICE IED
- 2	Minimum Standards on fire	NBC	Provided at	Old Case

A118-

	2) Upper floors	12 a/c per hour	Exhaust fan	MR		
5.	Fire Extinguishers					
No. of Contrast of	1) Total numbers		17 Nos.	MR		
	2) Types	ISI Marked	W.Co2,CO2&	MR		
	3) ISI marking	- ISI Marked	ABC.			
6.	First-Aid Hose Reel		Yes	MR		
0.	1) Total number of each floor	To				
	1) Total number of each floor	One at each floor	One at each	MR		
	2) Length of hose reel hose	30 m	floor	MR		
	3) Nozzle diameter	5 mm	Yes			
7.	105					
	Automatic Fire Detection & Alarming System 1) Type of detectors N/A N/A N/A					
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A N/A	N/A		
	4) Alternate source of power	N/A	N/A N/A	N/A		
	5) Hooter's Location	N/A		N/A		
8.	MOEFA	N/A	N/A N/A	N/A		
9.	Public Address System	Yes	N/A Provided	N/A MR		
10.	Automatic Sprinkler System	103	Trovided	IVII		
100 EUE	1) Basement	Yes	Provided	MR		
	2) Upper floors	N/A	N/A			
	3) Sprinkler above false ceiling	N/A	N/A N/A	N/A		
11.	Internal Hydrants	IV/A	IN/A	N/A		
	1) Size of riser/down-comer	Required	100 mm.	MD		
	2) Number of hydrants per floor	Required	1 Nos.	MR		
	3) Hose box	Required	1 Nos.	MR		
12.	Yard Hydrants	required	I NOS.	MR		
	1) Total number of hydrants	Required	2 Nos.	MR		
	2) Hose box	Required	2 Nos.	MR		
		Required	2 NOS.	IVIK		
13.	Pumping Arrangement			1 1		
	1) Ground level					
	a) Discharge of main pump	N/A	N/A	N/A		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual stopping	N/A	N/A	N/A		
ŧ	2) Terrace level		- 1/12	A 1/4 K		
	a) Discharge of pump	Required	450 LPM	MR /		
	b) Head of pump	Required	35 mtr.	MR		
	c) Power supply	Yes	Provided	MR		
	d) Auto starting of pump	Yes	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	20,000 ltrs.	Provided	MR		
	a) Draw-off connection	N/A	N/A	N/A		
	a) Diaw-off confiection			1 4/4 h		
				MR		
		Yes N/A	Provided N/A	MR N/A		

ply

15. 16.	Exit Signage. Provision of Lifts.	Yes	Provided	100
			Trovided	MR
	a) Pressurization of lift shaft	N/A	27/4	
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	Yes	N/A	N/A
	a) 1:0 ·	103	Provided	MR

			- To viacu	MR
	e) Lift signage	V		
17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area	Yes	160 KVA	
	Total area location	N/A	N/A	MR
19.	Total area location	N/A		N/A
	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel		N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	
0.	Special Fire P	N/A		N/A
TI	Special Fire Protection System for	Protection of specie	I Diele is	N/A
O. Special Fire Protection System for Protection of special Risk, if any: The shortcomings communicated vide letter dated 29/03/12 found complicit.				N/A
ie fire pro	otection	7/U.3/1/ found commit	1 1	

The shortcomings communicated vide letter dated 29/03/12 found complied.

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Rules 2010/

Accordingly DFA is put up please

Signature of the inspecting officer

Signature of the inspecting officer

Name

Designation

Name: - S.S. Kaushik.

Designation:- Assistant Divisional Officer.

DO South

7/9/12