GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 3525

Dated: 25/09/12

FIRE SAFETY CERTIFICATE

Certified that the Paramount Guest House, 4230. Tel Mandi, Pahar Ganj, New Delhi110055 comprised of ground floor (12 guest rooms + reception + 01 office). 1st floor (08 guest rooms), 2nd floor (06 guest rooms + DG set + temp. shed for servant), total 26 guest rooms, was granted NOC by this department vide letter No. F6/MS/DFS/GH/2009/3708 dated 04-12-2009. The premises was re-inspected by the officer concerned of this department on 17-09-2012 in the presence of Sh. Virendra Arora (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 26 guest rooms with effect from 25./.9.8/...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .25./0.8/12 at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony. New Delhi–110049.w.r.t. No.38549/Addl.C.P./Lic.(H) New Delhi dated 12-06-12
- 2. M/s Paramount Guest House, 4230, Tel Mandi, Pahar Ganj, New Delhi-110055 Condition for the validity of fire safety certificate
- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Shree Lodge (Ganpati Dharamshala), 2012-13/7, Chuna Mandi, Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : Paramount Guest House, 4230 Tel Mandi, Pahar Ganj, New Delhi

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. F6/DFS/MS/GH/2009/3708 Dated 04-12-2009

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 17-09-2012

7. Name of the Inspecting Officer : Sh. D.S. Yadav (A.D.O.)

8. Name and designation of Officer

from the building side : Sh. Virender Arora (owner)

9. Year of Construction : 1982 Starting Year

10. Applicant's letter No. : 38549/Addl.C.P./Lic.(H) dated New Delhi the 12-06-2012

S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR		
1	and fire safety U/R 33	Requirements	(PSS Area)	(Old Case)		
1.	Access of building					
	 Road width 	N/A	2 mtrs. Approx.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	 Upper floors 	01	01	MR		
	Basements	N/A	N/A	N/A		
	b. Width of staircases					
	Upper floors	80 cms	115 cms.	MR		
	 Basements 	N/A	N/A	N/A		
	c. Protection of exits			14/1		
	 Fire check door 	N/A	N/A	N/A		
W	 Pressurization 	N/A	N/A	N/A		
	d. No of continuous staircase to	01	01	MR		
	terrace			I III		
	e. Width Of Corridor	N/A	N/A	N/A		
	f. Door Size	N/A	N/A	N/A		
3.	Compartmentation			1 1//1		
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	 Water Curtain 	N/A	N/A	N/A		
	 Fire Dampers 	N/A	N/A	N/A		
l.	Smoke managements System					
	Basements	30 a/c per hour	N/A	N/A		
	 Upper floors 	The same of the sa		1 1// 1		
		12 a/c per hour	Natural ventilation	MD		
5.	Fire Extinguishers	12 are per frour	ratural ventuation	MR		

Shree Lodge (Ganpati Dharamshala), 2012-13/7, Chuna Mandi, Pahar Ganj, New Delhi-110055 Total numbers 12 MR **Types** Water Co2 & MR A.B.C. type. IS marking ISI marked Provided MR 6. First – Aid Hose Reels Total numbers on each floor 01 01 MR 30 M Length of hose reel hose Provided MR Nozzle diameter 5 mm Provided MR 7. Automatic fire detection and alarming system Type of detectors N/A N/A N/A Location of Main Panel N/A N/A N/A Location of Repeater Panel N/A N/A N/A Alternate source of power N/A N/A N/A Hooters' Location N/A N/A N/A MOEFA 8. N/A N/A N/A Public Address System 9. Yes Provided MR 10. Automatic Sprinkler System Basements N/A N/A N/A Upper Floor N/A N/A N/A Sprinkler above false ceiling N/A N/A N/A 11. Internal Hydrants Size of riser/down-comer N/A N/A N/A Number of hydrants per floor N/A N/A N/A Hose Box N/A N/A N/A 12. Yard Hydrants Total number of hydrants N/A N/A N/A Hose Box N/A N/A N/A 13. **Pumping Arrangements** Ground Level Discharge of main pump N/A N/A N/A Head of main pump N/A N/A N/A > Number of main pumps N/A N/A N/A Jockey pump out put N/A N/A N/A Jockey pump head N/A N/A N/A Standby Pump out put N/A N/A N/A Standby Pump Head N/A N/A N/A auto Staring/Manual stopping N/A N/A N/A Pump House Access N/A N/A N/A Terrace level Discharge of pump 225 LPM 225 LPM MR > Head of the pump 30 Mtrs. 30 Mtrs. MR Power supply Electric Electric MR Switch provided at MR Auto starting of pump G.F 14. Captive water Storage for fire fighting Under ground tank capacity N/A N/A N/A > Draw of connection N/A N/A N/A > Fire service inlet N/A N/A N/A Access to tank N/A N/A N/A • Overhead Tank capacity 2500 Ltrs. 2500 Ltrs. MR 15 Exit Signage Yes Provided

N/A

N/A

16.

Provision of Lifts

Pressurization of Lift Shaft

MR

N/A

	A	dge (Ganpati Dharamshala), 20 Pressurization of lift lobby	N/A	N/A		
		•			N/A	
		Communication in lift Car	N/A	N/A	N/A	
		Fireman's Grounding Switch	N/A	N/A	N/A	
	A	Lift Signage	N/A	N/A	N/A	
	Standby power supply		YES	D.G. Set	MR	
18.	Refuge	Area				
		Total area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19.	Fire control room					
		Detector system panel	N/A	N/A	N/A	
	>	Flow Switch Panel	N/A	N/A	N/A	
	A	PA System Panel	N/A	N/A	N/A	
	>	Batter backup	N/A	N/A	N/A	
	-	Building Floor Plans	N/A	N/A	N/A	
	Special Fire Protection Systems for Protection of special Risks, if any		N/A	N/A	N/A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name

Designation

Dharm vie singh yeder tion ADO (e-D)

Py CPO(NDZ) 2019