GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI – 110001

No: F 6/DFS/MS/2012/ school/3547

Dated: 25/09/12

FIRE SAFETY CERTIFICATE

	Certified that the It Mother Tesp Ca Public School B-Block Baka Colony Can't Nagar
	Certified that the St. Mother Tereca Public School B-Block Baka Colony Sant Nagar Bwrani Delhi located at Baka Colony Sant Nagan Bwrani Delhi 10084
	comprised of Goonal+ one upper floor having 23 class sooms. occupied
	by Mother Educational & Social Welfine Locie 14: was issued NOC vide this office letter
	No. F. 6) OFS MS (2007) 370 S. Dated: 1.3/12/20). The premises was re-inspected by the
	officer concerned of this department on 1.84.8/1.2 and observed that all the fire
	prevention and fire safety arrangements as provided in the premises found in good working
	condition. The premises have therefore, deemed complied with the requirement under Rule 33
	of the Delhi Fire Service rule 2010 and the building/premises is fit for occupancy Class
	Educational with effect from 25/08/12 for a period of
7	These Years in accordance with rule 36 unless renewed under Rule 37 or sooner cancelled under
	Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service
	Rules, 2010.

Issued on 25/08/12 at New Delhi.

Chief Fire Officer
Delhi Fire Service

Copy to:
1. The Manager

ST. Mother Teresa Public School

B-Block, Boba Colony,
Sant Nagan, Berari Delhi 84.

2. The Allell Dixeror (Edn.)

North M CD Civic Centre

Mintoo Rd.

New Delhi.

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of a fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non — functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.

5. Basement shall be used as per MG

6. This NOC may not be treated in any case for regularizations of unauthorized.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1	Name & address of the building St. Mo.	ther Teresa Ru	iblic School, B-Bl	ock, Baba Co	long,
2	Type of Occupancy : Edn	cational		int Mary Bura	ri, Delhi-
3	. Type of Case : New C	Case/ Renewal			w)
4			007/3705 Date	ed: 13-12-2	97
5. Fire Safety directives letter No : Circular, Dir. of Edun.					
6		8-2012			
7. Name of the Inspecting Officers: ADO - SHYAM LAL					
8			Ker Kanshi	al (man	e and
	from the building side :			c) (inne	
9	Year of Construction :26	02, Grs.	+ one uppersy	las)	-
1 (). Applicant's letter No. :	til dated	26-7-2012	-	
S.	Minimum Standards on fire	Circular Dix of Colum	Provided at site	Remarks	
No.	prevention and fire safety U/R 33	Requirement		MR/NMR	
Souther Sale	Access to building		Cold Ca	se)	-
	 Road width 	Accessible	6 m -	mIR	
	Gate width		NIA		
	 Width of internal road 				
^	N. J. W.		MIA		
2	Number, Width, Type & Arrangement	of Exits		116	EDDO-S
	a. Number of staircases	2	2	MIR	Dor Care
	 Upper Floors 	2	2	MIR	*
	• Basements				
	b. Width of staircases			1.	100
	 Upper Floors 	1.5 m	1.5 md. 1.701	n msR	Oldans
	• Basements	Ni'L	NIC		The state of the s
	c. Protection of exits		1118		
	 Fire check door 		1)10	тана запринента 10 ж.	-,
	 Pressurization 		/		
	e. No. of continuous staircases to terrace	1	1	MIR	
	g. Width of Corridor	P	7'	mIR	
	h. Door Size) m	Im .	mlR	Cold cases

St. Mother Torresa Public Schoo), Babon Calarry, Dels

3	Compartmentation.		111 8	
	 Fire check door 		1811	
	 Sealing of electrical shafts 			
	• Fire Rating of shaft door			
	Water Curtain			
	• Fire Dampers			
4	Smoke Management System.		NIR	
	Basements	30 a/c per hour	7111	
	 Upper floors 	12 a/c per hour		
5	Fire Extinguishers	011		.4210
	 Total numbers 	04 ABC 24.0 -	OG ·ABC ·yes	m/R
	• Types	ABC ON CO2	NOC	-// -
	IS marking	151 marked	yes	-h -
6	First-Aid Hose Reels.		One	mIR.
	Total numbers on each floor	0nl 30 m	0	mir (o
	• Length of hose reel hose	5 mm		MIR
pay	Nozzle diameter		1	1110
7	Automatic fire detection and alarmin	g system.	NIR	
	Type of detectors			
	 Location of Main Panel 			
	 Location of Repeater Panel 			,
	 Alternate source of power 			
	Hooters' Location			
	• Hooters Location			
8	MOEFA		NIR	
9	Public Address System.		MIR	
10	Automatic Sprinkler System.		NIR	
	 Basement 		////	

St. Mother Teressa Public School Baba calon

	Upper FloorSprinkler above false ceiling				2
Sameway A comment	Internal Hydrants		N 5 / A		
	 Size of riser/down-comer Number of hydrants per floor Hose Box 		N/K		
12	Yard Hydrants.		0111		
	Total number of hydrantsHose Box		MIK		
13	Pumping Arrangements.		NIL		
	Ground Level		7477		
	Discharge of main Pump			5	
	Head of Main pump				
	Number of main pumps				
	➤ Jockey Pump out put				
	Jockey pump head				
	Standby Pump out put	±			
	Standby Pump Head				
	Auto Starting/ Manual				
	stopping			*	
	Pump House Access		2 2		
	Terrace levelDischarge of pump				
	Head of the pump	225-18/mi	rit. Provided	MIR	(old Cure
	Power Supply	40 m	provided	MIR	
	Auto Starting of pump				
and the second	Captive Water Storage for fire fighting.		N// A		
	Underground tank capacity	×	1418		
	Draw-off connection				

St. Mother teresa Publi School, Baba Colony, Delhi

	 Fire service inlet Access to tank Overhead Tank capacity 	2500 LHS,	N/R 2500 LHs,	msR (olda
5	Exit Signage.		NIR	
16	Provision of Lifts.		> 1 1	
and the same of th	Pressurization of Lift Shaft		N) H	
	Pressurization of Lift lobby			
	Communication In lift Car			
	• Fireman's Grounding Switch			19
	Lift Signage			
17	Standby power supply		MIR	
18	Refuge Area.		V LI V	
	Total AreaLocation		74.1 M	
19	9 Fire Control Room			
	Detector System Panel	,	NIX	
	 Flow Switch Panel 			
	 PA System Panel 		, 2 e.a.	·
	Batter backup			
	 Building Floor Plans 			
20	Special Fire Protection Systems for Protection of special Risks, if any:		Mic	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Dy CF.O(W)

renter &

Shylaf 21/8/2012 (SHYAM LAZ) Assib. Dim. officer