

No. F6/MS/DFS/GH/2012/3 57 4

Dated: 28/09/12

FIRE SAFETY CERTIFICATE

Certified that the Savera Guest House, 1778/53, Hardhian Singh Road, Naiwala, Karol Bagh, New Delhi-110005 comprised of basement (storage), ground floor (reception + 01 office) upper ground floor (02 guest rooms), 1st floor to 2nd floor (04 guest rooms at each floor), 3rd & 4th floor (residence of the owner), total 10 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2603 dated 21-08-2009. The premises was re-inspected by the officer concerned of this department on 19-09-2012 in the presence of Sh. Bharat Singh (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 10 guest rooms with effect from .28/09/...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .28/09/12. at New Delhi by.

CHIEF FIRE OFFICER DELHI, FIRE SERVICE

Copy to :-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049: w. r. t. letter No. 38159/Addl/ C.P./ Lic (H) New Dlehi dated 08-06-2012.

2. M/s Savera Guest House, 1778/53, Hardhian Singh Road, Naiwala, Karol Bagh, New Delhi-110005

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTION	ON REPORT S	avera quest i	house,				
	1778/5	3, Hardhia	n singa Road					
1.	1778/53, Hasdisian sing Road, Name & address of the building Nae wala, Kasolsaga, New Selli							
2.	Type of Occupancy Lodging Rosese							
3.		: New Case/ Renewal						
4.	Details of previous NOC : Letter No	: Letter No. F6/3FS/N.S./GH/2009/ Dated: 21-08-09.						
5.	Fire Safety directives letter No : -NA -							
5.	Date of inspection : 18	18-09-12						
7.	Name of the Inspecting Officers : Da	ers. Dhagm vie singh yadav.						
8.	Name and designation of officers							
	from the building side Sk	ri Bharat si	in gh (manages)	WE SEE COME AND A LICENSING.				
9.	Year of Construction : Sta	esterg year 2	009.					
10	Applicant's letter No. :38159	parte. c. P. SLic	(A) dolar new sel	le the 08-06-12				
9.	Minimum Standards on fire	NBC/BBL	Provided at site	Remarks				
No:	prevention and fire safety U/R 33	Requirement		MR/NMR				
	Access to building			old care				
	• Road width	- N.A -	09 M trs appear	M.R				
	• Gate width	- N.A -						
	Width of internal road	- N.A -						
	Width of Internal Toda	- N.01		-				
. 2	Number, Width, Type & Arrangement o	of Exits						
	a. Number of staircases							
	 Upper Floors 	one	one	m·R				
(E (C	 Basements 	one	one					
	b Width of staircases							
1	• Upper Floors	0.80 Mts	90 cms to 1160	MR V				
	* Basements	0.80 mts	0.90 Mts	m.K				
	c. Protection of exits		2					
1	• Fire check door	- N.A-						
1	Pressurization	-N.A-	and the state of t					
1	e. No. of continuous staircases to terrace	one	one	N.R				
ì	g. Width of Corridor	-N.A -						
i i	h. Door Size	-N.A-						
2 - 2 mark	11. 12001 0120	And the second s	And the second s	contd:				

Hotel savela, 1778/53, Hardhyan singh Road, Naiwala, Kalol Bagh New Deltic

old case Compartmentation. -N.A -Fire check door Sealing of electrical shafts -N.A -Fire Rating of shaft door -N.A -Water Curtain Fire Dampors -N.A -4 Smoke Management System. Exhaust fans Basements 30 a/c per hour Natural ventilation Upper floors 12 a/c per hour 5 Fire Extinguishers 10 Nos 10 NO8 Total numbers Types ISI marked m.R IS marking Provided 6 First-Aid Hose Reels. one M.R. Total numbers on each floor Provided. MR Length of hose reel hose 30 m Provided. M.R. Nozzle diameter 5 mm Automatic fire detection and alarming system. Type of detectors Location of Main Panel Location of Repeater Panel . Alternate source of power -N.A -Hooters' Location -N.A yes. Provided MiR 8 MOEFA yes 9 Public Address System. 10 Automatic Sprinkler System. Provided. yes Basement

conta:-

savera quest house, 1778/53 marchyan singh Road, variagla, karol Bagh, new Delli Upper Floor Sprinkler above false ceiling -NA -1 11 Internal Hydrants Size of riser/down-comer - N.A -Number of hydrants per floor - NA -Hose Box - N.A -Yard Hydrauts. Total number of hydrants - N.A -Hose Box -NA -Pumping Arrangements. Ground Level - N.A -Discharge of main Pump - N.A -> Head of Main pump - NA > Number of main pumps Jockey Pump out put Jockey pump head - NA -Standby Pump out put > Standby Pump Head > Auto Starting/ Manual -N.A stopping > Pump House Access Terra e level 450 LPM 450 LPM M.R. 30 Mtes 30 Mtes M.R. Rectricity Electricity Mike > Lischarge of pump > Head of the pump > Power Supply Flectercity > Auto Starting of pump at ground flows Captive Water Storage for fire fighting. 14 Underground tank capacity -NA-> Draw-off connection -N-A -

contd:

4/7

Savela queet house, 1778/53, Hardhyan singh Ecad, minuela, Karol Bagh, New Delli

and case

-	NAME OF THE OWNER OWNER OF THE OWNER O			Otto Con
,	Fire service inlet	yes.	Pewidal -	MR
	Access to tank	yes	peovided.	M.R.
	 Overhead Tank capacity 	5,000 lites	5,000 leter	M.R. J
	Exit Signage.	yes	peovided.	M-R
16	Provision of Lists. one list	Count flore to		and the first the second class of the second c
	* Pressurization of Lift Shaft	-N.A-		
	Pressurization of Lift lobby	- N.A -		the set being a large for the description (in a settlement of these, and telescopes) of the total
	* Communication In lift Car	yes.	Dec id l-	
	Fireman's Grounding Switch	See to be seen to be s	Peovided-	M·R
	Lift Signage	yes	P. Eov icked	M.R
		yes.	Previoled:	M.R
117	Standby power supply	yes	DG. SEE	MR
18	Refuge Area.			
	> Total Area	-N.A-		and a real state and plat life and a property from the state and a second state of the state of
	> Location	-NA-		
10	Fire Control Room			And is a second of the second control of the second of the
	Detector System Panel	- N.A -	The same of the sa	4
	 Flow Switch Panel 	-N.A -		
	PA System Panel	- N.A -		
	Batter backup	-NA -		
	Building Floor Plans	-NA -		
20	Special Fire Protection Systems for Protection of special Risks, if any:	-NA-		
e in identity				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Service Rules 2010/ issue shortcomings as noted at serial numbers.

savela quelt house, 1778/53 Hardhyan singl Eard, Mainala Kalol Bagh New Della Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dealm vie single yarden Name Designation Assistant Dissipposal Designation officel (certical) Submitted please. Dy CHOCNOX)