GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ >787

Dated: 15/10/12

FIRE SAFETY CERTIFICATE

Certified that the Dollar Inn Guest House, 904-A, Gali Chandi Wali, Main Bazar, Pahar Ganj, New Delhi-110055 comprised of ground floor (02 guest rooms + reception) 1st floor to 3rd floor (04 guest rooms at each floor), 4th floor (02 guest rooms), total 16 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2952 dated 06-10-2009. The premises was re-inspected by the officer concerned of this department on 26-0**7**-2012 in the presence of Sh. Naresh Chadha (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 16 guest rooms with effect from ...[5...]....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .1.5./1.0/.1.2. at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi 110049 w.r.t. letter No. 55211/Addl.C.P./Lic.(H) New Delhi dated 17-09-2012
- 2. M/s Dollar Inn Guest House, 904-A, Gali Chandi Wali, Main Bazar, Pahar Ganj, New Delhi-110055.
- 3. Dy. Commissioner M.C.D. Idgah Road, Sadar Pahar Ganj Zone New Delhi with request to get the height of building measured and intimate to Delhi Fire Service.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

	Dollar	Inn Guest/	Youse, 904-A, Go	uli Chandi Wali
1.			Main Baser, K	whaz Ganj, New Dell
3.	ν .	ng House	anno describado estrador o describa en proprior de las participas de participas de participas de como construir de la como de construir de de const	
)	, 1	/ Renewal	1 1	
4.		F6/DPS/MS/GA	1/2009/2352 Dated	06/10/2009
5.		A -	(
5.		5-9-2012		
7.	Name of the Inspecting Officers :	. D.S. 490	lar (A.D.O)	
8	Name and designation of officers			
	from the building side SA.		hadha (Mane	ger)
9.	Year of Construction	2007 Stasti	ny Year	Control of the Contro
1(Applicant's letter No. SC211	Adds. C.P. Lic	(H). New Delhi	dated, 17-9-12
	Minimum Standards on fire	NBC	Previded at site	Remarks
10.	prevention and fire safety U/R 33	Requirement	(P.S.s. Areg)	(Old Case)
	Access to building			CANAL ATTRIBUTE OF THE STATE OF THE CANAL ATTRIBUTE
	 Road width 	-NIA-	2.50Mbs. Approx	4. MK L
	• Gate width	- N/A-		
	• Width of internal road	-MIA-		
2	Number, Width, Type & Arrangement o	of Exits	equination of the second second second	· Francisco de la company
	a. Number of staircases			
	 Upper Floors 	01	01	mR
	• Basements	-NIA-		
	b Width of staircases			
	 Upper Floors 	80 Cms.	110 Cms to 120 G	ms MR v
	* Basements	-N/A-		1 A
	c. Protection of exits			
	• Fire check door	- M/A -		
1	Pressurization	- N/A -		
1	e. No. of continuous staircases to terrace	01	61	MR
1	g. Width of Corridor	-N/A-		
E E	h. Door Size	- N/A-		
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			Conta -

NH

Dollar Inn Guest House, 904-A, Gali Chandi Wali, Main Bazar, Pahar Ganj, New Dolli- 110055

Pa .	har Gang, New Delhi - 1100.	ST.		old ease
Cor	upartmentation.			
	• Fire check door	-N/A-		
	• Sealing of electrical shafts	- N/A -		
	• Fire Rating of shaft door	-N/A-		
	Water Curtain	- N/A -		And the second s
	Fire Dampors	- N/A -		
4 Sn	noke Management System.	manadam dengan dan menumbahan bihan dan menumbahan dan menumbahan dan menumbahan dan menumbahan dan menumbahan		
	 Basements 	30 a/c per hour		- ×/A -
	• Upper floors	12 a/c per hour	Natural Ventila	tion. MR
	1	9		
5 Fi	re Extinguishers			
	 Total numbers 	16 Nos:	10 Nos	mk
	* Types	_	Water Coz & A.B.	· MR
	 IS marking 	ISI marked	Provided	mR
6 Fi	irst-Aid Hose Reels.			under Naue Charles i un and i un une resident annément à commande experience de la partie de la color.
	Total numbers on each floor	01	0/	mk
	 Length of hose reel hose 	30 m	Provided	mR
	Nozzle diameter	5 mm	Provided Provided	MR
$\frac{7}{A}$	utomatic fire detection and alarming	system.		
1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	• Type of detectors	-N/A-		
	• Location of Main Panel	-14/A-		
~	• Location of Repeater Panel	-N/A- -X/A-		
	Alternate source of power	- N/A -	and the second s	
	• Hooters' Location	- x/A -	an ann an Airminean an airm agus an	
8]	MOEFA	-M/A-		
9	Public Address Systém.	Yes	Provided	mR
10	Automatic Sprinkler System.			
	• Basement	-NIA-		

contd:

Dollar Inn Gruest House, 904-A, Gali Chandi Wali, Main Bazal, Papas Gay, Hew Delli-110055

A THE PARTY OF THE	-1/0055	7 114 6920
• Upper Floor	-V1/n	old ease
Sprinkler above false ceiling	-X/A -	P.SS DE
11 Internal Hydrants	-X/A -	
• Size of riser/down-comer		***
Number of hydrants per floor	-N/A-	
* Hose Box	-N/A -	
Vard Hydrauts.	-~/4 -	
Total number of hydrants		
1705e Box	-N/A-	
amping Arrangements.	-N/A -	
* Ground Level		
Discharge of main Pump	-N/A-	1
Head of Main pump	-MA-	
Number of main pumps	- N/A-	
> Jockey Pump out put	-X/A-	
> Jockey pump head	- M/A-	
Standby Pump out put	-N/A-	
Standby Pump Head	-N/A-	
Auto Starting/ Manual		
stopping 'Manual	-MA-	
	-NIA-	110
Pump House Access • Terra e level		
> Lischarge of pump	905 (4)	
Head of the pump	225 LPM. 225 LPM.	MR _
> Power Supply	30 Mts. 30 Mts.	mp
Auto Starting of pump	Electric Electric	
Captive Water San	- Swinch Provided	
Captive Water Storage for fire fighting.	24 G. F.	MK
Underground tank capacity	-x/n	
> Draw-off connection	-XI/A-	
	14/4-	21
		Conti.

Dollar Inn Guest House, 904-A, Gali Chandi Wali, Main Bazor, Bazar, Pahar Ganj, New Dellii - 110055

		,		PSS AROA
	Fire service inlet	- N/A-		
1	> Access to tank	- M/A-		
	 Overhead Tank capacity 	2500 Lbs.	2500 Ctos.	MR V
5	Exit Signage.	Yes	2500 Ctss. Provided	MR
6	Provision of Lifts.	1	r	man and the second seco
	• Pressurization of Lift Shaft	-M/A-		7
	 Pressurization of Lift lobby 	-M/A -		
	Communication In lift Car	- N/A-		
	Fireman's Grounding Switch	-N/A-		
	* Lift Signage	- M/A-		
17	Standby power supply	Yes	D.G. Set.	mR
18	Refuge Area.			
	> Total Area	-N/A-		*
1	> Location	-N/A-		
10	Fire Control Room			
	Detector System Panel	-NIA-		
	Flow Switch Panel	- N/A -		S 8
and the second second	PAl System Panel	- X1/A-		
	Batter backup	- N/A -		in a second
	Building Floor Plans	-NIA-		
	Special Fire Protection Systems for Protection of special Risks, if any:	-NIA		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi part The Service Rules 2010/ issue shortcomings as noted at serial numbers

Contact

Doller Inn Guest House, 904-A, Gali Chandi Wali, Main Bazar, Pahor Gaij, New Delli -110055 Gapton 09-12 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dalm vie Singh gada Name Designation

nation

Designation ADO (CD)

Submitted please.